

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003657/K1qbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 08-03-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBL 7388Z	Veh. Inspected	SHB 4736D	
Policy No.	0073451220-14	Coverage (\$)	0.00	
Claim No.	MT/0984783-001	Excess (\$)	0.00	
Assign From		Assign Date	22/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHLB41UMHU098324	Colour	YELLOW	
Odometer	165342	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	7 mm	
L/H Front Tyre	205/60 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/02/2018	Inspection Date	22/02/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		