

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SFQ6034C

Date of Accident : 19 February 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Drew Ameroid (S) Pte Ltd

Date : 26 February 2018

Estimate To Repair FBF6794Y - Yamaha T135
Chassis No : 5YP012945

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear wheel rim <i>n</i>	\$ 380.00
02	1 pc	rear wheel mudguard <i>n</i>	\$ 180.00
03	1 pc	rear exhaust pipe <i>in</i>	\$ 450.00
04	1 pc	rear exhaust pipe heat shield <i>but</i>	\$ 120.00
05	1 pc	chain guard <i>11</i>	\$ 150.00
06	1 pc	main park stand <i>n</i>	\$ 250.00
07	1 pc	rear swing arm <i>n</i>	\$ 460.00
08	1 pc	rider's foot rest pedal <i>but</i>	\$ 220.00
09	1 pc	n/s rider's foot rest pedal rubber <i>to in</i>	\$ 25.00
10	1 pc	foot gear selector pedal <i>but</i>	\$ 100.00
11	1 pc	n/s side fairing <i>n</i>	\$ 380.00
12	1 pc	o/s side fairing <i>n</i>	\$ 380.00
13	1 pc	front fairing <i>1 unit cut</i>	\$ 200.00
14	1 pc	handlebar <i>but</i>	\$ 250.00
15	1 pc	n/s handlebar balancer <i>scr</i>	\$ 20.00
16	1 pc	n/s front ^{wing} mirror <i>cut</i>	\$ 80.00
17	1 pc	speedo-meter fairing <i>11</i>	\$ 150.00
18	1 pc	front license plate sticker <i>new</i>	\$ 30.00
		Less 10 %	\$ 3,825.00
			\$ 382.50
			\$ 3,442.50
		<u>SPECIAL NETT ITEMS</u>	
19	1 pc	rear luggage box with carrier <i>cut</i>	\$ 400.00
20	1 pc	rear licence plate <i>n</i>	\$ 30.00
			\$ 430.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating and spray painting <i>250</i>	\$ 400.00
		the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	\$ 400.00
	Total		\$ 4,272.50