

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khor Saw Theng

Date: 02 Mar 2018

Preliminary Advice

Insured Vehicle No : SHB7730A

TP Vehicle No : SLM9941P

Make : VOLKSWAGEN SPORSCAN 1.4 TSI CL

Date of Inspection : 01/03/2018

Inspection At : VOLKSWAGEN GROUP SINGAPORE PTE LTD

Accident Date : 23/02/2018

Assignment Date : 28/02/2018

Est. Duration of Repair : 5/Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,246.60
Revised Amount	:S\$	7,087.81
Check Items (Estimated)	:S\$	1,038.78
Total	:S\$	8,126.59

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.