

INS. CASE OWNER

Lynthia

CC 4/AXA1800 3970

T. 063

LKK:
IDAC

Surveyor:

Tantleh

DOI:

ASSIGNMENT

26/1/18

Date / Time:

27/1/18

Registered in Merimen:

27/1/18

Pre-assign / CCU / FTE

SHO 1135



Insured Vehicle No.:

TRANS-UMB SERVICES P/L

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : \$5

AG000

D.O.A.:

15/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MB EMU LEE

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

10471438

Policy No.:

UPK/P168050

Make / Model:

MERCEDES

Place of Accident:

BEPUK NORTH ST1 TMS BEPUK
NORTH HWY 1

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability:

% Final ? Yes / No

GW 6692J



INSRS:

WSP:

Tel:

Liability:

RMKS:

SM
Gheng



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

1/1/18
TM

GW 6692J - 4 SHO 1135 V

STAGE

DATE / PIC

Non-Reporting Itr (1st):
Non-Reporting Itr (2nd):
Non-Reporting Itr (Final):
Notification Itr (if non-pickup):
Call OI:
After call Itr to OI:


Documentation Check List: Handler Typist

Notification Itr (if non-pickup):
After call Itr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA :
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:

29-11-18

TRANSFER : THIN2 TO JOY
REVIEWED: ON 21-6-18 AXA
MANDATE TO REJECT.
TP BEAT TRAFFIC
LIGHT.

RECEIVED 04 DEC 2018



PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5

(

\$

x

days)

Loss of Income (LOI):

\$5

(

\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/Independent)

Legal Cost:

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

VIDEO - GREEN ARROW FOR OI
COPY SENT
4/1/18

Tanfield

AXA

U

2018 July
2003 Sep

28/2/18

GW6692J

Q

Mikishiki L300
White
468731

2477

JMAJNP15V44 000 336

G

185/R14

Austine

6

6

6

6

28/2/18 @ 1432

Sin Sheng

Q

Tanfield

AXA

U

2018 July
2003 Sep

28/2/18

GW6692J

Q

Mikishiki L300
White
468731

2477

JMAJNP15V44 000 336

G

185/R14

Austine

6

6

6

6

28/2/18 @ 1432

Sin Sheng

Q

Tanfield

AXA

U

2018 July
2003 Sep

28/2/18

GW6692J

Q

Mikishiki L300
White
468731

2477

JMAJNP15V44 000 336

G

185/R14

Austine

6

6

6

6

28/2/18 @ 1432

Sin Sheng

Q

Tanfield

AXA

U

2018 July
2003 Sep

28/2/18

GW6692J

Q

Mikishiki L300
White
468731

2477

JMAJNP15V44 000 336

G

185/R14

Austine

6

6

6

6

28/2/18 @ 1432

Sin Sheng

Q



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/AXA18003870/ub3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 28-02-2018	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 113S	Veh. Inspected	GW 6692J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/02/2018	Inspection Date	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002408

Date : 27/02/2018

Vehicle Num. : GW6692J

Make/Model : MITSUBISHI L300-2003

Chassis/Eng# : JMAJNP15V4A000336/4D56KQ3363

Accident Date : 15/02/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	FRONT PANEL		dd✓ 1,250.00
2.	1	PANEL GARNISH		mis✓ 125.00
3.	1	CORNER PANEL, LHS		bt✓ 125.00
4.	2	SIGNAL LAMP - LH - ✓, RH - X	195.00	390.00
5.	2	HEADLAMP	210.00	X 420.00
6.	1	FRONT BUMPER		de✓ 675.00
7.	2	BUMPER SIDE LH - ✓, RH - X	55.00	110.00
8.	1	BUMPER REINFORCEMENT		bt✓ 245.00
9.	1	OIL COOLER		X 1,150.00
10.	1	CROSSMEMBER		bt✓ 550.00
11.	1	NUMBER PLATE		mis✓ 20.00
12.	1	HEATER AND BLOWER		? 950.00
13.	1	COOLING UNIT, A/C		? 450.00
14.	1	WINDSCREEN SEALANT		new✓ 40.00
Nett Total S\$:				6,500.00
10.00% Discount S\$:				650.00
				5,850.00
LABOUR :				
TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS				✓ 120.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002408

Date : 27/02/2018

Vehicle Num. : GW6692J

Make/Model : MITSUBISHI L300-2003

Chassis/Eng# : JMAJNP15V4A000336/4D56KQ3363

Accident Date : 15/02/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	FRONT PANEL	dd ✓ 1,250.00	
2.	1	PANEL GARNISH	mis ✓ 125.00	
3.	1	CORNER PANEL, LHS	bt ✓ 125.00	
4.	2	SIGNAL LAMP - LH - 24 ✓, RH - x nn	(195.00) 390.00	
5.	2	HEADLAMP	210.00 x 2 420.00	
6.	1	FRONT BUMPER	de ✓ 675.00	
7.	2	BUMPER SIDE LH - 1 ✓, RH - x nn	(55.00) 110.00	
8.	1	BUMPER REINFORCEMENT	bt ✓ 245.00	
9.	1	OIL COOLER	bt ✓ 1,150.00	
10.	1	CROSSMEMBER	bt ✓ 550.00	
11.	1	NUMBER PLATE	mis ✓ 20.00	
12.	1	HEATER AND BLOWER	nnx 950.00	
13.	1	COOLING UNIT, A/C	nnx 450.00	
14.	1	WINDSCREEN SEALANT	de ✓ 40.00	
Nett Total S\$:			4430	6,500.00
10.00% Discount S\$:			3987	650.00
				5,850.00
LABOUR :				
TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS			✓	120.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002408

Date : 27/02/2018

Vehicle Num. : GW6692J

Make/Model : MITSUBISHI L300-2003

Chassis/Eng# : JMAJNP15V4A000336/4D56KQ3363

Accident Date : 15/02/2018

Claim No. :

Reference :

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount SS
		TO REMOVE/REFIT DASHBOARD TO FACILITATE REPAIRS	180	280.00
		TO PANEL BEAT/REPAIR FR BODY	800	1,200.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS	100 ^{in photo}	150.00
		TO DISMANTLE/REPLACE AIR-CON HEATER AND BLOWER		
		TO TOP UP GAS		
		SPRAY PAINTING	500	700.00
		TOWING CHARGES	✓	60.00
		LOSS OF USE : 8 DAYS @ \$ 120/DAY		
		Labour Total SS :		2,510.00

Tan Jiah 97495749
 'WP'
 28/2/18 @ 1430
 6 days
 Lumpsum
 Resurvey after repair

Total SS : 8,360.00

sur@lkkauto.com

tanjiah@lkkauto.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SIN SHENG ENGINEERING SERVICES

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GW6692J
Vehicle to be Exported:	No
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	L300 HR M
Primary Colour:	White
Manufacturing Year:	2003
Engine No.:	4D56KQ3363
Chassis No.:	JMAJNP15V4A000336
Maximum Power Output:	-
Open Market Value:	\$13,516.00
Original Registration Date:	19 Sep 2003
First Registration Date:	19 Sep 2003
Transfer Count:	0
Actual ARF Paid:	\$676.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2018
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5

PQP Paid:	\$28,787.00
COE Rebate Amount:	\$2,383.00
Total Rebate Amount:	\$2,383.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 01 Mar 2018

OK



Mitsubishi L300 Price Range Depreciation > 10 year(s) of Vehicle Type

Home » Used Cars » Hoe Beng Auto Trading » Mitsubishi L300 (COE till 08/2018)

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Leasing

URBAN LEASING \$0 DOWNPAYMENT!

Mitsubishi L300 (COE till 08/2018)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions

Car Details

Price	\$5,900	
Depreciation	-	?
Reg Date	06-Aug-2003 (5mths 4days COE left)	
Lifespan	05-Aug-2023	
Manufactured	2003	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,477 cc	
Curb Weight	1,390 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	Good Conditions. Ideas For Short Terms Use.	
COE	\$29,749	?
OMV	\$13,381	?
ARF	\$670	?
Dereg Value	\$2,559 as of today (change)	?
No. of Owners	3	?
Type of Veh	Van	
Category	COE Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 07-Feb-2018 | Last Updated on: 09-Feb-2018

Tags: Mitsubishi L300, 2003 Mitsubishi L300, Mitsubishi L300, Used Mitsubishi



Seller Information

Company

Address

Office No

Contact Person(s)

Useful Services



M
W

Compare

Joy Irene (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Monday, 3 December 2018 2:49 PM
To: Joy Irene (LKKAuto)
Subject: FW: GW6692J REPAIR LIMIT
Attachments: SHD01135 DOA 15.02.18 (1).wmv

From: Thin Thin (LKKAuto)
Sent: Thursday, 21 June 2018 2:33 PM
To: 'sinsheng engineeringservices' <sinsheng1981@gmail.com>
Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: GW6692J REPAIR LIMIT

Your ref: GW 6692J

"Without Prejudice"

Dear Sir / Madam,

ACCIDENT INVOLVING GW 6692J & SHD 113S ON 15/02/2018

We refer to above matter.

Our insured has reiterated that the accident was caused due to the negligence of your client.

Your client beat the traffic light and collided with our insured vehicle. Please see the enclosed video footage.

Under such a circumstances, we are denying liability and unable to look into your client's claim.

Yours faithfully,

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineeringservices [<mailto:sinsheng1981@gmail.com>]
Sent: Thursday, 21 June 2018 11:03 AM
To: Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Cc: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: Re: GW6692J REPAIR LIMIT

Hi Ms Thin Thin,

We refer to the above. Despite several reminder, we had yet to received any response.

We could appreciate if can get your response end of 05/07/2018, failing which we have no choice and to close the file on ou

And will pass back the case to our client, any action taken by our client are not related to us.

View Received Message

This mail is associated with :

*GW6692J (C0471438)

[SHD113S]

TP

GOLDBELL LEASING PTE LTD

Feb 15 2018 4:00PM

[TRANS-CAB SERVICES PTE LTD]

Sin Sheng Engineering Services

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From

AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 21/06/2018 11:09 AM.

To

LKK_HQ

CC

AXA_SG; thinthin@lkkauto.com; admin-a@lkkauto.com

Subject

Re: C0471438/P1680520

Hi Thin Thin,

pls proceed to reject claim.

thank you.

<-- Original Message -->

From: LKK_HQ

To: cynthia.loh@axa.com.sg

CC: AXA_SG; thinthin@lkkauto.com; admin-a@lkkauto.com

Sent On: 22/05/2018 09:32 AM

Subject: Re: C0471438/P1680520

Dear Cynthia,

We refer to the below matter.

Please be inform that we have send the video footage via Accellion for your perusal.

Based on footage, OI is making right turn with green arrow and TP is beat the traffic light.

As such, we intend to reject the claim and kindly let us have your instruction / approval please.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG

To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com

Sent On: 27/02/2018 04:28 PM

Subject: C0471438/P1680520

 AXA Insurance



AXA INSURANCE PTE LTD
8 Raffles Way, #19-01, 808 Tower
Singapore 109921
Customer Centre #02-01
☎ Tel: 6841-2360
☎ Tel: 6841-2362
🌐 www.axa.com.sg
GST Reg No.: U990000220
In Reg No.: U990000220

Dear LKK Auto Consultants Pte Ltd,

OI counter claim TP.

Please obtain evidence and liaise with OI before any settlement.

Thanks & Regards,

Cynthia Loh

DOCUMENTS SUMMARY

...CLAIM SUBFOLDER...(Pending for Survey Report)

81 Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2018		27 Feb 2018 16:26 Edit Adj Rpt	S\$2,500.00 Edit Estimates	S\$2,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GW6692J	Date of Loss:	15/02/2018 16:00 - :59 [172 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0471438	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHD113S	Policy No. (Claimant):	29004183						
		Excess:	S\$5,000.00						
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Stacey Ng - 6880 4351]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/03/2018]								
Driver/Custodian (Insured):	NG ENG LEE (), NRIC: S0710131G, Tel: +6598153536								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AXA_SG (21/06/2018): Re: C0471438/P1680520 - AXA_SG (27/02/2018): C0471438/P1680520 - AXA_SG (27/02/2018): New TP Assignment - C0471438/P1680520									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GW6692J (C0471438)
[SHD113S]
TP
GOLDBELL LEASING PTE LTD
Feb 15 2018 4:00PM
[TRANS-CAB SERVICES PTE LTD]
Sin Sheng Engineering Services

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			▼		
Video															1 per page			▼			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	03/12/18 14:56		Video - Accident												1			Load WMV					
Assessment Reports															1 per page			▼			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	01/03/18 15:06		Adjuster Immediate Advice												1			Load HTM					
Photos/Images															3 per page			▼			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print					
1	19/04/18 17:04		General View												1			Load JPG			☒		
2	19/04/18 17:04		General View												1			Load JPG			☒		
3	19/04/18 17:04		General View												1			Load JPG			☒		
4	19/04/18 17:04		General View												1			Load JPG			☒		
5	19/04/18 17:04		General View												1			Load JPG			☒		
6	19/04/18 17:04		General View												1			Load JPG			☒		
7	19/04/18 17:04		General View												1			Load JPG			☒		
8	19/04/18 17:04		General View												1			Load JPG			☒		
9	19/04/18 17:04		General View												1			Load JPG			☒		
10	19/04/18 17:04		General View												1			Load JPG			☒		
11	19/04/18 17:04		General View												1			Load JPG			☒		
12	19/04/18 17:04		General View												1			Load JPG			☒		
13	19/04/18 17:04		General View												1			Load JPG			☒		
14	19/04/18 17:04		General View												1			Load JPG			☒		
15	19/04/18 17:04		General View												1			Load JPG			☒		
16	19/04/18 17:04		General View												1			Load JPG			☒		
17	19/04/18 17:04		General View												1			Load JPG			☒		
18	19/04/18 17:04		General View												1			Load JPG			☒		
19	19/04/18 17:04		General View												1			Load JPG			☒		
20	19/04/18 17:04		General View												1			Load JPG			☒		
21	19/04/18 17:04		General View												1			Load JPG			☒		
22	19/04/18 17:04		General View												1			Load JPG			☒		
23	19/04/18 17:04		General View												1			Load JPG			☒		
24	19/04/18 17:04		General View												1			Load JPG			☒		
25	19/04/18 17:04		General View												1			Load JPG			☒		
26	19/04/18 17:04		General View												1			Load JPG			☒		
27	19/04/18 17:04		General View												1			Load JPG			☒		
28	19/04/18 17:04		General View												1			Load JPG			☒		
29	19/04/18 17:04		General View												1			Load JPG			☒		
30	19/04/18 17:04		General View												1			Load JPG			☒		

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	19/04/18 17:04	General View	 Load JPG	☒
32	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
33	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
34	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
35	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
36	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
37	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
38	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
39	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
40	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
41	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
42	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
43	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
44	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
45	19/04/18 17:07	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 13:45	EMAIL_ABS	 Load PDF	
2	27/02/18 13:45	CO CLAIMANT_ABS	 Load PDF	
3	27/02/18 13:45	GW6692J TP GIA_ABS	 Load PDF	
4	27/02/18 13:45	LTA_ABS	 Load PDF	
5	27/02/18 13:45	SHD113S INSD GIA_ABS	 Load PDF	
6	27/02/18 13:47	LIST OF SURVEYOUR_ABS	 Load PDF	
7	27/02/18 14:45	EMAIL FROM WORKSHOP	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 16:57	TP ESTIMATE- MARKED	 Load PDF	
2	03/12/18 14:56	REJECTION EMAIL	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607188R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18003870/T1JB3Q2
Date: 11/12/2018

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1680520
Claimant Vehicle No :	GW6692J	Insured Vehicle No :	SHD113S
Date of Loss:	15/02/2018	Nature of Claim:	TP
		Claim No:	C0471438

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW6692J	Engine No:	4D56KQ3363
Make & Model:	MITSUBISHI L300, 2.5 D (M)	Chassis No:	JMAJNP15V4A000336
Reg. Date:	19/09/2003 (Man. Year: 2003)	Odometer:	468731 km
Colour:	White		
Engine Capacity:	2477 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/ R14	Rear Tyre Size:	185/ R14
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,850.00	3,987.00	1,863.00	31.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,760.00	750.00	29.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,360.00	5,747.00	2,613.00	31.26
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	8,360.00	2,500.00	5,860.00	70.10
+ GST 7.00/7.00% (S\$)	585.20	175.00	410.20	70.10
Nett Amount (S\$)	8,945.20	2,675.00	6,270.20	70.10

INSPECTION

Date of Assignment:	27/02/2018	
Date Inspected:	28/02/2018	Inspected At: Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park Singapore 638129
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Dec 2018)	
Parts:	N/A	mitsubishi L300 2.5 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW6692J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL (CONSISTENT)	Dented	1,250.00 FN	*1,250.00 FN
2	1		*PANEL GARNISH (CONSISTENT)	Missing	125.00 FN	*125.00 FN
3	1		*CORNER PAEL ,LHS (CONSISTENT)	Bent	125.00 FN	*125.00 FN
4	1		*SIGNAL LAMP (CONSISTENT)	N/S Cracked/O/SNot Necessary /	390.00 FN	*195.00 FN
5	2		*HEADLAMP (CONSISTENT)	Not Necessary	420.00 FN	*- FN
6	1		*FRONT BUMPER (CONSISTENT)	Deformed	675.00 FN	*675.00 FN
7	1		*BUMPER SIDE (CONSISTENT)	N/S Cut / O/S Not Necessary	110.00 FN	*55.00 FN
8	1		*BUMPER REINFORCEMENT (CONSISTENT)	Bent	245.00 FN	*245.00 FN
9	1		*OIL COOLER (CONSISTENT)	Bent	1,150.00 FN	*1,150.00 FN
10	1		*CORSSMEMBER (CONSISTENT)	Bent	550.00 FN	*550.00 FN
11	1		*NUMBER PLATE (CONSISTENT)	Missing	20.00 FN	*20.00 FN
12	1		*HEATED AND BLOWER (CONSISTENT)	Not Necessary	950.00 FN	*- FN
13	1		*COOLING UNIT,A/C (CONSISTENT)	Not Necessary	450.00 FN	*- FN
14	1		*WINDSCREEN SEALANT (CONSISTENT)	Necessary	40.00 FN	*40.00 FN

F=Franchise part, N=NettItemDisc.

Sub Total (\$\$)	6,500.00	4,430.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	650.00	443.00
Total Parts (\$\$)	5,850.00	3,987.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS	New	120.00	120.00
2	TO REMOVE/REFIT DASHBOARD TO FACILITATE REPAIRS	New	280.00	180.00
3	TO PANEL BEAT /REPAIR FR BODY TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS	New	1,200.00	800.00
4	TO DISMANTLE /REPLACE AIR-CON HEATER AND BLOWER TO TOP UP GAS	New	150.00	100.00
5	SPRAY PAINTING	New	700.00	500.00
6	TOWING CHARGES	New	60.00	60.00
Gross Labour Cost (\$\$)			2,510.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >