

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Saturday, 30 June, 2018 4:08 PM
To: Janet Tan
Cc: Admin A; Vic (LKKAUTO)
Subject: <SEEK MANDATE> RE: Direct Settlement - Accident Involving SJP8435Z (OI : EQI - TBA) AND SGC4444C (TP : LKK REF - CC6/EQI18003971/Uks3) on 01/03/2018
Attachments: LKK INSPECTION REPORT.pdf; LKK ADJUSTMENT REPORT.pdf; LKK INSPECTION PHOTOS.pdf; LKK REINSPECTION PHOTOS.pdf; TP LOD.pdf; LETTER TO OI.pdf
Importance: High

YOUR REF – TBA
LKK REF – CC6/EQI18003971/Uha3
=====

Dear Janet,

ACCIDENT INVOL VING VEHICLES SJP 8435Z (OI) / SGC 4444C (TP) / OTHERS ON 01/03/2018

We refer to the above matter.

It was reported that our Insured Vehicle was involved in a 3 vehicle chain collision and was the last car and rear-ended the TP vehicle.

We had spoken to the Insured Driver Mr Wang where he confirmed accident details and was informed of the TP claim, liability and agreed to settle and is aware of NCD issues on 06/03/2018.

In view of the above, our Insured is liable to the damages sustained by the TP vehicle.

Summary to offer to repairer **FASTECH AUTO PTE LTD** is as follows:

TP CLAIMED		REVISED - TO OFFER
Cost of Repair (w/gst)	\$ 39,382.74	\$ 14,445.00
Loss of Use (\$60 x 8 days)	\$ 480.00	\$ 480.00
GIA Search Fee	\$ 2.00	\$ 2.00
TOTAL	\$ 39,864.74	\$ 14,927.00

MARKET VALUE : \$86,000.00 (est)
LTA REBATE : \$57,913.00 (est)
NETT VALUE : \$28,087.00 (est)

Breakdown of days is as follows:

Our surveyor's recommended days to repair	7 days
Weekends / Downtime	1 days
TOTAL	8 days

Relevant supporting claim documents are attached herewith for your perusal and reference.

For your approval, please.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and is for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Zaini (LKK Auto)

Sent: Monday, 2 April, 2018 10:00 AM

To: Janet Tan

Cc: Admin A; Hsiao Tong (LKKAuto)

Subject: RE: Direct Settlement - Accident Involving SJP8435Z (OI : EQI - TBA) AND SGC4444C (TP : LKK REF - CC6/EQI18003971/Uks3) on 01/03/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SGC 4444C at M/s FASTECH AUTO PTE LTD.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly take note that the case handler in-charge is as stated on the undersigned.

Thank you.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Monday, 5 March 2018 9:56 AM

To: Janet Tan <janet.tan@eqinsurance.com.sg>; Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving SJP8435Z (OI : EQI - TBA) AND SGC4444C (TP : LKK REF - CC6/EQI18003971/Uks3) on 01/03/2018

Dear Janet,

Thanks and noted.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]

Sent: Monday, 5 March 2018 9:03 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: FW: Direct Settlement - Accident Involving SJP8435Z (OI : EQI - TBA) AND SGC4444C (TP : LKK REF - CC6/EQI18003971/Uks3) on 01/03/2018

Dear Shirley,

OI report as attached.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Monday, March 5, 2018 8:58 AM

To: Janet Tan <janet.tan@eqinsurance.com.sg>; Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SJP8435Z (OI : EQI - TBA) AND SGC4444C (TP : LKK REF - CC6/EQI18003971/Uks3) on 01/03/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SGC 4444C at M/s Fastech Auto Pte Ltd – Kaki Bukit.

Enclosed for your perusal is:

- TP GIA report
- Photographs of TP vehicle in its damaged condition

We will revert preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)