

 $51~\mathrm{UBI~AVE~1}, \#02\text{-}25~\mathrm{PAYA~UBI~INDUSTRIAL~PARK}, \mathrm{SINGAPORE~408933~TEL:} \\ (065)~62563561~\mathrm{FAX:} \\ (065)~62564315$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 10/9/2018

Survey Details:

Date of loss	27-Feb-18
Date of appointment	1-Mar-18
Date of survey	1-Mar-18
Location of survey	SMRT AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHF 488A
Make and Model	TOYOTA PRIUS 1798cc
Date of registration	Sep-14
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate

Proposed/Revised repair cost:

Parts	\$ 800.22
Check items (estimate)	\$0
Labour	\$ 760.00
Total	\$ 1,560.22
Lump Sum(if applicable)	\$ 1,550.00

Number of days for repair	<u>4 days</u>
	· · · · · · · · · · · · · · · · · · ·



 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\;\; FAX: (065)\; 6256415\;\; FAX: (065)\;\; FAX: (065$

Remarks:

Both drivers OI and TP reported that they changed lane. Scene photos uploaded. A letter was sent out to the Insured to inform of liability and TP claim. No feedback from OI till date. BOLA NIL - both changed lane. TP LOD IN.

Mandate:

Liability(TP)	50%	
Proposed Repair Cost	\$ 1,550.00	
Loss of Use	\$ -	No. of days
Loss of Rental	\$ 670.92	\$111.82 x 6 days
Loss of Income	\$ 360.00	\$60 x 6 days
GIA/LTA search fees	\$ 7.00	
Others	\$ -	
Proposed Total	\$ 2,587.92	
50%	\$ 1,297.46	