

ASS. REC. BY:

REF: CS/FCI 18003992/ Tlv d3ⁿ² Special Instruction: photos

Surveyor:

ASSIGNMENT (Office)

CWS

From (Person): May chuen

of FCI

Date/Time: 28/2/18 @ 9:15pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKT 22291

Insured:

SHD 42704

at Workshop m/s

cycle & Carriage France

Tel:

6568 4501

of

209 Pender Gardens

Policy No:

Claim No:

D18001669MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

'DS)

D.O.A. 25/02/18

5/3/18 @ 12pm owner waiting

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:11am 01/3/18

Person Contacted:

Don Bong

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SKT 22291 - X
	SHD 42704 - NS/INC 18003662/K/H
	D.O.A. 20/2/18
6/3/18	Email preli revised to FCI
17/7/18	check with Mr Lau, can submit report.
18/7/18	Final fig \$ 13,851 confirmed by email (Ref 5174, 2790)

Tanpin

FCI

ASSIGNMENT

Date 5/3/18

Estimated Cost

22 (P) S / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No SKT 2229J
at Workshop No Cycle & Carriage France
209 Pandan Gardens

Insured

Policy No

Claim No

Sum Insured

Excess


Diagnosis Record

12pm owner waiting
Don Bong

Make of vehicle

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Salvage / Market Value

DAC Accident Report Consistent? Yes or No

DAC PR Seen Consistent? Yes or No

Est. Repairs days Fee Yes or No

LTM Sum % 3 year Yes or No

CA / REY / REP / 24 HRS / wop

Date Person Contacted

Vehicle IN / OUT

Date Time Action / Instruction

RECEIVED 7 JUL 2018

SKT 2229 J

2015 April

Type (1) Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer

Make Citroen Grand Picasso (4 1560

Colour Grey

57442

Engine

Cyls

VF7349HCBES772900

Gen Cond (1) 2nd / 3rd / 4th / 5th / 6th / 7th / 8th / 9th / 10th

Steering (1) 1st / 2nd / 3rd / 4th / 5th / 6th / 7th / 8th / 9th / 10th

Brake (1) 1st / 2nd / 3rd / 4th / 5th / 6th / 7th / 8th / 9th / 10th

Mod N/A (1) 1st / 2nd / 3rd / 4th / 5th / 6th / 7th / 8th / 9th / 10th

Tyre Size 205 / 55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / R / SUM

TOYO / YOKO

Front

R.Ba

L.Ba

D.O.A

Surveyed at

Detail of Damages Front Rear (1) NS / UC / Roof / Floor

The U.C / Chassis frame Body Structure affected due to collision

Date Time File Pass



Prel. Report

Final Report

Days Of Repair 11

Resurvey No. of Trip 1

Date Time File Return

18/7 - typist

Add Fee



File Fee

Agent Fee

Techn Fee

Repairs Fee

Report Format

CWS

PLP \$13,851.2

LTM Sum

Survey Fee

Management

File Fee

Agent Fee

Techn Fee

Repairs Fee

9x15=135

170+135

50

50

54

08P

18/7/18

459



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003992/T1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4270U	Veh. Inspected	SKT 2229J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001669MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	01/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/02/2018	Inspection Date		
Survey held at	CYCLE & CARRIAGE FRANCE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001669MFSH

Our ref: CS/FC118003992/T1vd3

Date: 6/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKT 2229J


We thank you for your instruction on 28/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 5/3/2018 at the premises of M/s CYCLE & CARRIAGE FRANCE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$18,725.00
Revised Estimate Amount	: S\$13,167.00
"Check" Items Amount	: S\$1,579.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

Survey Department Check List (Case Handler)

Reference No.: CS/FCI 18003992/TIV03

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA/REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 18/7/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20

MOTOR SURVEY ASSIGNMENT

Date	27-02-2018	Our Ref No. D18001669MFSH
Accident Date	25-02-2018	Claim Type. Third Party
Insured Vehicle	SHD4270U	Third Party Vehicle. SKT2229J
Survey Location	209 PANDAN GARDENS	
Contact Person.	DON BONG	
Contact No.	65684501/ 0	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR - \$18725.00)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE FRANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235395)



PRI Documents



Close



PRI Header Details

Claim No	D18001669MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CYCLE & (
Workshop Name	CYCLE & CARRIAGE FRANCE PTE LTD (Contact Person : DON BONG)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 0 , Phone: 65684501 , Fax: 65651240 EmailId: KIONGHUA.BONG@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. C		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4270U	TP Vehicle No	SKT2229J
PRI Recieved Date	27-02-2018 07:06:16 PM	Surveyor Appointed Date	28-02-2018 09:14:40 PM	Surveyor Accept Date	01-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	01-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>
Sent: Friday, 27 April 2018 10:06 PM
To: Admin-D (LKKAUTO); Taufikh (LKKAUTO)
Cc: Andre Chow En De; Coco Lu Ting; Loi Ai Ting; Lauro Araos Songcuan Jr; Cheng Jo Jo
Subject: FW: SURVEYOR APPOINTED; OUR REF : D18001669MFSH ; YOUR REF: SKT2229J
Attachments: CIMG0545.JPG; CIMG0547.JPG; CIMG0548.JPG; CIMG0551.JPG; CIMG0554.JPG; CIMG0598.JPG


Importance: High

Hi Taufikh,

Attached ? /supp parts damages for you reference

No.1 Door Hinge Right INF - Bend
No.2 Bumper Bracket Set Lat - Crack
No.3 Rear Quarter Moulding Clip - Nec

Don Bong
Claim Division Operations
209 Pandan Gardens
Singapore 609339



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 1 March, 2018 11:13 AM
To: Don Bong Kiong Hua; admin-a@lkkauto.com
Cc: Andre Chow En De; Coco Lu Ting; Edwin Abcede Caina; Tay Jian Ye
Subject: RE: SURVEYOR APPOINTED; OUR REF : D18001669MFSH ; YOUR REF: SKT2229J

Dear Don,

Noted with thanks.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

From: Don Bong Kiong Hua [<mailto:kionghua.bong@cyclecarriage.com.sg>]
Sent: Thursday, 1 March, 2018 11:09 AM
To: 'admin-a@lkkauto.com' <admin-a@lkkauto.com>; Catherine Chong (LKK Auto) (admin-d@lkkauto.com) <admin-d@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>
Subject: FW: SURVEYOR APPOINTED; OUR REF : D18001669MFSH ; YOUR REF: SKT2229J
Importance: High

Hi Catherine,

As spoken, kindly arrange survey on 05.03.2018 (Mon) time 12 noon (customer is waiting).

Thanks.

Don Bong
Claim Division Operations
209 Pandan Gardens
Singapore 609339



WE DRIVE FIRST CLASS

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 28 February, 2018 9:15 PM
To: Don Bong Kiong Hua
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: SURVEYOR APPOINTED; OUR REF : D18001669MFSH ; YOUR REF: SKT2229J

Dear Sir/Madam

PRI Request For **SKT2229J** Accident Involving **SHD4270U** On 25-02-2018 AT 19:50:00HRS.

Please find below details for your reference

- Claim number : D18001669MFSH
- Insured vehicle number : SHD4270U
- Accident date : 25-02-2018
- Third-party vehicle number : SKT2229J
- Assignment type : DIRECT SETTLEMENT
- Surveyor : LKK AUTO CONSULTANTS PTE LTD

• Officer-in-Charge : MAY CHUA

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 6 March 2018 3:33 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001669MFSH/1, SKT 2229J
Attachments: SKT 2229J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKT 2229J
Date of survey: 5/3/2018
Number of days: 11 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 1 March 2018 10:32 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001669MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 28 February 2018 9:15 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001669MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 18 July 2018 12:02 PM
To: 'Lauro Araos Songcuan Jr'; Taufikh (LKKAUTO); Admin A
Cc: 'Andre Chow En De'; 'Loi Ai Ting'; 'Cheng Jo Jo'; 'Yusof Bin Hashim'; SUR
Subject: RE: SKT2229J, Cit WIP: 13264, finalisation - photos 2

Dear Larry,

WITHOUT PREJUDICE

Confirmed amount \$13,851 before GST @ 11 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 16 July 2018 4:51 PM
To: Lauro Araos Songcuan Jr <lauro.songcuan@cyclecarriage.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Yusof Bin Hashim <yusof.hashim@cyclecarriage.com.sg>
Subject: RE: SKT2229J, Cit WIP: 13264, finalisation - photos 2

Dear Larry,

Please refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lauro Araos Songcuan Jr [mailto:lauro.songcuan@cyclecarriage.com.sg]
Sent: Monday, 16 July 2018 4:36 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Cheng Jo

Jo <jojo.cheng@cyclecarriage.com.sg>; Yusof Bin Hashim <yusof.hashim@cyclecarriage.com.sg>
Subject: RE: SKT2229J, Cit WIP: 13264, finalisation - photos 2

Dear Sir/Madam,

It's been 2 months now since we send our finalization.

Kindly confirm finalized amount of \$ **13,851.00** before Gst.

Thank you so much for your kind attention.

Best regards,

Larry Songcuan
Customer Service



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4658 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Loi Ai Ting
Sent: 17 May 2018 12:45
To: Taufikh (LKKAUTO)
Cc: Lauro Araos Songcuan Jr; Cheng Jo Jo; Admin A; Admin-D (LKKAUTO); Veron Chen (LKKAUTO)
Subject: RE: SKT2229J, Cit WIP: 13264, finalisation - photos 2

Hi, Taufikh,

Please refer attached photos.

Thanks.

Regards,
Loi

From: Loi Ai Ting
Sent: Thursday, 17 May, 2018 12:44 PM
To: Taufikh (LKKAUTO)
Cc: Lauro Araos Songcuan Jr; Cheng Jo Jo; Admin A; Admin-D (LKKAUTO); 'Veron Chen (LKKAUTO)'
Subject: SKT2229J, Cit WIP: 13264, finalisation - photos 1

Hi, Taufikh,


Please confirm finalised amount at \$14,820.57.

Attached photos for your reference.

Thanks.

Best Regards,

Loi Ai Ting
Customer Service Advisor



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4556 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

MOTOR MAX PLUS
Comprehensive

Certificate No. A 28926515 QMY

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SKT2229J

2. Name of Policyholder
Yeo Kwee Ping Emily

3. Effective Date of the Commencement of Insurance for the purposes of the Act
10/04/2017

4. Date of Expiry of Insurance
09/04/2018

5. Persons or Classes of Persons entitled to drive*

Yeo Kwee Ping Emily
Tay Sze Kiat

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7631574D



Name
EMILY YEO KWEE PING
(YANG GUIPING)
杨 贵 萍

Race
CHINESE

Date of birth
22-09-1976

Sex
F

Country of birth
SINGAPORE



FOR C&C USE ONLY

3959626



NRIC No: S7631574D



Date of issue
15-11-2006

40 BLANDFORD DRIVE
SINGAPORE 559633
NRIC No: S7631574D

Date: 23/04/2011 No: 6744067

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7424001A**
Name
TAY SZE KIAT
(ZHENG ZHIJIE)

Birth Date: 29 Jul 1974
Issue Date: 10 Oct 2003

000910082F

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 04 Nov 1996

FOR C&C USE ONLY

Licence No. S7424001A

NP 428A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7424001A



Name

TAY SZE KIAT
(ZHENG ZHIJIE)

郑志杰

Race

CHINESE

Date of birth

29-07-1974

Country of birth

SINGAPORE

Sex

M



FOR C&C USE ONLY

3595100



NRIC No. S7424001A

FOR C&C USE ONLY

Date of issue

29-07-2004



10 BLANDFORD DRIVE
SINGAPORE 559833
NRIC No: S7424001A

Date: 23/04/2011

No: 6744066

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
EMILY YEO KWEE PING		Cust No/Name	/MS EMILY YEO KWEE PING
40 BLANDFORD DR		Reg No/Reg Date	SKT2229J / 10/04/2015
559833		Date In/Mileage	/ 0
		Chassis No	VF73A9HCBEJ772900
		Engine No	10JBEX3043871
Contact No	Mobile: 98415330	Make/Model	CIT/GC4P INTENSIVE 1.6 E-HDI 115 ETG
		Colour/Trim	9PM / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	26/02/2018/ 14:28	QUD	247 / DonBong	13264

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, RH REAR DOOR, CUT/WELD RH REAR FENDER, REPAIR RH FRONT DOOR , RH SIDE SILL	600		✓	3000 3600.00
E PNT88000 REMOVE AND INSTALL PARKING SENSOR			✓	60 80.00
E PNT88000 REMOVE AND RENEW RH QUATER GLASS TO FACILITATE REPAIR WORK			✓	200 300.00 ✓
E PNT88000 TO TRANSFER RH FRONT DOOR GLASS, MECHANISM, DOOR TRIM AND OTHERS ATTCAHMENT TO FACILITATE REPAIR WORK			✓	300 500.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, RH-REAR DOOR, CUT/WELD RH REAR FENDER, REPAIR RH FRONT DOOR , RH SIDE SILL AND AFFECTED PORTION			✓	2100 2520.00
M SUNDRY APPLY RH REAR QUATER GLASS SEALNT			✓	80 100.00
M SUNDRY APPLY BODY SEALANT			✓	150 200.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM			✓	60.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST			✓	300.00
M SUNDRY PERFORM RUST PREVENTION			✓	120 150.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment			✓	180.00
M SUNDRY RENEW RH REAR WHEEL DISC INCLUDING BALACNING			✓	30 30.00
E PNT88000 REMOVE INYERIOR CABIN INCLUDING FLOOR MAT TO FACILITATE REPAIR WORK			✓	300 400.00
A 20000001			X	600.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
EMILY YEO KWEE PING		Cust No/Name	/MS EMILY YEO KWEE PING
40 BLANDFORD DR		Reg No/Reg Date	SKT2229J / 10/04/2015
559833		Date In/Mileage	/ 0
		Chassis No	VF73A9HC8EJ772900
		Engine No	10JBEX3043871
Contact No	Mobile: 98415330	Make/Model	CIT/GC4P INTENSIVE 1.6 E-HDI 115 ETG
		Colour/Trim	9PM / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	26/02/2018/ 14:28	QUD	247 / DonBong	13264

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
RENEW RH REAR WHEEL HUB BEARING				50.00
M SUNDRY				
SUNDRIES				
M REAR BUMPER	1.00	858.00	0.00	858.00
M BUMPER BRACKET	1.00	258.00	0.00	258.00
M BUMPER SKIRT	1.00	313.00	0.00	313.00
M RECESS DOOR	1.00	50.00	0.00	50.00
M BRACKET SET	1.00	101.00	0.00	101.00
M BRACKET SET LAT	1.00	101.00	0.00	101.00
M BUMPER SEAL	1.00	47.00	0.00	47.00
M BUMPER BRACKET	1.00	296.00	0.00	296.00
M ANGLEPLATE	1.00	43.00	0.00	43.00
M STIFFENER LH	1.00	59.00	0.00	59.00
M STIFFENER RH	1.00	59.00	0.00	59.00
M LOW RR PAN FIX	1.00	167.00	0.00	167.00
M REAR WING RH	1.00	2429.00	0.00	2429.00
M RR QUARTER GLASS RH	1.00	181.00	0.00	181.00
M RR QTR MOULDING RH	1.00	467.00	0.00	467.00
M MOULDING CLIP	2.00	5.00	0.00	10.00
M REAR DOOR RH ASS	1.00	1361.00	0.00	1361.00
M DOOR HINGE RH INF	1.00	73.00	0.00	73.00
M DOOR HINGE RH SUP	1.00	73.00	0.00	73.00
M DOOR STOP	2.00	72.00	0.00	144.00
M REAR DOOR SEAL RH INFERIEUR	1.00	94.00	0.00	94.00
M REAR DOOR SEAL RH	1.00	200.00	0.00	200.00
M SEALING PANEL RH	1.00	106.00	0.00	106.00
M DECOR STRIP RH	1.00	146.00	0.00	146.00
M DOOR FIXINGS	1.00	219.00	0.00	219.00
M WINDOW LIFTER RH	1.00	570.00	0.00	570.00
M WINDOW OUTSIDE RH	1.00	115.00	0.00	115.00
M ALLOY WHEEL 7 J17 CH5-50	1.00	821.00	0.00	821.00
M BEARING HUB	1.00	294.00	0.00	294.00

LYS Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE: 5/3/18 @ 1230.

Confirm & accepted by

REMARKS:

Resurvey before paint

Authorized signatory and company stamp

sure e lkhanto.com

Parts	9,655.00
Labour	8,540.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	530.00
Total(w/o GST)	18,725.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor :
Company : TP FIRST CAPITAL
Emailed : 17/5/2018

P-36

VEHICLE NO : SKT 2229 J
MODEL : Citroen G4 1.6
WIP : 13264

Material	:	\$	<u>6,651.00</u>
Labour	:	\$	<u>7,200.00</u>
Sub-Total	:	\$	<u>13,851.00</u>
	:	\$	<u>13,851.00</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>13,851.00</u>
GST 7%	:	\$	<u>969.57</u>
Grand Total	:	\$	<u>14,820.57</u>
Finalise By/Date	:	<u>LOI / 17/05/18</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 11 WORKING DAYS + 4 Days (2) Weekends
+ 0 Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 15

☒ TP claim SHD4270U

☐ Claim GIA / LTA fee -

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report

PRO-FORMA INVOICE

Invoice Name & Address	Owner Name & Vehicle Info
MS FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No. 65073848	Cust No/Name /MS FIRST CAPITAL INSURANCE LINI Reg No/Reg Date SKT2229J / 10/04/2015 Date In/Mileage 09/04/2018/ 59340 Chassis/Package VF73A9HC8EJ772900 /FS515 Engine No 10JBEX3043871 Make/Model CIT/GC4P INTENSIVE 1.6 E-HDI 115 ETG Colour/Trim 9PM / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
CTP00073	Cash	16/05/2018/ 10:16	TLD	260 / AtTing	13264	0

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR. <i>→ Supp.</i>				✓ 30.00
S SPECIALISTJOB				
REPLACE RH REAR SPORTS RIM, REPLACE TYRE VALVE, CONDUCT WHEEL BALANCING	1.00	✓ 101.00	0.00	101.00
X BRACKET SET LAT	1.00	✓ 167.00	0.00	167.00
X LOW RR PAN FIX	1.00	✓ 2429.00	0.00	2429.00
X REAR WING RH	1.00	✓ 181.00	0.00	181.00
X RR QUARTER GLASS RH	1.00	✓ 467.00	0.00	467.00
X RR QTR MOULDING RH	2.00	✓ 5.00	0.00	10.00
X MOULDING CLIP	1.00	✓ 1361.00	0.00	1361.00
X REAR DOOR RH ASS	1.00	✓ 73.00	0.00	73.00
X DOOR HINGE RH INF	1.00	✓ 106.00	0.00	106.00
X SEALING PANEL RH	1.00	✓ 146.00	0.00	146.00
X DECOR STRIP RH	1.00	✓ 219.00	0.00	219.00
X DOOR FIXINGS	1.00	✓ 570.00	0.00	570.00
X WINDOW LIFTER RH	1.00	✓ 821.00	0.00	821.00
X ALLOY WHEEL 7 J17 CH5-50				
Z TEXT				
TP CLAIM FIRST CAPITAL SHD4270U				
DOA : 25.02.18				
SURVEYOR TAUFIKH LKK 05.03.18				

"Guarantee your warranty, maintain with Cycle & Carriage."

Parts	6,651.00	7% GST on	13851.00	Nett	13,851.00
Labour	6,800.00				969.57
Standard Menu	0.00				
Specialist Job	30.00			Total Payable	14,820.57
Diagnostics Job	0.00			Paid	0.00
Sundry/Others	370.00			Total Due	14,820.57
Total (w/o GST)	13,851.00				

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Company Reg No. 200609327M
 GST Reg No. MR-6500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No 65073848	Cust No/Name /MS FIRST CAPITAL INSURANCE LIM Reg No/Reg Date SKT2229J / 10/04/2015 Date In/Mileage 09/04/2018/ 59340 Chassis/Package VF73A9HC8EJ772900 /FS515 Engine No 10JBEX3043871 Make/Model CIT/GC4P INTENSIVE 1.6 E-HDI 115 ETG Colour/Trim 9PM / BK



Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No		
CTP00073	Cash	16/05/2018/ 10:16	TLD	260 / AiTing	13264	0		
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 3000.00
REPLACE DAMAGED PARTS,REPLACE REAR BUMPER, RH REAR DOOR, CUT/WELD RH REAR FENDER, REPAIR RH FRONT DOOR, RH SIDE SILL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								
E PNT88000	REMOVE AND INSTALL PARKING SENSOR TO FACILITATE REPAIR							✓ 60.00
E PNT88000	REMOVE AND REINSTALL RH REAR QUARTER GLASS TO FACILITATE REPAIR							✓ 200.00
E PNT88000	TRANSFER RH FRONT DOOR GLASS, MECHANISMS, DOOR TRIMS, AND ALL OTHER ATTACHMENTS TO FACILITATE REPAIR							✓ 300.00
E PNT98000	RESPRAY ON REAR BUMPER, RH REAR DOOR, RH REAR FENDER, RH FRONT DOOR RH SIDE SILL, AND ALL OTHER AFFECTED AREAS TO THE SAME							✓ 2100.00
M SUNDRY	APPLY RH REAR QUARTER GLASS SEALANT							✓ 80.00
M SUNDRY	APPLY BODY SEALANT							✓ 150.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							✓ 60.00
A 10028901	CONDUCT DIAGNOSTIC CHECK FOR CAR SYSTEM							✓ 300.00
M SUNDRY	PERFORM RUST PREVENTION ON AFFECTED AREAS							✓ 120.00
A WHEELALIGNMENTBP	CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT							✓ 180.00
E PNT88000	REMOVE INTERIOR CABIN INCLUDING FLOOR MAT TO FACILITATE REPAIR							✓ 300.00
M SUNDRY	SUNDRIES							✓ 20.00
A 30000001								300.00

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS

INSURANCE CO. : FIRST CAPITAL

Supplementary Parts For Registration No.: SKT 2229 J

<u>Labour</u>	<u>Cost (\$)</u>
1 Remove & install fuel tank to facilitate repair	300.00 (A)
Total Labour	300.00
Taxable amount	300.00
7% GST	21.00
Grand total	\$ 321.00

Thank You.
Yours faithfully

LOI AI TING
CUSTOMER SERVICE ADVISOR
CITROEN SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003992/T1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4270U	Veh. Inspected	SKT 2229J
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001669MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	28/02/2018
2. Vehicle Particulars & Condition			
Make & Model	CITROEN GRAND PICASSO C4	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF73A9HC8EJ772900	Colour	GREY
Odometer	57442	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R17	MICHELIN	6 mm
L/H Front Tyre	205/55 R17	MICHELIN	6 mm
R/H Rear Tyre	205/55 R17	MICHELIN	6 mm
L/H Rear Tyre	205/55 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/02/2018	Inspection Date	05/03/2018
Survey held at	CYCLE & CARRIAGE FRANCE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 2229J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	858.00	-
1	BUMPER BRACKET (SN)	NOT NECESSARY	258.00	-
1	BUMPER SKIRT (SN)	NOT NECESSARY	313.00	-
1	RECESS DOOR (SN)	NOT NECESSARY	50.00	-
1	BRACKET SET (SN)	NECESSARY	101.00	101.00
1	BRACKET SET LAT (SN)	NOT NECESSARY	101.00	-
1	BUMPER SEAL (SN)	NOT NECESSARY	47.00	-
1	BUMPER BRACKET (SN)	NOT NECESSARY	296.00	-
1	ANGLEPLATE (SN)	NOT NECESSARY	43.00	-
1	STIFFENER LH (SN)	NOT NECESSARY	59.00	-
1	STIFFENER RH (SN)	NOT NECESSARY	59.00	-
1	LOW RR PAN FIX (SN)	NECESSARY	167.00	167.00
1	REAR WING RH (SN)	BENT	2,429.00	2,429.00
1	RR QUARTR GLASS RH (SN)	NECESSARY	181.00	181.00
1	RR QTR MOULDING RH (SN)	NECESSARY	467.00	467.00
2	MOULDING CLIP (SN)	NECESSARY	10.00	10.00
1	REAR DOOR RH ASS (SN)	BENT	1,361.00	1,361.00
1	DOOR HINGE RH INF (SN)	BENT	73.00	73.00
1	DOOR HINGE RH SUP (SN)	TO REPAIR SEE LABOUR	73.00	-
2	DOOR STOP (SN)	NOT NECESSARY	144.00	-
1	REAR DOOR SEAL RH INFERIEUR (SN)	NOT NECESSARY	94.00	-
1	REAR DOOR SEAL RH (SN)	NOT NECESSARY	200.00	-
1	SEALING PANEL RH (SN)	NECESSARY	106.00	106.00
1	DECOR STRIP RH (SN)	NECESSARY	146.00	146.00
1	DOOR FIXINGS (SN)	NECESSARY	219.00	219.00
1	WINDOW LIFTER RH (SN)	BENT	570.00	570.00
1	WINDOW OUTSIDE RH (SN)	NOT NECESSARY	115.00	-
1	ALLOY WHEEL 7 J17 SH5-50 (SN)	CUT	821.00	821.00
1	BEARING HUB (SN)	NOT NECESSARY	294.00	-

Report Ref No. CS/FCI18003992/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			9,705.00	6,671.00
	LABOUR			
	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER,RH REAR DOOR,CUT/WELD RH REAR FENDER,REPAIR RH FRONT DOOR,RH SIDE SILL.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND DOOR HINGE RH SUP.		3,600.00	3,000.00
	REMOVE AND INSTALL PARKING SENSOR.		80.00	60.00
	REMOVE AND RENEW RH QUARTER GLASS TO FACILITATE REPAIR WORK.		300.00	200.00
	TO TRANSFER RH FRONT DOOR GLASS,MECHANISM,DOOR TRIM AND OTHERS ATTACHMENT TO FACILITATE REPAIR WORK.		500.00	300.00
	PAINT WORK SPRAY REAR BUMPER,RH REAR DOOR,CUT/WELD RH REAR FENDER,REPAIR RH FRONT DOOR,RH SIDE SILL AND AFFECTED PORTION.		2,520.00	2,100.00
	APPLY RH REAR QUARTER GLASS SEALANT.		100.00	80.00
	APPLY BODY SEALANT.		200.00	150.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		60.00	60.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		300.00	300.00
	PERFORM RUST PREVENTION.		150.00	120.00
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.		180.00	180.00
	RENEW RH REAR WHEEL DISC INCLUDING BALANCING.		30.00	30.00
	REMOVE INTERIOR CABIN INCLUING FLOOR MAT TO FACILITATE REPAIR WORK.		400.00	300.00
	RENEW RH REAR WHEEL HUB BEARING.	NOT NECESSARY	600.00	-
	REMOVE & STALL FUEL TANK TO FACILITATE REPAIR. (ADDITIONAL)		300.00	300.00
	-		-	-
	-		-	-
	-		-	-
			9,320.00	7,180.00
	GRAND TOTAL		19,025.00	13,851.00
RECOMMENDED COST OF REPAIRS				13,851.00

Report Ref No. CS/FCI18003992/T1vd3n2



Report Ref No. CS/FCI18003992/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.