

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146 email: ben@allswellmotor.com.sg

(3rd party claim against EQ Insurance Insured STD2204B

Estimate repair

Vehicle No. : SW 8563G Submitted by : Bm
 Make & Model : Toyota Voxy Hybrid Year Manufacture :
 Chassis No. : Engine No. :
 Date of survey :

S/No	Part Description	Qty	Unit Price	P	Disposition
01	Rear bumper / DD / WP	01	\$1190.80	✓	N
02	Dismantle & assembly of rear bumper	01	\$240	200	
03	Respraying painting of rear bumper	01	\$460	200	
04	Cups 2x (11.11) ✓ NEC	02	\$22.00	✓	N
* → Parts (List)			\$1190.80		
Discount 25%		-	\$297.70		
			\$893.10		
Parts (S/Nett)		+	\$122.00		
Labour / S.P			\$915.10		
Total			\$1315.10		
* Repair Bill →			\$1315.10		
2 Days (Part By Part) Repair					
* Lump Sum 20				\$1500	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

1972.80