

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

01st March 2018BLOCK 3020A UBI ROAD 1
01-33

Singapore 408714

Tall
Xiao TangAccident date: 27th feb 2018

Estimated repair cost for vehicle no: SKZ8043G HONDA FIT 1.3 A

S/n	Qty	Items	U/price	Amount
1	1	rear fender -RH <i>Repair</i>		\$650.00 *
2	1	Rear fender inner trim board		\$386.10 *
3	10	Rear fender inner trim board clips <i>new</i>	\$5.00	\$50.00 *
4	1	Rear shock absorber		\$190.70 *
5	1	Rear knuckle bearing		\$250.70 *
6	1	rear rim -RH <i>new</i>		\$400.00 *
7	1	Rear tail lamp-RH	\$368.10	\$368.10 *
8	1	Rear tail lamp panel-RH <i>new</i>		\$128.40 *
9	1	Rear tail lamp inner panel		\$110.00 *
10	2	Rear tail lamp clips	\$6.50	\$13.00 *
11	1	Rear Bumper <i>Repair</i>		\$853.00 *
12	1	Rear Bumper Side Bracket <i>new</i>		\$68.70 *
13	8	Rear bumper clips	\$5.00	\$40.00 *
14	1	Rear Bumper reverse sensor		\$350.00 *

Subtotal :- \$3,858.70

Labour charges

To remove & re-fix cushion

\$120.00 *

Tuff Kote

\$100.00 *

To Check Wiring System

\$60.00 *30*

Tuff Kote

\$120.00 *

Panel beating

\$600.00 *100*

Spray painting

\$600.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Subtotal :- \$1,600.00

Total:- \$5,458.70

total: 730 (P/P),
030mp.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5685D

Vehicle Details

Vehicle No: SKZ8043G
Vehicle to be Exported: Yes
Intended Deregistration Date: 18 Oct 2018
Vehicle Make: HONDA
Vehicle Model: FIT 1.3A
Primary Colour: Silver
Manufacturing Year: 2006
Engine No: L13A2296207
Chassis No: GD12375623
Maximum Power Output: 63.0 kW (84 bhp)
Open Market Value: \$12,569.00
Original Registration Date: 05 Feb 2007
First Registration Date: 05 Feb 2007
Transfer Count: 3
Actual ARF Paid: \$8,870.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 04 Feb 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$25,197.00
COE Rebate Amount: \$16,614.00
Total Rebate Amount: \$16,614.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Oct 2018

OK