

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

22/02/2018

Owner: MKM CAR LEASING PTE LTD

Not Authorized
L15887
Resurvey After Paint
6 days

ESTIMATE TO REPAIR TOYOTA ESTIMA - SJL2879L

1pc	rear tailgate	Bj	\$ 1,718.45	✓
1pc	rear tailgate "TOYOTA" logo	mu	\$ 51.10	X
1pc	rear tailgate "ESTIMA" emblem	mu	\$ 53.90	✓
1pc	rear tailgate "X" emblem	mu	\$ 61.10	✓
1pc	rear tailgate RH reflector	su	\$ 374.50	?
1pc	rear tailgate centre reflector	su	\$ 281.25	X
1pc	rear tailgate outer chrome	su	\$ 581.90	X
1pc	rear tailgate inner lock	mu	\$ 581.75	✓
1pc	rear tailgate inner rubber	mu 100%	\$ 374.45	50% mu
1pc	rear tailgate inner garnish		\$ 381.90	?
1pc	rear tailgate inner handle	su	\$ 122.10	X
1pc	rear LH taillamp	su	\$ 581.90	X
1pc	rear bumper	Bj	\$ 581.90	✓
2pcs	rear bumper side retainer 1 @\$132.25	dis D.Y	\$ 264.50	✓
2pcs	rear bumper side retainer 2 @\$121.25	dis D.Y	\$ 242.50	✓
1pc	rear bumper RH side reflector	su	\$ 191.60	X
1pc	rear end panel	Bj	\$ 781.10	✓
1pc	rear end panel inner top garnish	my D.Y	\$ 374.45	—
1pc	rear end panel inner lower garnish	Bu	\$ 281.50	—
2pcs	rear fender inner garnish @\$781.10	dis Bu	\$ 1,562.20	✓
1pc	rear float panel trim		\$ 974.45	?
			<u>\$ 10,418.50</u>	
	less 25%		<u>\$ 2,604.63</u>	
			<u>\$ 7,813.88</u>	
1set	rear parking sensor	s.nett	\$ 280.00	?
	remove & refit rear windscreen glass		\$ 150.00	12cl
	wiring		\$ 80.00	2cl
	tuffkote		\$ 80.00	6cl
	spray painting		\$ 1,000.00	72cl
	labour charges		\$ 1,200.00	70cl
	Total		<u><u>\$ 10,603.88</u></u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

