

15/5/2010

INS. CASE OWNER:

Priya

CC4 / III1800462

P. 2. 1/1/13

LKK:

IDAC:

Surveyor:

MA CHIN FOOK

DOI:

ASSIGNMENT

06/03/13

Date / Time:

05/03/13

Registered in Merimen:

05/03/13

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH 6525X

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: ROH KEE CAEONG

Driver Tel No.:

(V/L YES / NO)

Claim No.:

MCT18020940

Policy No.:

MCOM 0015

Make / Model:

HYUNDAI SONATA - 2.0 (A)

Place of Accident:

GAMBAS AVE > YISHUN AVE 7

OI GIA REPORT YES / NO ; TP GIA REPORT YES / NO

Insured Liability:

% Final ? Yes / No

SH 6525X

9LD 336T

9LD 3374D



INSRS:

WSP: EM-1 AUTO

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date/Time | STAGE | DATE / PIC |
|----------------|-----------------------------------|------------|
| 05/03/13 (vic) | Non-Reporting ltr (1st): | |
| 10/04/13 | Non-Reporting ltr (2nd): | |
| | Non-Reporting ltr (Final): | |
| | Notification ltr (if non-pickup): | |
| | Call OI: | |
| | After call ltr to OI: | |
| 11/04/13 | Documentation Check List: Handler | Typist |
| 19/04/13 | Notification ltr (if non-pickup) | |
| | After call ltr to OI: | |
| | Authorisation To Act: | |
| | Release Voucher: | |
| | Final Repair Bill: | |
| | Car Rental Invoice: | |
| | Towing Invoice: | |
| | LTA / GIA: | |
| | Medical Bill: | |
| | PIR: | |
| | Mandate/Reject Instruction: | |
| | LOD: | |
| | Payment Breakdown Form: | |
| | Post-Repair Photos: | |
| | Others: | |
| 08/05/13 | TYPE REPORT FOR WINDSHIELD | |
| | REPORT DONE | |
| 15/8/13 | File -> Juti to send DV. | |
| 20/9/13 | File pass to LSP to close. | |

| PRELIMINARY ADVICE | Date/Time: | Sent By: | Confirm with: | Confirm by: |
|---|---|------------|----------------------------------|--|
| FINALIZATION | Date/Time: | | Confirm with: | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| Repair Cost: | SS 12,600.00 | 13 days | Reduction: 47 % | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| FINAL SETTLEMENT | Date/Time: | 15/9/13 | Confirm with: PAFF Karen | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| Final Liability: | % 100 | | Agreed / Assessed) BOLA S/N No.: | 100% |
| Repair Cost: | SS 12,519.00 | | | |
| Loss of Rental (LOR): | SS 1353.55 | 11 days | X @ 115 | |
| Loss of Use (LOU): | SS - | (S x days) | | |
| Loss of Income (LOI): | SS - | (S x days) | | |
| LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> | LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> | | [Tick only one] | |
| GIA/LTA Search | SS 29.00 | | | |
| Medical: | SS - | | (e.g. Tow) Independent) | |
| Disbursement: | SS 60.00 | | | |
| Legal Cost | SS - | | | |
| Total: | SS 13,961.55 | | Global Sum SS: 13,950.00 | Email <input type="checkbox"/> Call <input type="checkbox"/> |
| FINAL PAYMENT | Date/Time: | | Confirm with: | |
| Payee 1: | SS 13,950.00 | | Name 1: | EM-1 AUTO PGB LTD |
| Payee 2: (Strike if N.A.) | SS - | | Name 2: | |
| Payee 3: (Strike if N.A.) | SS - | | Name 3: | |




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|----------------------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | Ref : CC4/AIG18000108/Ges3 | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 | | Date : 03-01-2018 |  |
| | | Code : AIG | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SBD 4810H | Veh. Inspected | SKV 7555Z |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 03/01/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 28/12/2017 | Inspection Date | 02/01/2018 |
| Survey held at | ALLSWELL MOTOR TRADERS 100 JALAN SULTAN #02-41 SULTAN PLAZA SINGAPORE 199001 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) displayed for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) contact
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Acknowledged by Repairer

Vehicle Number : SLD 336T

Vehicle Model : HONDA CIVIC

Accident Date : 28.02.2018

Original Reg Date : 17.05.2006

Date : 02.03.2018

Chassis : JHMF163065207880

TP Ins. INDIA

ESTIMATE

| | | | | | | |
|----|-------|---|---|--------|--------|---------|
| 1 | 1 pc | Boot Lid Assy | ✓ | | 690.50 | bt |
| 2 | 1 pc | Boot Lid Badge | ✓ | | 52.20 | ncc |
| 3 | 1 pc | Boot Lid Emblem CIVIC | ✓ | | 52.00 | ncc |
| 4 | 1 pc | Boot Lid Emblem 1.8 | ✓ | | 48.00 | ncc |
| 5 | 1 pc | Boot Lid Emblem IVTEC | ✓ | | 48.00 | ncc |
| 6 | 2 pcs | Boot Lid Number Plate Lamps | X | 52.00 | 104.00 | bt |
| 7 | 1 pc | Boot Lid Number Plate Outer Garnish | ✓ | | 192.20 | dis |
| 8 | 1 set | Boot Lid Number Plate Outer Garnish Clips | ✓ | | 30.00 | 20 ncc |
| 9 | 1 pc | Boot Lid Key Lock | X | | 127.20 | bt |
| 10 | 2 pcs | Boot Lid Lamps | ✓ | 280.00 | 560.00 | avg |
| 11 | 2 set | Boot Lid Lamp Inner Sealer | ✓ | 38.00 | 76.00 | ncc |
| 12 | 2 set | Boot Lid Lamp Clips | ✓ | 25.00 | 50.00 | 20 |
| 13 | 1 pc | Boot Lid Stopper 'Long' | ✓ | 22.00 | 44.00 | ncc/dis |
| 14 | 1 pc | Boot Lid Inner Lock | ✓ | | 194.00 | bt |
| 15 | 1 pc | Boot Lid Lock Catch | ✓ | | 46.20 | bt |
| 16 | 1 pc | Boot Lid Weatherstrip | ✓ | | 159.20 | dis |
| 17 | 2 pcs | Boot Lid Hinges | X | 56.20 | 112.40 | 2 |
| 18 | 1 pc | Rear Bumper Assy | ✓ | | 689.20 | det |
| 19 | 2 pcs | Rear Bumper Side Retainers | ✓ | 38.00 | 76.00 | dis |
| 20 | 1 set | Rear Bumper Clips | ✓ | | 50.00 | ncc |
| 21 | 1 pc | Rear Bumper Lower Arch Garnish | X | | 69.10 | bt |
| 22 | 2 pcs | Rear Bumper Mudflaps | X | 92.00 | 184.00 | bt |
| 23 | 2 pcs | Taillamps Assy | ✓ | 339.20 | 678.40 | avg |
| 24 | 2 pcs | Taillamp Inner Sealer | ✓ | 38.00 | 76.00 | ncc |
| 25 | 2 set | Taillamp Clips | ✓ | 25.00 | 50.00 | 20 ncc |
| 26 | 2 pcs | Taillamp Lower Retainer | ✓ | 36.00 | 72.00 | dis |
| 27 | 1 pc | End Panel Assy | ✓ | | 592.50 | bt |
| 28 | 1 pc | End Panel Top Trim | ✓ | | 95.20 | dis |
| 29 | 1 pc | End Panel Top Trim Cover | X | | 36.20 | bt |
| 30 | 1 set | End Panel Top Trim Clips | ✓ | ncc | 30.00 | 20 |
| 31 | 1 pc | Spare Tyre Panel | ✓ | | 952.60 | bt |

C/F

6,237.10

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLD 336T

B/F

6,237.10

| | | | | | | |
|----|-------|--|---|----------|----------|-------------|
| 1 | 1 pc | Spare Tyre Panel Top Board | ✓ | | 321.80 | dis |
| 2 | 1 pc | Spare Tyre Panel Top Tools Sponge | X | | 116.20 | gve |
| 3 | 1 pc | Spare Tyre Wheel Nut | X | | 42.00 | gve |
| 4 | 1 pc | Rear Chassis Frame Members | X | -544.00 | 544.00 | R. |
| 5 | 2 pcs | Rear Air Vent | X | -42.60 | 85.20 | gve |
| 6 | 2 pcs | Rear Fender Inner Trims | ✓ | 223.00 | 446.00 | dis |
| 7 | 2 set | Rear Fender Inner Trim Clips | ✓ | 30.00 | 60.00 | h.e |
| 8 | 1 pc | Rear Exhaust Silencer | ✓ | DEF | 629.30 | R.S.S.S.N |
| 9 | 2 pcs | Rear Exhaust Mountings | X | -38.00 | 76.00 | gve |
| 10 | 1 pc | Rear Exhaust Gasket | ✓ | | 46.20 | h.e |
| 11 | 1 pc | Rear Exhaust Heat Plate | X | | 93.10 | gve |
| 12 | 1 pc | Bonnet Inner Lock | X | | 97.20 | R. |
| 13 | 1 pc | Front Bumper | ✓ | | 692.60 | def |
| 14 | 2 pcs | Front Bumper Side Retainers | ✓ | 38.00 | 76.00 | dis |
| 15 | 1 set | Front Bumper Clips | ✓ | | 50.00 | h.e |
| 16 | 1 pc | Front Bumper Reinforcement | ✓ | | 272.00 | DD |
| 17 | 1 pc | Front Bumper Reinforcement Bracket | X | 69.00 | 138.00 | NN |
| 18 | 1 pc | Front Bumper Number Plate Base Garnish | X | | 56.00 | gve |
| 19 | 2 pcs | Front Bumper Fog Lamps RH-CRA, LH-NN | ✓ | 296.40 | 592.80 | 296.40 |
| 20 | 2 pcs | Front Bumper Fog Lamps Cover RH-CRA, LH-NN | ✓ | 36.00 | 72.00 | 36.00 |
| 21 | 1 pc | Front Grille | ✓ | | 196.50 | dis |
| 22 | 1 pc | Front Grille Chrome Moulding | ✓ | | 198.50 | dis |
| 23 | 1 pc | Front Grille Badge | ✓ | | 52.00 | h.e |
| 24 | 1 set | Front Grille Clips | ✓ | | 30.00 | h.e |
| 25 | 2 pcs | Headlamps LH-NN | ✓ | 1,774.50 | 3,549.00 | gve 1774.50 |
| 26 | 2 pcs | Headlamps Lower Retainers LH-NN | ✓ | 46.00 | 92.00 | 46.00 |
| 27 | 2 set | Headlamps Clips | X | 20.00 | 40.00 | 20.00 |
| 28 | 1 pc | Front Fender RH | X | | 520.00 | |
| 29 | 1 pc | Front Fender Inner Shield RH | ✓ | | 119.00 | |
| 30 | 1 set | Front Fender Inner Shield Clip | ✓ | | 25.00 | |
| 31 | 1 pc | Front Fender Top Garnish RH | X | | 59.00 | |
| 32 | 1 pc | Support Panel | X | | 612.50 | |
| 33 | 1 pc | Support Panel Top Garnish | ✓ | | 149.30 | |
| 34 | 1 set | Support Panel Top Garnish Clips | ✓ | | 40.00 | 20 |

C/F

16,426.30

5065.80

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLD 336T

B/F

16,426.30

| | | | | | |
|---|-------|--------------------------|---|---|----------|
| 1 | 1 set | Horns | ✓ | 7 | 120.00 |
| 2 | 1 pc | Radiator | ✓ | 7 | 1,507.00 |
| 3 | 1 pc | Air Con Condenser | ✓ | 7 | 852.40 |
| 4 | 1 pc | Condenser Air Con Pipe | X | X | -196.00 |
| 5 | 1 pc | Condenser Suction Pipe | X | X | -212.00 |
| 6 | 1 pc | Condenser Discharge Pipe | X | X | -247.00 |
| 7 | 1 pc | Dashboard Center Console | ✓ | 7 | 426.00 |
| 8 | 1 pc | Meter Box Outer Garnish | ✓ | 7 | 487.10 |

20,473.80

Less 20% 5,118.45

15,355.35

Special Nett

| | | | | | |
|----|-------|--------------------------------|-----|--------|----------|
| 1 | 1 pc | Rear Number Plate with Holder | 40 | | -70.00 |
| 3 | 1 pc | Body Panel Joint Sealant | 80 | | 120.00 |
| 4 | 1 pc | Rear Floor Panel Insulator Pad | 120 | | -150.00 |
| 5 | 1 set | Reverse Sensor | 220 | | 250.00 |
| 6 | 1 pc | Reverse Camera | 350 | | 450.00 |
| 7 | 2 pcs | Rear Exhaust Chrome Pipe | 120 | 120.00 | 240.00 |
| 8 | 1 pc | Front Number Plate with Cover | 40 | | -70.00 |
| 9 | 1 pc | Radiator Coolant | 40 | | -40.00 |
| 10 | 1 pc | Radio Set | 400 | | 7,850.00 |

Labour charge

| | | |
|---|------|-----------|
| Panel Beating | 1800 | -2,600.00 |
| Spray painting | 1700 | 2,400.00 |
| Check Wiring | 60 | 100.00 |
| Anti rust | 90 | 180.00 |
| Remove and install carpet and seat. | 80 | -120.00 |
| Remove and install reverse sensor. | 60 | -90.00 |
| Remove and install reverse camera. | 80 | 150.00 |
| Remove and install rear silencer. | 80 | 120.00 |
| Remove and install petrol tank. | 80 | 120.00 |
| To jack and align rear chassis frame member | - | -350.00 |
| Remove and install air con. | 120 | 150.00 |

\$ 23,975.35

| | | | | |
|----|--------|----------|--------|----------|
| 1 | 690.50 | 321.80 | 40.00 | 1,800.00 |
| 2 | 52.20 | | 80.00 | 1,700.00 |
| 3 | 52.00 | | 120.00 | 60.00 |
| 4 | 48.00 | | 220.00 | 90.00 |
| 5 | 48.00 | | 350.00 | 80.00 |
| 6 | | 446.00 | 120.00 | 60.00 |
| 7 | 192.20 | 60.00 | 40.00 | 80.00 |
| 8 | 20.00 | | 40.00 | 80.00 |
| 9 | | | 400.00 | 80.00 |
| 10 | 560.00 | 46.20 | | |
| 11 | 76.00 | | 250.00 | 120.00 |
| 12 | 20.00 | | | |
| 13 | 44.00 | 692.60 | | |
| 14 | 194.00 | 76.00 | | |
| 15 | 46.20 | 50.00 | | |
| 16 | 159.20 | 272.00 | | |
| 17 | | | | |
| 18 | 689.20 | | | |
| 19 | 76.00 | 296.40 | | |
| 20 | 50.00 | 36.00 | | |
| 21 | | 196.50 | | |
| 22 | | 198.50 | | |
| 23 | 678.40 | 52.00 | | |
| 24 | 76.00 | 30.00 | | |
| 25 | 20.00 | 1,774.50 | | |
| 26 | 72.00 | 46.00 | | |
| 27 | 592.50 | 20.00 | | |
| 28 | 95.20 | | | |
| 29 | | 119.00 | | |
| 30 | 20.00 | 25.00 | | |
| 31 | 952.60 | | | |
| 32 | | | | |
| 33 | | 149.30 | | |
| 34 | | 20.00 | | |
| 35 | | 120.00 | | |
| 36 | | 1,507.00 | | |
| 37 | | 852.40 | | |
| 38 | | | | |
| 39 | | | | |
| 40 | | | | |
| 41 | | 426.00 | | |
| 42 | | 487.10 | | |

| | | |
|-----------------------------|----|-----------|
| Total List Price | \$ | 13,844.50 |
| Discount | | 20% |
| List Price (after Discount) | \$ | 11,075.60 |
| Total Nett Price | | |
| Discount | | 10% |
| Nett Price (after Discount) | \$ | - |
| Total Special Nett | \$ | 1,660.00 |
| Total Labour | \$ | 4,150.00 |
| Grand Total | \$ | 16,885.60 |
| Discount 20% | | 20% |
| Lump Sum Repair Cost | \$ | 13,508.48 |

\$ 13,500.00

| Columns | |
|---------------------------|--------------|
| A | Serial No. |
| B | List Price |
| C (contiune frm column B) | List Price |
| D | Special Nett |
| E | Labour |

FILE NO. : 5226

VEHICLE NO.
SLD 336T

DOA :
28.02.2018

MODEL NO.
HONDA CIVIC

RENTAL :
15 DAYS

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2604G

Vehicle Details

Vehicle No.: SLD336T

Vehicle to be Exported: Yes

Intended De-registration Date: 02 Mar 2018

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.8 LA

Primary Colour: Silver

Manufacturing Year: 2006

Engine No.: R18A11026695

Chassis No.: JHMFD16306S207880

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$20,907.00

Original Registration Date: 17 May 2006

First Registration Date: 17 May 2006

Transfer Count: 1

Actual ARF Paid: \$22,998.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 May 2021

COE Category: B - Car (1601cc & above)

COE Period(Years): 5

PQP Paid: \$23,024.00

COE Rebate Amount: \$14,755.00

Total Rebate Amount: \$14,755.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 01 Mar 2018

OK



Honda Civic Price Range Depreciation > 10 year(s) of Vehicle Type Search

Advanced Search

Home » Used Cars » Esprit Motor Trading » Honda Civic 1.8A (COE till 08/2021)

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Car Tyres



① >

Top
Coworking
Space in
SG

Collaborative
Workspaces,
Professional
Community,
Events &
Growth - All
under (

The Workle



Compare

Honda Civic 1.8A (COE till 08/2021)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

| | | |
|---------------|---|---------|
| Price | \$33,800 | ? |
| Depreciation | \$9,650 /yr | ? |
| Reg Date | 07-Sep-2006 (3yrs 5mths 30days COE left) | 17/5/06 |
| Manufactured | 2006 | ? |
| Mileage | 16,000 km (1.4k /yr) | |
| Transmission | Auto | |
| Engine Cap | 1,799 cc | |
| Road Tax | \$1,174 /yr | ? |
| Power | 103.0 kW (138 bhp) View specs of the Honda Civic (2006-2012) | |
| Curb Weight | 1,219 kg | ? |
| Features | - | |
| Accessories | - | |
| COE | \$27,232 | ? |
| OMV | \$21,245 | ? |
| ARF | \$23,370 | ? |
| Dereg Value | \$19,085 as of today (change) | ? |
| No. of Owners | 6 | ? |
| Type of Veh | Mid-Sized Sedan | |
| Category | COE Car, Low Mileage Car | |
| Availability | Available | |

Add to Shortlist Add to Compare Add a Note

Posted on: 15-Feb-2018 | Last Updated on: 15-Feb-2018

Tags: Honda Civic, 2006 Honda Civic, Honda, Civic, Used Honda

Upfront Payment

* more Financial info

| | | |
|-----------------------|--------------------------------|--------------------|
| Transfer Fee | \$25 | ? |
| Down Payment | \$10,140 (change) | Maximum 70% Loan ? |
| 1st Instalment | \$651 | ? |
| Total Upfront Payment | \$10,816 (excluding insurance) | ? |

Estimates based on 70% loan at 3.75% interest rate. Check with seller for exact figure.

Items for Honda Civic

* View All



GT Wing Spoiler
\$280



Scuff Plate
\$10



Location Map

Seller Information

| | |
|-------------------|---|
| Company | Esprit Motor Trading » dealer's pricelist » 1 vehs sold 17 vehs available |
| Address | 210 Turf Club Road Lot C10 Search cars nearby this location |
| Location | Car Mall @ The Grandstand |
| Office No | 64568623 |
| Contact Person(s) | Francis Goh 96608623 |

Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Svy-

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|---|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 2604G |
| Vehicle Details | |
| Vehicle No.: | SLD336T |
| Vehicle to be Exported: | Yes |
| Intended De-registration Date: | 02 Mar 2018 |
| Vehicle Make: | HONDA |
| Vehicle Model: | CIVIC 1.8L A |
| Primary Colour: | Silver |
| Manufacturing Year: | 2006 |
| Engine No.: | R18A11026695 |
| Chassis No.: | JHMFD16306S207880 |
| Maximum Power Output: | 103.0 kW (138 bhp) |
| Open Market Value: | \$20,907.00 |
| Original Registration Date: | 17 May 2006 |
| First Registration Date: | 17 May 2006 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$22,998.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Forfeited |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 16 May 2021 |
| COE Category: | B - Car (1601cc & above) |
| COE Period(Years): | 5 |
| PQP Paid: | \$23,024.00 |
| COE Rebate Amount: | \$14,755.00 |
| Total Rebate Amount: | \$14,755.00 |
| Message | |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 01 Mar 2018

OK

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLD 336T
Vehicle Model : HONDA CIVIC
Accident Date : 28.02.2018
Original Reg Date : 17.05.2006

Date : 02.03.2018
Chassis : JHMF163065207880
TP Ins. INDIA

ESTIMATE

| | | | | | |
|----|-------|---|--------|--------|----------|
| 1 | 1 pc | Boot Lid Assy | | 690.50 | HA |
| 2 | 1 pc | Boot Lid Badge | | 52.20 | HA |
| 3 | 1 pc | Boot Lid Emblem CIVIC | | 52.00 | HA |
| 4 | 1 pc | Boot Lid Emblem 1.8 | | 48.00 | HA |
| 5 | 1 pc | Boot Lid Emblem IVTEC | | 48.00 | HA |
| 6 | 2 pcs | Boot Lid Number Plate Lamps | 52.00 | 104.00 | HA |
| 7 | 1 pc | Boot Lid Number Plate Outer Garnish | | 192.20 | dis |
| 8 | 1 set | Boot Lid Number Plate Outer Garnish Clips | | 30.00 | 20 HA |
| 9 | 1 pc | Boot Lid Key Lock | | 127.20 | HA |
| 10 | 2 pcs | Boot Lid Lamps | 280.00 | 560.00 | avg |
| 11 | 2 set | Boot Lid Lamp Inner Sealer | 38.00 | 76.00 | HA |
| 12 | 2 set | Boot Lid Lamp Clips | 25.00 | 50.00 | 20 |
| 13 | 1 pc | Boot Lid Stopper 'Long' | 22.00 | 44.00 | HA (dis) |
| 14 | 1 pc | Boot Lid Inner Lock | | 194.00 | HA |
| 15 | 1 pc | Boot Lid Lock Catch | | 46.20 | HA |
| 16 | 1 pc | Boot Lid Weatherstrip | | 159.20 | dis |
| 17 | 2 pcs | Boot Lid Hinges | 56.20 | 112.40 | R |
| 18 | 1 pc | Rear Bumper Assy | | 689.20 | det |
| 19 | 2 pcs | Rear Bumper Side Retainers | 38.00 | 76.00 | dis |
| 20 | 1 set | Rear Bumper Clips | | 50.00 | HA |
| 21 | 1 pc | Rear Bumper Lower Arch Garnish | | 69.10 | HA |
| 22 | 2 pcs | Rear Bumper Mudflaps | 92.00 | 184.00 | HA |
| 23 | 2 pcs | Taillamps Assy | 339.20 | 678.40 | avg |
| 24 | 2 pcs | Taillamp Inner Sealer | 38.00 | 76.00 | HA |
| 25 | 2 set | Taillamp Clips | 25.00 | 50.00 | 20 |
| 26 | 2 pcs | Taillamp Lower Retainer | 36.00 | 72.00 | dis |
| 27 | 1 pc | End Panel Assy | | 592.50 | HA |
| 28 | 1 pc | End Panel Top Trim | | 95.20 | dis |
| 29 | 1 pc | End Panel Top Trim Cover | | 36.20 | HA |
| 30 | 1 set | End Panel Top Trim Clips | | 30.00 | 20 |
| 31 | 1 pc | Spare Tyre Panel | | 952.60 | HA |

C/F

6,237.10

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLD 336T

B/F

6,237.10

| | | | | | |
|----|-------|--|----------|----------|----------|
| 1 | 1 pc | Spare Tyre Panel Top Board | | 321.80 | dis |
| 2 | 1 pc | Spare Tyre Panel Top Tools Sponge | | 116.20 | orc |
| 3 | 1 pc | Spare Tyre Wheel Nut | | 42.00 | orc |
| 4 | 1 pc | Rear Chassis Frame Members | 544.00 | 544.00 | R. |
| 5 | 2 pcs | Rear Air Vent | 42.60 | 85.20 | orc |
| 6 | 2 pcs | Rear Fender Inner Trims | 223.00 | 446.00 | dis |
| 7 | 2 set | Rear Fender Inner Trim Clips | 30.00 | 60.00 | orc |
| 8 | 1 pc | Rear Exhaust Silencer | | 629.30 | R 250 SN |
| 9 | 2 pcs | Rear Exhaust Mountings | 38.00 | 76.00 | orc |
| 10 | 1 pc | Rear Exhaust Gasket | | 46.20 | orc |
| 11 | 1 pc | Rear Exhaust Heat Plate | | 93.10 | orc |
| 12 | 1 pc | Bonnet Inner Lock | | 97.20 | R. |
| 13 | 1 pc | Front Bumper | | 692.60 | det |
| 14 | 2 pcs | Front Bumper Side Retainers | 38.00 | 76.00 | dis |
| 15 | 1 set | Front Bumper Clips | | 50.00 | orc |
| 16 | 1 pc | Front Bumper Reinforcement | | 272.00 | |
| 17 | 1 pc | Front Bumper Reinforcement Bracket | 69.00 | 138.00 | |
| 18 | 1 pc | Front Bumper Number Plate Base Garnish | | 56.00 | orc |
| 19 | 2 pcs | Front Bumper Fog Lamps | 296.40 | 592.80 | |
| 20 | 2 pcs | Front Bumper Fog Lamps Cover | 36.00 | 72.00 | |
| 21 | 1 pc | Front Grille | | 196.50 | dis |
| 22 | 1 pc | Front Grille Chrome Moulding | | 198.50 | dis |
| 23 | 1 pc | Front Grille Badge | | 52.00 | orc |
| 24 | 1 set | Front Grille Clips | | 30.00 | orc |
| 25 | 2 pcs | Headlamps | 1,774.50 | 3,549.00 | orc |
| 26 | 2 pcs | Headlamps Lower Retainers | 46.00 | 92.00 | orc |
| 27 | 2 set | Headlamps Clips | 20.00 | 40.00 | orc |
| 28 | 1 pc | Front Fender RH | | 520.00 | orc |
| 29 | 1 pc | Front Fender Inner Shield RH | | 119.00 | orc |
| 30 | 1 set | Front Fender Inner Shield Clip | | 25.00 | orc |
| 31 | 1 pc | Front Fender Top Garnish RH | | 59.00 | orc |
| 32 | 1 pc | Support Panel | | 612.50 | orc |
| 33 | 1 pc | Support Panel Top Garnish | | 149.30 | orc |
| 34 | 1 set | Support Panel Top Garnish Clips | | 40.00 | 20 |

C/F

16,426.30

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

LKK Auto Consultants hence notify

the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

16,426.30

B/F

Vehicle No : SLD 336T

| | | | | |
|---|-------|--------------------------|---|----------|
| 1 | 1 set | Horns | 7 | 120.00 |
| 2 | 1 pc | Radiator | 7 | 1,507.00 |
| 3 | 1 pc | Air Con Condenser | 7 | 852.40 |
| 4 | 1 pc | Condenser Air Con Pipe | X | 196.00 |
| 5 | 1 pc | Condenser Suction Pipe | X | 212.00 |
| 6 | 1 pc | Condenser Discharge Pipe | X | 247.00 |
| 7 | 1 pc | Dashboard Center Console | 7 | 426.00 |
| 8 | 1 pc | Meter Box Outer Garnish | 7 | 487.10 |

20,473.80

Less 20% 5,118.45

15,355.35

Special Nett

| | | | | | |
|----|-------|--------------------------------|--------|----------|-------------|
| 1 | 1 pc | Rear Number Plate with Holder | | 70.00 | 40. cut |
| 3 | 1 pc | Body Panel Joint Sealant | | 120.00 | 50% 2 |
| 4 | 1 pc | Rear Floor Panel Insulator Pad | | 150.00 | 120. h.c |
| 5 | 1 set | Reverse Sensor | | 250.00 | 220. 2nd |
| 6 | 1 pc | Reverse Camera | | 450.00 | 350. 2nd |
| 7 | 2 pcs | Rear Exhaust Chrome Pipe | 120.00 | 240.00 | 120? 40 am. |
| 8 | 1 pc | Front Number Plate with Cover | | 70.00 | 2 |
| 9 | 1 pc | Radiator Coolant | | 40.00 | |
| 10 | 1 pc | Radio Set | 500. | 7,850.00 | |

Labour charge

| | | |
|---|----------|------|
| Panel Beating | 2,600.00 | 1800 |
| Spray painting | 2,400.00 | 1700 |
| Check Wiring | 100.00 | 60 |
| Anti rust | 180.00 | 90 |
| Remove and install carpet and seat. | 120.00 | 80 |
| Remove and install reverse sensor. | 90.00 | 60 |
| Remove and install reverse camera. | 150.00 | 80 |
| Remove and install rear silencer. | 120.00 | 80 |
| Remove and install petrol tank. | 120.00 | 80 |
| To jack and align rear chassis frame member | 350.00 | X |
| Remove and install air con. | 150.00 | 120? |

\$ 23,975.35

Shirley Hiew (LKK Auto)

From: Admin-D (LKKAuto)
Sent: Monday, 5 March 2018 1:57 PM
To: 'Motor Claim - III'; assignments; Admin A
Cc: 'Manivel Priyadarshini'
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLD336T (Accident involving SLD336T and SH6525X on 28.02.2018)

Dear Gabriel,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
Sent: Monday, 5 March, 2018 1:40 PM
To: Chia Sin Muk <em1autopteltd@gmail.com>; 'sur@lkkauto.com' <sur@lkkauto.com>; Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Cc: Manivel Priyadarshini <manivel@iii.com.sg>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLD336T (Accident involving SLD336T and SH6525X on 28.02.2018)

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLD336T and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Chia Sin Muk [<mailto:em1autopteltd@gmail.com>]
Sent: 05 March, 2018 10:43 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLD336T (Accident involving SLD336T and SH6525X on 28.02.2018)

WITHOUT PREJUDICE

Dear All,

We request LKK Auto Consultant P/L to survey our client's vehicle.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380K

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On 2 March 2018 at 13:42, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 5 March, 2018 1:40 PM
To: Chia Sin Muk; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLD336T (Accident involving SLD336T and SH6525X on 28.02.2018)
Attachments: sh6525x_20180302133609.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLD336T and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

05032018 @ 1:50pm
Mr. Chia Veh in.
MG.

From: Chia Sin Muk [mailto:em1autopteltd@gmail.com]
Sent: 05 March, 2018 10:43 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLD336T (Accident involving SLD336T and SH6525X on 28.02.2018)

WITHOUT PREJUDICE

Dear All,

We request LKK Auto Consultant P/L to survey our client's vehicle.

Thanks & Best Regards,
Nicole, on behalf of,
Chia Sin Muk (Mr)
m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643
Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On 2 March 2018 at 13:42, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this

message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Vic (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Friday, 5 October, 2018 12:49 PM
To: Chia Sin Muk
Cc: Admin A; Vic (LKKAUTO)
Subject: FW: LOD - SLD 336T DOA 28.02.2018 - TP INDIA
Attachments: 336-05102018112020.pdf; 336-05102018111955.pdf

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

| LKK ref | Officer in charge |
|-----------------------|-------------------|
| CC4/III18004162/M1hb3 | Vic |

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Friday, 5 October 2018 11:25 AM
To: Admin A <admin-a@lkkauto.com>
Subject: LOD - SLD 336T DOA 28.02.2018 - TP INDIA

WITHOUT PREJUDICE

Dear Sir/Madam,

Please find the attached LOD.

COR \$ 13,482.00
GIA \$ 29.00
Tow \$ 60.00
LOR \$ 1,845.75
Total : \$ 15,416.75

Kindly arrange for settlement.

Thanks & Best Regards,
Nicole, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

Print Received Message

This mail is associated with :

***SLD336T (MCT18020940)**
[SH6525X]

TP

TAN SAY JOON

Feb 28 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Em-1 Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 17/07/2019 16:01 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SLD336T - Claim Handler: Priya

Maintained: Please try to negotiate Repair cost @ 11,700 lump sum and 11 working days repair.


Claim Audit

| AUDIT TRAIL | | | | | By |
|-------------|----------------------|-----------------------------------|---|--|----------------------------|
| No. | On | Audit | Remarks | | |
| 1 | 05 Mar 2018 14:59 | Clim Veh Model Changed | (201999) HONDA ACCORD 1.6 (M). | | [A] Hiew May Fung |
| 2 | 05 Mar 2018 14:59 | Clim Created | Reg No: SLD336T. Acct Date: 2018/02/28. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Em-1 Auto Pte Ltd (HQ) | | [A] Hiew May Fung |
| 3 | 05 Mar 2018 14:59 | Adj Co Assigned | LKK Auto Consultants Pte Ltd (HQ): | | [A] Hiew May Fung |
| 4 | 05 Mar 2018 14:59 | Adj Next Rpt Changed | Next Rpt:Final Rpt.Due Date:2018/03/14 | | [A] Hiew May Fung |
| 5 | 05 Mar 2018 14:59 | Adj Mandate Set | Approved:0.00.Reinsp:Adj decides. | | [A] Hiew May Fung |
| 6 | 05 Mar 2018 15:00 | Label Added | (30653):Direct Settlement. | | [A] Hiew May Fung |
| 7 | 05 Mar 2018 15:00 | Adj Adjuster Assigned | [None] -> KENNETH KONG | | [A] Hiew May Fung |
| 8 | 09 Mar 2018 09:19 | Clim Registration Modified | Init.Est.:8,000 - 9,000->20,000 - 25,000. | | [A] Hiew May Fung |
| 9 | 09 Mar 2018 09:19 | Clim Veh Model Changed | (201999) -> (201611) HONDA CIVIC 1.8 L (A). | | [A] Hiew May Fung |
| 10 | 09 Mar 2018 09:20 | Adj Adjuster Assigned | KENNETH KONG -> MA CHIN FOOK | | [A] Hiew May Fung |
| 11 | 09 Mar 2018 09:21 | Adj Rpt Initiated | | | [A] Hiew May Fung |
| 12 | 09 Mar 2018 09:21 | Clim Dtl Modified | Claimant's Name: -> -, Claimant's ID: -> -. | | [A] Hiew May Fung |
| 13 | 09 Mar 2018 09:21 | Clim Details Notified | | | [A] Hiew May Fung |
| 14 | 09 Mar 2018 09:25 | Clim Dtl Modified | Claimant's Name: - -> COMFORT TRANSPORTATION PTE LTD. Claimant's ID: - -> 199303821R. | | [A] Hiew May Fung |
| 15 | 10 Apr 2018 15:43 | Adj Mandate Request | Cur.Req:0.00:PODS LIABILITY: 100% REMARKS: BOLA 28 (3 veh.c.c; OID last car) | | [A] VIC ALPEH |
| 16 | 11 Apr 2018 09:09 | Adj Next Rpt Changed | Next Rpt:Final Rpt.Due Date:2018/03/14 | | [I] Priya |
| 17 | 11 Apr 2018 09:09 | Adj Mandate Set | Approved:0.00. | | [I] Priya |
| 18 | 04 Jul 2019 11:29 | Adj Mandate Request | Cur.Req:15416.75:PODS Liability: 100% Quantum: a)COR (w/gst): \$13,482.00 + b)LO R: \$1,845.75 (15 days x\$115.00+7%gst) + c) GIA: \$29.00 (\$15.00 + \$14.00) + d) Towing fee: \$60.00 = Total \$15,416.75 Vehicle Model: HONDA CIVIC- 1.8(A) (1799cc) For y o | | [A] Chong Poh Kin |
| 19 | 17 Jul 2019 16:01 | Adj Next Rpt Changed | Cur Rpt:Final Rpt. Cur Due Date:2018/03/14. Mandate Remarks: Please try to negotiate Repair cost @ 11,700 lump sum and 11 working days repair. | | [I] Priya |

AUDIT TRAIL

| No. | On | Audit | Remarks | By |
|-----|----------------------|---------------------|---|----------------------|
| 20 | 17 Jul 2019 16:01 | Adj Mandate Set | Maintained: Please try to negotiate Repair cost @ 11,700 lump sum and 11 working days repair. | [I] Priya |
| 21 | 02 Aug 2019 12:15 | Adj Mandate Request | Cur.Req: 13961.55: PODS Liability: 100% Quantum: a) COR (w/gst): \$12,519.00 + b) LO R: \$1,353.55 (11 days x \$115.00 + 7%gst) + c) GIA: \$29.00 (\$15.00 + \$14.00) + d) Towi ng fee: \$60.00 = Total \$13,961.55 Vehicle Model: HONDA CIVIC- 1.8(A) (1799cc) For yo ur app | [A] CHEW HSHIAO TONG |

Date From



Date To

Audit Type None

Go

ACTIVITY

[05/04/2019 09:00] VIC ALPEH:
PREPARING REPORT FOR MANDATE APPROVAL
[23/08/2018 09:33] VIC ALPEH:
PENDING TP LOD
[27/07/2018 10:30] VIC ALPEH:
PENDING COR FINALIZATION
[19/04/2018 15:26] VIC ALPEH:
Alert - Adj Mandate Approved (S\$0.00) - SLD336T - Claim Handler: Priya
Approved: 0.00.
[12/04/2018 14:15] Lau Shu Pei :
PENDING FINALIZE
[10/04/2018 15:42] VIC ALPEH:
FILE REVIEWED. OIC Mr Koh Kee Cheong reported that he was involved in a 3 veh.c.c. and was the last car and rear-ended TP. Seek liability mandate via merimen

Merimen Billing for this case - Transaction History

| Bill Ref No | Bill Date | Acc Type | Acc Name | Co Name (Branch) | Ref 1 | Ref 2 | Amount |
|-------------|---------------------|----------|------------------------------|-----------------------------------|---------|-------|--------|
| 1743682 | 09/03/2018 09:21 | Motor | LKK Auto Consultants Pte Ltd | LKK Auto Consultants Pte Ltd (HQ) | SLD336T | | 10.70 |

Print Received Message

This mail is associated with :

***SLD336T (MCT18020940)**
[SH6525X]
TP
TAN SAY JOON
Feb 28 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Em-1 Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/08/2019 16:06 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13961.55) - SLD336T - Claim Handler: Priya

Approved:13961.55.