

KIM CHWEE AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50, AUTOBAY,
SINGAPORE 417883

VEHICLE NO: SLR 4098E

not Authorized
date
2/5/18 9800
6 day.
5/3/18

QTY	PARTICULAR	AMOUNT
1PCS	REAR WINDSCREEN MOULDING	rec \$105.30
1PCS	TAILGATE 1456.10	m/bad \$1,880.00
1PCS	TAILGATE OUTER GARNISH	negd/cu \$982.20
1PCS	TAILGATE REAR LOGO	rec \$68.50
1PCS	TAILGATE 'TOYOTA' EMBLEM	rec \$60.20
1PCS	TAILGATE 'C-HR' EMBLEM	rec \$68.50
1PCS	TAILGATE 'HYBRID' EMBLEM	rec \$62.20
1PCS	TAILGATE INNER LOCK 295.10	4w/should \$449.60
1PCS	TAILGATE LOCK STRIKER	11 \$48.90 X
1PCS	TAILGATE INNER TRIM BOARD	11 \$614.55 X
1SET	TAILGATE INNER TRIM BOARD CLIPS	rec \$60.00
2PCS	TAILGATE REFLECTORS @ \$486.30	11 \$972.60 X
1PCS	TAILGATE WEATHERSTRIP 321.10	4w1 \$399.20
1PCS	REAR BUMPER 688.20	Dis \$1,655.90
1PCS	REAR BUMPER LOWER SKIRTING 450	Dis \$805.30
1PCS	REAR BUMPER TOW COVER	Torn \$45.00
2PCS	REAR BUMPER SIDE RETAINERS @ \$68.50	bad \$137.00
1SET	REAR BUMPER CLIPS	rec \$50.00
2PCS	REAR BUMPER REFLECTORS @ \$105.00	11 \$210.00 X
1PCS	REAR BUMPER REFLECTOR GARNISHS @ \$188.00	11 \$376.00 X
1PCS	REAR BUMPER REINFORCEMENT 318	Dis \$482.70
1PCS	REAR BUMPER LOWER CENTRE BRAKE LIGHT	rec \$385.00
1PCS	REAR END PANEL 820.11	3.0 dy. \$1,195.80
1PCS	REAR END PANEL TOP GARNISH	4w1 \$275.80
1PCS	REAR END PANEL LOCK SENSOR 245.60	cu \$320.00
1PCS	REAR FLOOR PANEL	11 \$1,480.00 X
1PCS	REAR FLOOR PANEL TOP BOARD	11 \$685.00 X
1PCS	REAR FLOOR PANEL TOOLS SPONGE	Torn \$622.30
1PCS	REAR FENDERS @ \$805.30	11 \$1,610.60 X
1PCS	REAR FENDER INNER TRIMS @ \$499.20	Dis/Torn \$998.40
1PCS	REAR FENDER OUTER PROTECTORS @ \$215.20	Torn \$430.40
1PCS	TAILLAMPS @ \$755.70	cu \$1,511.40
1PCS	TAILLAMPS HOUSING PANELS @ \$214.50	11 \$429.00 X
1PCS	REAR EXHAUST HEAT SHIELD 215.10	bad \$320.00
1PCS	REAR EXHAUST ASSY 1415.10	Dis/4w1 \$1,650.00
1PCS	REAR EXHAUST MOUNTINGS @ \$45.00	rec \$90.00

S.NETT

257

12176.61
9132.48

1SET	REAR BUMPER REVERSE SENSOR	Should	\$280.00	200
1PCS	REAR END PANEL SEALANT	✓	\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	✓	\$300.00	120
1PCS	REAR WINDSCREEN SEALANT	✓	\$50.00	40
1PCS	REAR WINDSCREEN INNER SEAL	✓	\$50.00	✓
1SET	REAR FENDER INNER TRIM CLIPS	✓	\$50.00	✓
	TO CHECK WIRING		\$80.00	30
	TO DISMENTLE & REPLACING REVERSE SENSOR		\$80.00	50
	TO DISMENTLE & REFIX REAR WINDSCREEN		\$150.00	120
	TO TRANSFER TAILGATE MECHANISM		\$100.00	80
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY		\$180.00	80
	TO DISMENTLE & REPLACING REAR EXHAUST		\$180.00	80
	TO SPRAY RUST PROOFING		\$180.00	80
	TO MOUNT VEHICLE ON CAR O-LINER	✓	\$380.00	✓
	TO CONDUCT WHEEL ALIGNMENT	✓	\$100.00	✓
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED		\$1,500.00	1000
	REPLACING PARTS			
	TO PUTTY & SPRAY PAINTING		\$1,500.00	1100
	TOTAL		\$26,747.35	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: