

Performance Motors Limited

A member of the Sime Darby Group
Co.Reg.No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : **b1 45933**
Date Estimated : **14/02/2018**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

REPAIR FOR -
Chong Heong Wee (Zhong Xiongwei)
Apt Blk 62 Lorong 4 Toa Payoh
#21-109

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Singapore 310062

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SGN9239M	CM75562	30/11/2006	523iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER LH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER RH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER LH FLAP COVER LEVER	11.65	1.00		11.65
# FRT BUMPER RH FLAP COVER LEVER	11.65	1.00		11.65

Total Labour :	
Total Parts :	59.60
Total Labour & Parts :	59.60