

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 09 Mar 2018

Preliminary Advice

Vehicle No	: XD1815D	Accident Date	: 02/03/2018
Make	: ISUZU CYZ52L	Policy No.	: MB022525
Assignment Date	: 06/03/2018	Excess	: S\$1,500.00
Date of Inspection	: 07/03/2018	Est. Duration of Repair	: 0.00
Inspection At	: LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT) 24 SUNGEI KADUT STREET 4 SINGAPORE 729050		

Point of Impact / General Description of Damages

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	18,488.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,512.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING INVESTIGATION