


Sketch Plan Pg. 2

SKETCH PLAN



A - GBA 7174G

B - SHD4115K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was on the 2nd lane of Tuas Ave 2 as I wanted to turn left into Pioneer Road, I was about 20meter away from the traffic junction. I also notice a road work so I signal my intention, just after the road work I check on my left and proceed to make my shift after the road construction while moving slowly into two lane this taxi SHD4115K which was behind my vehicle and speed on and squeeze inbetween the road core and upon seeing his reckless action which make me to step on my brakes.

DECLARATION

We declare the foregoing particulars are true in every respect.
KOH BROTHERS BUILDING & CIVIL
ENGINEERING CONTRACTOR (PTE) LTD
LOGISTICS DEPT.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3

WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
KOH BROS BUILDING & CIVIL ENGINEERING CONTRACTOR (PTE.) LTD.
Sector: CONSTRUCTION
Name: SEKAR KARTHIKEYAN
Occupation: CONSTRUCTION WORKER



Work Permit No. D 35363327
Date of Application: 05-11-2012
Date of Issue: 22-09-2016
Date of Expiry: 09-10-2018



L7226887

REPUBLIC OF SINGAPORE DRIVING LICENCE
G 6941986 R
SEKAR KARTHIKEYAN
Birth Date: 20 Jul 1989
Issue Date: 22 Jun 2015
Valid Till 21/06/2020
002442087J
SG 50

VISIT PASS Immigration Regulations

Name:
SEKAR KARTHIKEYAN



Date of Birth: 20-07-1989 Sex: M Nationality: INDIAN
FIN: G6941986R Date of Issue: 22-09-2016 Date of Expiry: 09-10-2018

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(E)

Class	Vehicle Description	EFFECTIVE DATE
Class 2B	Motorcycles <= 200 cc	22 Jun 2015
Class 3C	Motor Cars unladen weight <= 3000kg with <= 7 passengers, exclusive of the driver	22 Jun 2015

NP 428A



Accident Photo



Accident Photo

