

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)Sending Sunny & repair
26/3/2018 morning

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

06 MAR 2018

Estimate No. : b1 46130
Date Estimated : 06/03/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Lee Kong Meng
Blk 627 Senja Road
#27-174
Singapore
Singapore 670627**- ACCOUNT - 40000**Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJX9819B	VN76310	28/07/2010	X1 sDrive18i	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

1275 1,700.00

Spray painting rear bumper

934 1,038.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

? 531.00

To replace tyre and wheel rim including balancing. (1x). right rear

80 94.00

Sundries.

40 150.00

Total Labour 1: 3,513.00

DESCRIPTION

ALLOY RIM 71/2Jx17 VSPOKE 318

HUB CAP WITH CHROME EDGE (BMW)

RR BUMPER CTR GUIDE

RR BUMPER LOWER COVERING

RR BUMPER RH GUIDE

RR BUMPER (PRIMED)

RR BUMPER BOTTOM (XLINE/PDC)

RR RH WHEEL ARCH COVER

EXPANDING RIVET

EXPANDING RIVET

RR BUMPER RH REFLECTOR

QTY	PRIC	VALUE
1	778.55	778.55
1	24.30	24.30
1	61.35	61.35
1	31.45	31.45
1	56.95	56.95
1	831.40	831.40
1	322.35	322.35
1	146.10	146.10
10	1.35	13.50
2	1.35	2.70
1	35.20	35.20

Total Parts : 2,303.85

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 46130	Page No. : 2 of 2
Date Estimated	: 06/03/2018	
Prepared By	: Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJX9819B	VN76310	28/07/2010	X1 sDrive18i	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

before paint photos.

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>26/3/18</u>	Excess S\$ _____
Surveyor's Name <u>Gue Qi-p</u>	Sign _____
Surveyor's Tel <u>82880282</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3</u>	

Labour 1	:	3,513.00
Parts	:	2,303.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	407.18
Grand Total	:	<u>6,224.03</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **