## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd 8 Shenton Way #24-01

AXA Tower Singapore 068811 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Cynthia Loh Date: 08 Mar 2018

# **Preliminary Advice**

Insured Vehicle No : SHD9512P

TP Vehicle No : SHC6106D Accident Date : 05/03/2018

Make : KIA OPTIMA 1.7(A) DIESEL Assignment Date : 06/03/2018

Date of Inspection : 06/03/2018 Est. Duration of Repair : 3 days

Inspection At : Premier Automotive Services Pte Ltd (HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ....O/S body.... portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 3,527.50 |
|-----------------------------|------|----------|
| Revised Amount              | :S\$ | 1,454.40 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 1,454.40 |

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

### Remarks

| ( | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|---|---|
| ( | ) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.   |

(X) Other comments: We have not authorized repairs.