

INSURANCE

INS. CASE OWNER:

Joane

CC 4 / LCR18004404 / TWS3

LKK

IDAC:

Surveyor:

TAUFIKH

DOI:

08/03/18

Date / Time:

06/03/18

Registered in Merimen:

07/03/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 2232R

Claim No.:

959630610859

Name of Insured:

LCR

Policy No.:

Insured Tel No.:

HP:

Make / Model:

MITSUBISHI ATTRAGE -1.2 (UT (A)

Excess Sec II :SS

D.O.A:

26/02/18

Place of Accident:

TJONG BAHU ROAD TURNING OUTRA ROAD

Is driver the owner?

(YES ☒ NO)

Nature of Accident:

If NO, Driver Name / Age: MOHAMMAD REWMAN BEN RAZALI

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Driver Tel No.:

(V/L ☒ YES / NO)

Insured Liability:

% Final ? Yes / No

FBI 27741C



INSRS:

WSP: Southern motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

FBI 27741C - N50 / INC 180038011 2018-06/03/18
SLE 2232R - X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LT / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with LIPV

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 25, Ass. Lia

Repair Cost:

Inc 544

SS

388.50

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

40.00

(5.20 x 2 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

628.50

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

628.50

Name 1:

Southern motor

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
28/03/18

RECEIVED 28 MAR 2018

ASSIGNMENT

From: Date 08092018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBJ 2774K

at Workshop m/s Southern Motor

of Bldg 1006 Bukit merah lane 2

Insured #01-10

Policy No.

Claims No.

Sum Insured Excess:

(Client's Record)

Make of Veh:

(Policy Condition) morning

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: FBJ2774K Yr Regn: 2014 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Jupiter cc 134.

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 58487 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH 350C004DK 682874

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: (NI) / S/Rim / STD A/Rim or

Tyre Size: F: 70/90 R17 R: 90/80 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Racingsone

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 4/3/80 / pm

Survey held at Southern motor

Des. of Damages: Ent / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/3/18 confirm CS \$550.00 with 3 working days.

(Red. \$249.20 31%)

Date/Time: File Pass to: ☐ : Preli. Report ☐ : Final Report

Date/Time: File Return to:

21

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. S - RS 1

2. Photos

3. Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/LCR18004404/T1ws3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 07-03-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLE 2232R	Veh. Inspected	FBJ 2774K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/02/2018	Inspection Date	08/03/2018
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel: 62730369 Fax: 62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 6th March 2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 078120

Dear Sirs

Re: Cost of repair to Yamaha Jupiter MX155-7852774K

1 pc of Front mudguard
1 pc of Centre fairing
1 pc of Lower cowling
" Brake pedal
" Footrest
" Footrest rubber
" Brake lever
" Mirror
" Handle bar
" Handle bar cover

S\$ 4500 cut ✓
1500 cut ✓
2500 cut ✓
4500 cut ✓
6500 cut ✓
1500 cut ✓
1500 cut ✓
5500 cut ✓
6500 cut ✓
2500 cut ✓
13500
13500
48400 ✓

Less 10%

Nett

Transport
Alignment fork
Alignment spoke rim
No plate
Labour

4000 30
6500 ✓
4500 30
1500 X 11
15000 100
S\$ 74920

S\$ 709.20

50%

S\$ 567.36

Less Sum =
S\$ 550

Truful 97495749

WP

8/3/18 @ 1250

2 days

hmpson

Fax: 64153727

Tel: 64192000

Recovery after repair

By email: www.aig.com.sg

SVC@interim.co.uk 64153727

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Friday, 9 March, 2018 3:15 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto)
Subject: ACCIDENT INVOLVING SLE 2232R & FBJ 2774K ON 26/02/2018

Our Ref: CC4/LCR18004404/ws3

09 March 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLE 2232R & FBJ 2774K ON 26/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, MOHAMMAD AZIM BIN ABDUL AZIZ ("the third party claimant")
of Blk 469 Ang Mo Kio Ave 10 #07-884 Singapore 560469 (address),
owner of FBJ 2774K (vehicle no.) hereby authorize
Southern Motor

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. FBJ 2774K that was
damaged pursuant to the accident which occurred on 26-01-2018 (date) along
Butram Rd towards Kim Seng Rd (location)
involving vehicle no/s GLE 2232R ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 28th day of January (month) 2018 (year)


Signed by "the third party claimant"



SOUTHERN MOTOR
Blk 1006, Bukit Merah Lane 2
#01-10 Singapore 159762
Tel: 62730369 Fax: 62746614
Signed by the Workshop

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, SOUTHERN MOTOR ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 588.50 (repair costs), S\$ 40.00 (loss of use/rental) S\$ - (search fees) for vehicle no. 7BJ2774K that was damaged pursuant to the accident which occurred on 26-02-2018 (date) along Outram Rd towards Kim Seng Rd (location) involving vehicle no/s 522 232 R.

This is pursuant to the inspection conducted on 08-03-2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Khalid bin Zin Abdul Aziz ("third party claimant") of vehicle no. 7BJ2774K to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to 7BJ2774K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 2nd day of March (month) 20 18 (year)

MTH

Signed by AIG appointed surveyor



SOUTHERN MOTOR
8B-1008, Bala Muthu Lane 2P
#01-10 Singapore 159762
Tel: 62730368 Fax: 62746614

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2018 Edit Reg		06 Mar 2018 00:00 Edit Adj Rpt	S\$550.00 Edit Estimates	S\$550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LION CITY RENTALS PTE LTD , Co. Reg. No.: 201504621K		
Main Claimant:	MOHAMMAD AZIM BIN ABDUL AZIZ , ID: S8127306E		
Vehicle Reg. No.:	FBJ2774K	Date of Loss:	26/02/2018 15:00 - :59
Claim Type:	TP / 9596306108SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLE2232R	Policy No. (Claimant):	5085081648-01
		Excess:	
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ2774K (9596306108SG)
[SLE2232R]
TP
MOHAMMAD AZIM BIN ABDUL AZIZ
Feb 26 2018 3:00PM
[LION CITY RENTALS PTE LTD]
Southern Motor

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
Letters/Correspondences					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit		
Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	08/03/18 14:52	Accident Statement <small>From: SC - Reg. No: SLE2232R, Claimant: LION CITY RENTALS PTE LTD</small>	1	Load HTM		
Documentation					1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	07/03/18 16:05	EMAIL FROM WORKSHOP DD 06.03.2018	1	Load PDF		
2	07/03/18 16:05	ACKNOWLEDGEMENT EMAIL TO AIG DD 06.03.2018	1	Load PDF		
3	07/03/18 16:05	TP ESTIMATE + NOTIFICATION FROM WORKSHOP + TP GIA REPORT	1	Load PDF		
4	09/03/18 15:16	Email letter to OI ACCIDENT INVOLVING SLE 2232R & FBJ 2774K ON 26.02.2018	1	Load PDF		
5	14/03/18 12:13	TP ESTIMATE- MARKED	1	Load PDF		
6	29/03/18 09:26	WORKSHOP INVOICE	1	Load PDF		
7	29/03/18 09:26	AUTHORISATION TO ACT FORM	1	Load PDF		
8	29/03/18 09:26	Release Voucher	1	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid #ccc; padding: 5px; margin-bottom: 10px;"> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 40px; margin-top: 5px;"></div> </div> <div> Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> </div>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE2232R (Insd veh)	Model:	YAMAHA JUPITER MX
	FBJ2774K (TP veh)		134CC HC
Date of Accident:	26/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		855.14
Final Repair Cost	:	\$		588.50
Loss of Use	:	\$		40.00
				2.00 days at \$20.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		0.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		628.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Southern Motor	:	\$ 628.50
2)		:	\$

JOANNE LEE KHANG MIN

29 Mar
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18004404/T1WS3Q2

Date: 29/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBJ2774K

Insured Vehicle No : SLE2232R

Date of Loss: 26/02/2018

Nature of Claim: TP

Claim No: 9596306108SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ2774K

Make & Model: YAMAHA JUPITER MX, 134cc HC

Engine No: 50C683033

Reg. Date: 11/03/2014 (Man. Year: 2013)

Chassis No: MH350C004DK682874

Colour: Red

Odometer: 58487 km

Engine Capacity: 134 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Rear Tyre Size: 90/80 R17

Front Left Side: Racingstone 5 mm

Rear Left Side: Racingstone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	499.20	484.20	15.00	3.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	300.00	225.00	75.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	799.20	709.20	90.00	11.26
Approved Total (Overridden) (S\$)		550.00		
(S\$)	799.20	550.00	249.20	31.18
+ GST 7.00/7.00% (S\$)	55.94	38.50	17.44	31.18
Nett Amount (S\$)	855.14	588.50	266.64	31.18
+ Loss of Use (2.0 x S\$20.00/day) (S\$)		40.00		
Nett Liability (S\$)		628.50		

INSPECTION

Date of Assignment: 06/03/2018

Date Inspected: 08/03/2018 Inspected At:

Southern Motor (HQ)

BLK 1006 BUKIT MERAH LANE 2, #01-10

Singapore 159762

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Cut	45.00 FL	*45.00 FL
2	1		*CENTRE FAIRING	Cracked	150.00 FL	*150.00 FL
3	1		*LOWER COWLING	Cut	55.00 FL	*55.00 FL
4	1		*BRAKE PEDAL	Dented	45.00 FL	*45.00 FL
5	1		*FOOTREST	Bent	65.00 FL	*65.00 FL
6	1		*FOOTREST RUBBER	Torn	15.00 FL	*15.00 FL
7	1		*BRAKE LEVER	Cut	18.00 FL	*18.00 FL
8	1		*MIRROR	Cut	55.00 FL	*55.00 FL
9	1		*HANDLE BAR	Bent	65.00 FL	*65.00 FL
10	1		*HANDLE BALANCER	Cut	25.00 FL	*25.00 FL
11	1		*NO PLATE	Not Necessary	15.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 553.00 538.00

- List Item Discount on L Items 10.00/10.00% (S\$) 53.80 53.80

Total Parts (S\$) 499.20 484.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	40.00	30.00
2	ALIGNMENT FORK	New	65.00	65.00
3	ALIGNMENT SPOKE RIM	New	45.00	30.00
4	LABOUR	New	150.00	100.00
Gross Labour Cost (S\$)			300.00	225.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >