



南方摩哆
SOUTHERN MOTOR

Block 1006, Bukit Merah Lane 2, #01-10
Singapore 159762 Tel:62730369 Fax:62746614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 6th March 2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Dear Sirs

Re: Cost of repair to Yamaha Jupiter MX155-78J2774K

1 pc of Front mudguard
1 pc of Centre fairing
1 pc of Lower cowling
~ Brake pedal
~ Footrest
~ Footrest rubber
~ Brake lever
~ Mirror
~ Handle bar
~ Handle balancer

S\$ 4500 cat -
150.00 one -
5500 cat -
4500 cat -
6500 cat -
1500 cat -
1500 cat -
5500 cat -
6500 ?
2500 int -
53800
53800
48420

Less 10%

Nett

Transport
Alignment fork
Alignment spoke rim
No plate
Labour

4000 30
6500 ✓
4500 30
1500 X
1500 100
S\$ 79920

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Taufik 97495749

WP

8/3/18 @ 1250

2 days

hmp sm

Repair after repair

sw@lkkauto.com Fax 64153727

Fax: 64153727

Tel 64192000

By email: www.aig.com.sg