

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cynthia Loh

Date: 20 Mar 2018

## **Preliminary Advice**

Insured Vehicle No : SHB7583H  
TP Vehicle No : SLK2566X  
Make : TOYOTA PRIUS HYBRID  
Date of Inspection : 07/03/2018  
Inspection At : Esteem Performance Pte Ltd (HQ)  
385 Sin Ming Drive  
Singapore 575718

Accident Date : 02/03/2018  
Assignment Date : 06/03/2018  
Est. Duration of Repair : 14 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....rear & front.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,021.16
Revised Amount	:S\$	18,422.90
Check Items (Estimated)	:S\$	9,252.80
Total	:S\$	27,675.70

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.