



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 28/8/2018

Survey Details:

Date of loss	5-Mar-18
Date of appointment	7-Mar-18
Date of survey	9-Mar-18
Location of survey	PERFORMANCE MOTORS LIMITED

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKF 1089B
Make and Model	BMW 116I 1598cc
Date of registration	Apr-12
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 5,763.20
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$0
Labour	\$ 3,302.00
Total	\$ 3,302.00
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>5 days</u>
----------------------------------	----------------------



Remarks:

We had spoken to the Insured Mr Chng Johnny and he was informed on the TP claim and liability. A letter was sent out to the Insured to notify of the TP claim and NCD issue. No feedback from Insured till date. BOLA NIL - OI reversed and hit TP. TP LOD IN.

Mandate:

Liability(TP)	100%	
Proposed Repair Cost	\$ 3,533.14	w/gst
Loss of Use	\$ 300.00	\$60 X 5 days
Loss of Rental	\$ -	No. of days
Loss of Income	\$ -	No. of days
GIA/LTA search fees	\$ 2.00	
Others	\$ -	
Proposed Total	\$ 3,835.14	