

REF:

CC3/ALH 18004427 /Arb

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 2100482803-01

Claims No. 4684657689 56

Sum Insured:

Excess:

8600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

133K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 M/s days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF9674 Y

Yr Regn:

2016 Sept.

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 Sedan

C.C.

1395

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp. Reading

25547

T/Radio: Insured / Std / NI / NA

Eng/No:

WAUZZZF49HA 026093

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

07/03/18

Survey held at:

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

SLF 9674Y - X

Confirm \$3941.84, 4 days
Red: \$3150.16, 44%

RECEIVED 04 MAY 2018

Date/Time, File Pass to?



: Prel. Report

1) Typist

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

) \$+R5 \$

) Photos

) Others

Add Fee:



Site Insp

\$



Interview

\$



Tech. Invs

\$



Weekend

\$

Report Format:

OD

Lump Sum / I.B.I. (\$

3941.84

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 406933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199507198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18004427/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 07-03-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLF 9674Y
Policy No. 2100482803	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	07/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 16/02/2018	Inspection Date 07/03/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

5a. Remarks

A)THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/02/2018 13:29
Date Of Accident	16/02/2018 17:15
Exact Location Of Accident	B638, ANG MO KIO AVE 6 CARPARK (S560638)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF9674Y
Insured/Policyholder	
Name Of Registered Owner	LIM TEOW SENG
NRIC No	S1204769Z
Email Address	CLEMENT.LIM@HS.UTC.COM
Mobile Phone No	(LOCAL) +65-90303017
Alternative Phone No	HOME-66364855

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100482803-01
Cover Note Number	

Driver

Name of Driver	LIM TEOW SENG
NRIC No	S1204769Z
Date Of Birth	29/12/1955
Occupation	INDOOR
Date Of Driving Pass	21/07/1976
Driving Experience	41 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90303017
Fax Number	
Contact Number	HOME-66364855
EMail Address	CLEMENT.LIM@HS.UTC.COM

Address	BLK 71 PASIR RIS GROVE #14-20
Postcode	518205
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (including Driver)	3
Passenger 1	NAME: : PECK SIEW TEE GENDER: : FEMALE
Passenger 2	NAME: : LIM QIAN YU GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

TRYING TO PARK INTO LOT AT ANG MO KIO AVE 6 CARPARK WHEN VEHICLE SKP7635H, WHO WAS TRAVELLING BEHIND TRIED TO OVERTAKE ME ON THE RIGHT HAND SIDE AGAINST THE OPPOSITE DIRECTION OF DRIVE PATH SCRATCH AGAINST MY FRONT RHS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKP7635H
Vehicle Make/Model/Colour	VOLVO / WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HENRY RAMAS
NRIC/Passport Number	S7973494B
Contact Number	

Address

BLK 710 HOUGANG AVE 2
#04-133

Postcode

530710

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ii. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:


19-2-2018
11:40am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: 
NRIC/IN No: G3B4904P

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Trying to park into lot @ Amy's Mobile Auto Co carport when vehicle SKP4035H
while back travelling behind tried to overtake me on the right hand side against
the opposite direction of drive path scratch against my front R/Hs.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

17/4/2018

12.03.14

Driver's Signature _____

Driver's Signature _____
(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Yvonne S.

NRIC/FIN No: 02249002

Accident Photo



REPUBLIC OF SINGAPORE **DRIVING LICENCE**

License Number: **S1204769Z**

Name: **LIM TEOW SENG**

Birth Date: **29 Dec 1955**
Issue Date: **10 May 2003**

000471860A




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1204769Z

Name: **LIM TEOW SENG**

林朝盛

Race: **CHINESE**
Date of birth: **29-12-1955**
Country of birth: **SINGAPORE**

Sex: **M**

S1204769Z




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES):

Class	Description	PASS DATE
Class 2	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	21 Jul 2016

NP 428A

Licence No: **S1204769Z**



4800859

S1204769Z

NRIC No: **S1204769Z**

Date of Issue: **10-12-2011**

BLK 71 PASIR RIS GROVE #14-20
SINGAPORE 518205

NRIC No: **S1204769Z** Date: **10/12/2011** No: **6963203**






CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM TEOW SENG
Period of Insurance : 16 Sep 2017 To 15 Sep 2018
Engine No. : CVN017882
Chassis No. : WAUZZZF49HA026093

Vehicle No. : SLF9674Y
Policy No. : 2100482803-01
Endorsement No. :
Issued Date : 16 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIM TEOW SENG - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Centre Add: 55 Ubi Road 1 Singapore #38699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0504125259

PREMIUM LEASING -PSHS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

53047

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0209/2018/CCS
Date	:	1-Mar-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Teow Seng
Address	:	71 Pasir Ris Grove #14-20 Singapore 518205
Telephone	:	HP +65 90303017
Type of Claim	:	Own Damage Claims
Policy No.	:	2100482803-01000
Vehicle No	:	SLF 9674 Y
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	Sep-16
Engine No	:	CVN 017882
Chassis No	:	WAUZZZF49HA026093
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Feb-18
Place of Accident	:	B638, ANG MO KIO AVE 6 CARPARK (S560638)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 9674 Y.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00 ✓	360
2	To dismantle and renew front bumper and rhs front fender. Re-organise front crash management components. Reinstall all parts removed.	\$	1,500.00	1000 1000
3	To respray front bumper and rhs front fender.	\$	1,500.00	1100 1100
4	To renew rhs front rim with tyre, carry out wheel alignment.	S/N \$	280.00 ✓	280
5	To carry out diagnostic checks.	S/N \$	192.00 ✓	192
TOTAL LABOUR CHARGES		:	<u>\$ 3,832.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 9674 Y.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	FRONT FENDER - RH <i>Deated</i>	S	665.00	✓ 532.00
2	FRONT FENDER ATTACHMENT PARTS <i>Not in</i>	S	45.00	✗
3	FRONT FENDER CLOSING ELEMENT - RH <i>Not in</i>	S	44.00	✗
4	FRONT FENDER BRACE - RH <i>Not New</i>	S	103.00	?
5	FRONT BUMPER GUIDE - RH <i>Not in</i>	S	32.00	✗
6	FRONT FENDER RIVET SET <i>Not in</i>	S	35.00	✓ 27.84
7	FRONT WHEEL HOUSING LINER - RH <i>Not in</i>	S	209.00	✗
8	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not in</i>	S	78.00	✗
9	FRONT BUMPER <i>Repair</i>	S	1,849.00	✗
10	ALUMINIUM RIM - RH FRONT <i>Not</i>		PRICE TBA	✓ 450
11	TYRE - RH FRONT <i>Not in</i>		PRICE TBA	✗
12	SUNDRIES <i>Not New</i>	S	200.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 3,260.00	
TOTAL LABOUR CHARGES			\$ 3,832.00	
GRAND TOTAL			\$ 7,092.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 07/03/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 04 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0209/2018/CCS
Date : 01-Mar-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - JB - 19 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Teow Seng
Address : 71 Pasir Ris Grove
#14-20
Singapore 518205
Telephone : HP +65 90303017
Type of Claim : Own Damage Claims
Policy No. : 2100482803-01000
Vehicle No : **SLF 9674 Y**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Sep-16
Engine No : CVN 017882
Chassis No : WAUZZZF49HA026093
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Feb-18
Place of Accident : B638, ANG MO KIO AVE 6 CARPARK (S560638)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 9674 Y.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper and rhs front fender. Re-organise front crash management components. Reinstall all parts removed.		\$ 1,500.00	\$ 1,000.00
3	To respray front bumper and rhs front fender.		\$ 1,500.00	\$ 1,100.00
4	To renew rhs front rim with tyre, carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
5	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 3,832.00</u>	<u>\$ 2,932.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLF 9674 Y.**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT FENDER - RH	\$ 665.00	\$ 532.00
2	FRONT FENDER ATTACHMENT PARTS	\$ 45.00	
3	FRONT FENDER CLOSING ELEMENT - RH	\$ 44.00	
4	FRONT FENDER BRACE - RH	\$ 103.00	
5	FRONT BUMPER GUIDE - RH	\$ 32.00	
6	FRONT FENDER RIVET SET	\$ 35.00	\$ 27.84
7	FRONT WHEEL HOUSING LINER - RH	\$ 209.00	
8	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 78.00	
9	FRONT BUMPER	\$ 1,849.00	
10	ALUMINIUM RIM - RH FRONT	\$ 562.50	\$ 450.00
11	TYRE - RH FRONT	PRICE TBA	
12	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES :		\$ 3,822.50	\$ 1,009.84
TOTAL LABOUR CHARGES		\$ 3,832.00	\$ 2,932.00
GRAND TOTAL		\$ 7,654.50	\$ 3,941.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, April 19, 2018 7:29 PM
To: Adrian Ling (LKKAUTO); Veron Chen (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION SLF9674Y - OD AIG - SURVEYED 7 MAR 18
Attachments: PA02092018 - SLF 9674 Y - A4 SEDAN 1.4 TFSI - RH FRONT (Direct Asia).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3941.84 @ 4 days of repairs.

Your early closure is well appreciated.

best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLF 9674 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0209/2018/MAS

3 May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLF 9674 Y, Audi A4 Sedan 1.4 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLF 9674 Y**, claimant, **Mr. Lim Teow Seng**, please find the related document per attached.

1. A copy of the Original invoice no. 85012409 – S\$3,575.77
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLF 9674 Y

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S1204769Z**

Name: **LIM TEOW SENG**

Birth Date: **29 Dec 1955**
Issue Date: **10 May 2003**

1000471860A




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1204769Z**

Name: **LIM TEOW SENG**

林 朝 盛

Race: **CHINESE**
Date of birth: **29-12-1955**
Country of birth: **SINGAPORE**

Sex: **M**

S1204769Z




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	21 Jul 1976

NP 428A

Licence No: **S1204769Z**



4800850

S1204769Z

NRIC No: **S1204769Z**

Date of Issue: **10-12-2011**

BLK 71 PASIR RIS GROVE #14-20
SINGAPORE 518205

NRIC No: **S1204769Z** Date: **10/12/2011** No: **6963203**






Name of Policyholder : LIM TEOW SENG
Period of Insurance : 16 Sep 2017 To 15 Sep 2018
Engine No. : CVN017882
Chassis No. : WAUZZZF49HA026093

Vehicle No. : SLF9674Y
Policy No. : 2100482803-01
Endorsement No. :
Issued Date : 16 Aug 2017

Make/Model	AUDI A4 1.4 TFSI S tronic			
Engine Capacity/Tonnage	1,395.00 CC	Sum Insured	Market Value	First Year of Registration
Driver Restriction	NA	Off Peak Car	No	Insuring with COE/PARF
				Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$1,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

This Policy is intended for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 2 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 99 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreens : \$100

Named Driver and Excess (where applicable)

LIM TEOW SENG - \$800 (Own Damage)

1. Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408699 63662727

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

0504125259

PREMIUM LEASING -PSHS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

550/2489



Premium Automobiles Pte Ltd

Audi Centre Singapore
251 Alexandra Road
Singapore 119938
Main Telephone: 6856 2223
Main Telefax: 6471 3733

Alexandra Service Centre
251 Alexandra Road
Singapore 119938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408671
Telephone: 6388 2223
Telefax: 6475 1023

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6388 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 15:41

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012409 Date : 30/04/2018 Order : SLF9674Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF9674Y (V 31217)	Regn Date: 16/09/2016	Mileage: 26301	WIP No.: 56140
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF49H0026093	Engine: CVN 017882	Dept: U
VS8 No.:			
You have been assisted by :- UB-Carrine (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
D	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO DISMANTLE AND RENEW RHS FRONT FENDER, REPAIR FRONT BUMPER, RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNME	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
X	ABW0601025B	RIM 16" C4M Less 020%	1.00	562.50	450.00
X	ABW0821106A	FENDER Less 020%	1.00	665.00	532.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6838 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6838 2223
Telefax: 6475 1022

Ubi Service Centre
55 Ubi Road 1
Singapore 408780
Telephone: 6308 2323

Customer Service
Service Appointment
Motor Breakdown Service
Email: customer.care@premiumauto.com.sg
6886 2323
6828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 15:41

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012409 Date : 30/04/2018 Order : SLF9674Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF9674Y (V 31217) Regn Date: 16/09/2016 Mileage: 26301 WIP No.: 56140

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF49HA026093 Engine: CVN 017882 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
X	AN 0161857	POP-RIVET Less 020%	12.00	2.98	27.84

Parts 1,009.84
Labour 0.00
Sublet 2,932.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,341.84

7% GST 233.93

Grand Total 3,575.77



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLF 9674 Y

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0209/2018/JT
24 March 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI S-tronic
Vehicle Chassis No. : WAUZZZF49HA026093
Vehicle Regn No. : SLF 9674 Y
Vehicle Mileage : 26301 KM
Vehicle Owner : Mr. Lim Teow Seng
Certificate No : 2100482803-01000
Policy Excess : S\$ 642.00 (inclusive 7% GST)
Accident Date : 16th February 2018
Place : B638, Ang Mo Kio Ave 6
Repair Cost : \$ 3,575.77
WIP No. : 56140
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



24/03/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Feb 2018		07 Mar 2018 17:25 Edit Adj Rpt	S\$3,941.84 Edit Estimates	S\$3,941.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by Insurer]

Insured:	LIM TEOW SENG, ID: S1204769Z, Tel: +6590303017, Email: CLEMENT.LIM@HS.UTC.COM		
Vehicle Reg. No.:	SLF9674Y	Date of Loss:	16/02/2018 17:00 - :59 [17 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 4684657689SG	Policy/Cover Note No.:	2100482803-01 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 16/03/2018]		
Driver/Custodian:	LIM TEOW SENG (62 / Male), NRIC: S1204769Z, Tel: +6590303017		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (08/03/2018): SLF9674Y / OD / 16/02/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF9674Y (4684657689SG)
OD
Feb 16 2018 5:15PM
[LIM TEOW SENG]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	20/04/18 12:49	General View													Load JPG	☒				
2	20/04/18 12:49	General View													Load JPG	☒				
3	20/04/18 12:49	General View													Load JPG	☒				
4	20/04/18 12:49	General View													Load JPG	☒				
5	20/04/18 12:49	General View													Load JPG	☒				
6	20/04/18 12:49	General View													Load JPG	☒				
7	20/04/18 12:49	General View													Load JPG	☒				
8	20/04/18 12:49	General View													Load JPG	☒				
9	20/04/18 12:49	General View													Load JPG	☒				
10	20/04/18 12:49	General View													Load JPG	☒				
11	20/04/18 12:49	General View													Load JPG	☒				
12	20/04/18 12:49	General View													Load JPG	☒				
Documentation															1 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	07/05/18 09:05	WORKSHOP INVOICE													Load PDF					
2	07/05/18 09:05	DISCHARGE VOUCHER													Load PDF					

Linked Accident Report Documents

View View in Browser

Assessment Reports					1 per page	☐
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print	
1	19/02/18 16:20	Accident Statement		Load HTM		
2	01/03/18 08:42	Addendum Sheet		Load JPG	☒	
3	01/03/18 08:43	Accident Statement Addm. #1		Load HTM		

Photos/Images

3 per page ☐

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/02/18 16:01	Accident Photo		Load JPG	☒
2	19/02/18 16:01	Accident Photo		Load JPG	☒
3	19/02/18 16:01	Accident Photo		Load JPG	☒
4	19/02/18 16:01	Accident Photo		Load JPG	☒
5	19/02/18 16:01	Accident Photo		Load JPG	☒
6	19/02/18 16:01	Accident Photo		Load JPG	☒
7	19/02/18 16:01	Accident Photo		Load JPG	☒
8	19/02/18 16:01	Accident Photo		Load JPG	☒
9	19/02/18 16:01	Accident Photo		Load JPG	☒
10	19/02/18 16:01	Accident Photo		Load JPG	☒
11	19/02/18 16:01	Accident Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
12	19/02/18 16:01	Accident Photo	 Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	19/02/18 15:53	Sketch Plan	 Load JPG	☒
2	19/02/18 15:53	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18004427/ARBQ2

Date: 07/05/2018

REFERENCE

Insured/Claimant: LIM TEOW SENG Policy No: 2100482803-01
Date of Loss: 16/02/2018 Nature of Claim: OD Claim No: 4684657689SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF9674Y**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN017882
Reg. Date: 16/09/2016 (Man. Year: 2016) Chassis No: WAUZZZF49HA026093
Colour: Blue Odometer: 25547 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$133,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,710.00	1,009.84	2,700.16	72.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,832.00	2,932.00	900.00	23.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,542.00	3,941.84	3,600.16	47.73
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,942.00	3,341.84	3,600.16	51.86
+ GST 7.00/7.00% (S\$)	485.94	233.93	252.01	51.86
Nett Amount (S\$)	7,427.94	3,575.77	3,852.17	51.86

INSPECTION

Date of Assignment: 07/03/2018
Date Inspected: 07/03/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Dented	665.00 FS	*532.00 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	45.00 FS	*- FS
3	1		*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	44.00 FS	*- FS
4	1		*FRONT FENDER BRACE-RH	Not Necessary	103.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE-RH	Not Necessary	32.00 FS	*- FS
6	1		*SET FRONT FENDER RIVET	Necessary	35.00 FS	*27.84 FS
7	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	209.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	78.00 FS	*- FS
9	1		*FRONT BUMPER	Repair	1,849.00 FS	*- FS
10	1		*ALUMINIUM RIM -RH FRONT	Cut	450.00 FS	*450.00 FS
11	1		*TYRE -RH FRONT (NPA)	Not Necessary	0.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,710.00	1,009.84
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,500.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO RENEW RHS FRONT RIM WITH TYRE ,CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			3,832.00	2,932.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >