



1094 Lower Delta Road Motorway Building Singapore 169205
Main +65.6468 2200 | Fax +65.6273 5535

EQ INSURANCE COMPANY LTD
MOTOR CLAIMS DEPARTMENT
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

ESTIMATES

VEHICLE NO. : SLS4301M
CHASSIS NO : KPT30B1USHP182499
MAKE & MODEL : SSANGYONG TIVOLI
DATE OF ACCIDENT : 18/02/2018 @ 11:50HRS

PARTS DISCRPTION	QTY	LIST PRICE	TOTAL LIST
REAR BUMPER	1		\$ 585.40
REAR BUMPER CLIPS	10	\$ 5.00	\$ 50.00
REAR BUMPER REVERT	10	\$ 3.00	\$ 30.00
REAR BUMPER NUMBER PLATE WITH HOLDER	1		\$ 30 55.00
REAR BUMPER TOW HOOK COVER	1		\$ 12.80
REAR BUMPER THIRD BRAKE LAMP	1		\$ 186.70
REAR BUMPER LOWER SPOILER LH & RH	2	\$ 87.20	\$ 174.40
REAR BUMPER REFLECTOR LH & RH	2	\$ 19.80	\$ 39.60
REAR BUMPER REINFORCEMENT	1		\$ 385.70
TOTAL			\$ 1,519.60
LESS 10%			\$ (151.96)
TOTAL PARTS			\$ 1,367.64

del
del
del
CRP
Ryo
?
del
LH-X, RH-OM
?

LABOUR CHARGES

TO REPAIR & REMOVE & REPLACE ALL DAMAGE PARTS DUE TO ACCIDENT \$ 600.00 ⁴⁵⁰
TO SPRAY PAINT ON THE AFFECTED AREAS DUE TO ACCIDENT \$ 700.00 ³⁵⁰
TOTAL LABOUR \$ 1,300.00

TOTAL	\$ 2,667.64
--------------	--------------------

Kit Ngai
Motorway Car Care Centre Pte Ltd
TEL : 6571 9639
FAX : 6278 5535
EMAIL : kknagai@motorway.com.sg
WEBSITE : www.motorway.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
-wp'
8/3/18 @ 1545
Lampson
Resurvey after repair
sur@lkkauto.com
3 days