



ComfortDeiGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP

Ins Company : AIG / AXA

Excess : \_\_\_\_\_

Date of Accident : 23.02.2018

Suggested Days of Repair : \_\_\_\_\_

Vehicle No. : SKE8837T

Make & Model : TOYOTA WISH 1.8 CVT

Year of Manufacture : 2012

Chassis No. : JTDGG20W605002705

Engine No. : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Time of Accident : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimates**

Parts (a) Cost / List Price Items	<u>\$5,262.40</u>
Plus/Less 25%	<u>\$1,315.60</u>
Total of Cost / List	<u>\$3,946.80</u>
(b) Nett Price Items	<u>\$-</u>
Less	_____
Total of Nett Item	_____
(c) Special Nett Items	<u>\$450.00</u>
<b>Total Parts Cost (Appendix A)</b>	<u><b>\$4,396.80</b></u>
<b>Labour (Appendix B)</b>	<u><b>\$1,950.00</b></u>
<b>Total Repair Cost</b>	<u><b>\$6,346.80</b></u>

Case Owner : ROHANI

Signature : \_\_\_\_\_

Contact No

**63837466 – Patrick**  
[patricktia@sparkcarcare.com](mailto:patricktia@sparkcarcare.com)

**63837890 – Eric**  
[ericppg@sparkcarcare.com](mailto:ericppg@sparkcarcare.com)

**63837362 – EZEL**

**63837730 – Brenda Ng**

**63838115 – WILLIAM**

**63837656 - Ngo**  
[ngotw@cdge.com.sg](mailto:ngotw@cdge.com.sg)

The above total will be subjected to 7% G.S.T.

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax:62815767

## Spare Parts

Vehicle No : SKE8837T Case Owner : ROHANI

Make & Model : TOYOTA WISH 1.8 CVT Year Manufacture : 2012

Chassis No : JTDGG20W605002705 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	REAR TAILGATE	1		\$1,278.45		
2	REAR TAILGATE WINDSCREEN GLASS MOULDING	1		\$174.40		
3	SEALANT	1				\$40.00
4	INNER SEAL	1				\$30.00
5	TAILGATE LOCK	1		\$374.25		
6	REAR LOGO	1		\$124.05		
7	REAR DULUXE BLADGE	1		\$121.55		
8	REAR VALVE MATIC BLADGE	1		\$134.45		
9	TAILGATE OUTER CHROME MOULDING	1		\$385.10		
10	TAILGATE WEATHER STRIP	1		\$377.10		
11	TAILGATE LH REVERSE LAMP	1		\$369.10		
12	REAR BUMPER	1		\$481.90		
13	REAR BUMPER SIDE RETAINER RH	1		\$132.10		
14	REAR BUMPER SIDE RETAINER LH	1		\$132.10		
15	REAR BUMPER REFLECTOR LH	1		\$141.45		
16	REAR BUMPER REINFORCEMENT	1		TBA		
17	REAR BUMPER CLIP	6		\$77.40		
18	REVERSE SENSOR	1				\$380.00
19	TAILLAMP LOWER BRACKET LH	1		\$141.45		
20	TAILLAMP LOWER BRACKET RH	1		\$141.45		
21	REAR END PANEL	1		\$581.90		
22	REAR BUMPER NUT COVER RH	1		\$47.10		
23	REAR BUMPER NUT COVER LH	1		\$47.10		
24	0	1				
25	0	1				
26	0	1				
27	0	1				
28	0	0				
29	0	0				
30		0				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

