

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4816G

MAKE :

MODEL : HYUNDAI SONATA

A1G

DATE 6/3/2018 14:44

DOA: 06.03.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) X 1/2		\$ 38.00	\$ 76.00
	SUB TOTAL			\$ 1,482.90
	LESS 20%			\$ 296.58
	DISCOUNTED TOTAL			\$ 1,186.32
	Rear Bumper Reverse Sensor X			\$ 135.70
				\$ 135.70
	Labour Charge			20%
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 720.00
	ESTIMATE TOTAL			\$ 2,042.02

Nett

1/2

X

X

Larry Ng

Kahin 11/1/18

7/3/18 1620hrs

2 P-1

4/3

After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are "Without Prejudice"
- No iller: ... is allowed
- Supplier's price must be resurveyed and is subject to ... from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.