



Your Ref: 18.24306 V

Date: 31st October 2018

Our Ref: CS1/LAW18004521/T1tbs2

M/s Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

GBF 6161Z

INSURED VEHICLE: YN 2203Z

ACCIDENT DATE: 12/10/2017

We thank you for your instruction on 19/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBF 6161Z from M/s FormTeam Consultancy Pte Ltd.
- b) Singapore Accident Statement of Vehicles GBF 6161Z and YN 2203Z.
- c) Colour damaged vehicle photographs of GBF 6161Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBF 6161Z
Make & Model	: Toyota Hiace DX 3.0
Year of Registration	: 2017
Chassis Number	: KDH2015021736
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 20 (Twenty) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.