

(Jkt)

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Lee Chen Sin  
CLAIM DEPARTMENT  
DID : 66547520  
FAX :

Date : 08/03/2018  
To : EQ INSURANCE COMPANY LIMITED

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd  
: SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D17MTRENT000070 Accident Date : 04/01/2018  
Vehicle No : SLH-1690-S Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|-------------|-------------------|---------------|
|-----|-------------|-------------------|---------------|

#### List Item

|    |                                 |        |       |
|----|---------------------------------|--------|-------|
| 1  | FRONT FENDER RH                 | 750.00 | PA    |
| 1  | FRONT FENDER INNER SHIELD RH    | 235.00 | X     |
| 10 | FRONT FENDER INNER SHIELD CLIPS | 30.00  | see - |
| 1  | FRONT FENDER EMBLEM RH          | 45.00  | see - |
| 1  | HEADLAMP RH                     | 750.00 | X     |
| 1  | FRONT BUMPER                    | 458.00 | ?     |
| 10 | FRONT BUMPER CLIPS              | 30.00  | see - |
| 1  | FRONT BUMPER SIDE RETAINER RH   | 55.00  | X     |

Date : 08/03/2018  
To : EQ INSURANCE COMPANY LIMITED

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd  
: SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D17MTRENT000070 Accident Date : 04/01/2018  
Vehicle No : SLH-1690-S Make & Model : TOYOTA COROLLA ALTIS 1.6 STANDARD (A)

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

| QTY | DESCRIPTION                                  | REPAIRER AMT (\$) | SURVEYOR APP. |
|-----|----------------------------------------------|-------------------|---------------|
|     | Sub Total                                    | 2353.00           |               |
|     | Discount 25% On Parts                        | (588.25)          |               |
|     | <u>Labour &amp; Misc</u>                     |                   |               |
|     | LABOUR TO FACILIATE REPAIR                   | 300.00            | 200           |
|     | TO CHECK AND RECONNECT ALL NECESSARY WIRINGS | 35.00             | X             |
|     | TO SPRAY PAINT ON AFFECTED AREAS             | 500.00            | 400           |
|     | Sub Total                                    | 835.00            |               |

2,599.75

Remarks:

3 days - Lumpsum

Surveyor's name:

Rasul - Hp 90010068

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

09/04/18 @ 1535

Resurvey after repair

SUB TOTAL

GST 7.0%

TOTAL

181.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE : 2