

INS. CASE OWNER:

Sherini

CC 4/III1800 4623

RI Mb3072

LKK:

IDAC:

Surveyor:

Rasul

DOI:

17/2/18

Date / Time:

12/2/18

Registered in Merimen:

12/2/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 18327

Name of Insured : LTPU

Insured Tel No. : HP:

Excess Sec II : S\$ D.O.A : 06/02/18

Is driver the owner? (YES / ☒ NO) Nature of Accident :

If NO, Driver Name / Age : Mb HAF UMANA

Driver Tel No. : (VL: ☒ YES / NO)

Claim No. : MJ1512V76

Policy No. : MLOM0015

Make / Model : HYUNDAI

Place of Accident : Bukit Timah KO

OI GIA REPORT ☒ YES / NO : TP GIA REPORT ☒ YES / NO

Insured Liability : % Final ? Yes / No

SFT 9994



INSRS:

WSP:

Tel:

Liability:

RMKS:

STUTTAMT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

12/2/18

Beran

13/3/18

11/3/18

seek mandate from III for liability
liability mandate reported by III

Renting LUP

16/11/18

File passed to Reports Team (STUTAMT)

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: 47

Repair Cost: PIR S\$ 7,026.41

(4 days) Reduction:

41 %

Email ☒ Call ☐

FINAL SETTLEMENT Date/Time: 01.12.18

Confirm with: STUTAMT

Email ☒ Call ☐

Final Liability: % (100) (Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost: S\$ 7,026.41

Loss of Rental (LOR): S\$ -

(15 days) x 4 days

Loss of Use (LOU): S\$ 600.00

(15 days) x 4 days

Loss of Income (LOI): S\$ -

(15 days) x 4 days

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GIA/LTA Search S\$ -

Medical: S\$ -

Disbursement: S\$ -

(e.g. Tow/ Independent)

Legal Cost: S\$ -

Total: S\$ 8,226.41

Global Sum S\$:

FINAL PAYMENT Date/Time: 07.12.18

Confirm with: STUTAMT

Email ☒ Call ☐

Payee 1: S\$ 8,226.41

Name 1: STUTAMT Auto PE Co

Payee 2: (Strike if N.A.) S\$ -

Name 2:

Payee 3: (Strike if N.A.) S\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +800

COPY SENT
14/11/18OIO Vayli: VOW tomorrow
with TD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18004623/mb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 12-03-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1832Z	Veh. Inspected	SFT 999S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/03/2018	Inspection Date		
Survey held at	STUTTGART AUTO PTE LTD 12 SUNGEI KADUT AVE. SINGAPORE 729648			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3531D
Vehicle Details	
Vehicle No.:	SFT999S
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Nov 2018
Vehicle Make:	PORSCHE
Vehicle Model:	911 GT3 (3.8)
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	61A24396
Chassis No.:	WP0ZZZ99ZAS780653
Maximum Power Output:	320.0 kW (429 bhp)
Open Market Value:	\$192,045.00
Original Registration Date:	23 Nov 2009
First Registration Date:	23 Nov 2009
Transfer Count:	0
Actual ARF Paid:	\$192,045.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Nov 2019
PARF Rebate Amount:	\$105,624.00
Intended COE Rebate Details	
COE Expiry Date:	22 Nov 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$20,200.00
COE Rebate Amount:	\$2,013.00
Total Rebate Amount:	\$107,637.00

The information contained herein is correct as at 16 Nov 2018

OK

SFT 9995

DOA 06/03/2018

DOR 11/2009

IA calculation: 16/11/2018 (Olivia)

		Revised	Cross	Check
1	4,042.50	4,042.50		
2	901.90		901.90	
3	1,572.90		1,572.90	
4	22.60		22.60	
5	157.00		157.00	
6	21.00		21.00	
7	16.80		16.80	
8	18.60		18.60	
9	8.00	8.00		
10	2.20	2.20		
11	206.10		206.10	
12	91.40	45.70		
13	1,021.60		1,021.60	
14	45.90		45.90	
15	30.00		30.00	
16	15.00		15.00	
17	83.70	83.7		SUPPL
18	2.8	2.8		SUPPL
	8,260.00	4,184.90	4,029.40	0.00
10%	7,434.00	3,766.41		
	6,170.00	3,360.00	780.00	
	13,604.00	7,126.41		
	RED	6,477.59		
	RED%	47.61%		

		Revised	Cross	Check
1	3,120.00	1,560.00		
2	1,500.00	1,200.00		
3	780.00		780.00	
4	600.00	480		
5	70.00	70.00		
6	100.00	50.00		
	6,170.00	3,360.00	780.00	

TP DOA	06/03/2018	TUE	1150
TP Veh in			
TP write Ill	08/03/2018	THU	1116
INDIA assign	09/03/2018	FRI	1412
LKK Merimen	12/03/2018	MON	
OI GIA in	12/03/2018	MON	1231
Liab Clear	14/03/2018	WED	0822
DOI	13/03/2018	TUE	
TP Veh out			

LKK recc 3+1 DAYS
 TP asking
 Finalised \$7,126.41 23/05/2018 / RASUL

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
FINALIZATION COST OF REPAIRS

INDIA INT'L INSURANCE PTE LTD 64 CECIL STREET #04-06 IOB BUILDING SINGAPORE 049711		NAME : Mr Howard Ronald Delaney ADDRESS : 21 Anguilla Park #20-02 TwentyOne Anguilla Park Singapore 239974		WIP : 32299 DATE: 08.03.2018	
ATTN :	MOTOR CLAIMS DEPT	TEL :			
FAX :	62244174				
VEH NO :	SFT999S	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP0ZZZ99ZAS780653	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SHC1832Z
MODEL :	911 GT3	DATE REG :	23/11/2009	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	REVISED	(NETT) PRICES
1	LINING	1	P997-505-411-9A-	\$ 4,042.50	\$ 4,042.50
2	HEAT PROTECTION	1	P997-505-475-91-	\$ -	\$ 901.90
3	BUMPER REINFORCEMENT	1	P997-505-121-92-	\$ -	\$ 1,572.90
4	BOLT-HEX HEAD (M12 X 100)	2	P900-378-088-01-	\$ -	\$ 22.60
5	IMPACT PIPE BUMPER	2	P996-505-019-01-	\$ -	\$ 157.00
6	R/BUMPER TUBE SEAL	2	P996-505-775-00-	\$ -	\$ 21.00
7	P900-378-267-01-/SCREW	4	P900-378-351-01-	\$ -	\$ 16.80
8	PROTECTIVE FILM	2	P997-504-631-00-	\$ -	\$ 18.60
9	RIVET	4	P999-591-941-40-	\$ 8.00	\$ 8.00
10	BLIND RIVET	2	P999-190-104-30-	\$ 2.20	\$ 2.20
11	HEAT PROTECTION	1	P997-505-811-91-	\$ -	\$ 206.10
12	NUMBER PLATE LIGHT	1	P997-631-620-02-	\$ 45.70	\$ 91.40
13	TAIL PIPE	1	P997-111-253-90-	\$ -	\$ 1,021.60
14	HEXAGON NUT	3	P999-084-649-01-	\$ -	\$ 45.90
15	WASHER	2	P997-111-753-91-	\$ -	\$ 30.00
16	WASHER TAIL PIPE	1	P997-111-755-91-	\$ -	\$ 15.00
SUPPLEMENTARY					
1	WIRING HARMLESS	1	P997-612-660-01	\$ 83.70	cut
2	FIXING CLIP	1	999-507-944-40	\$ 2.80	new
SUB TOTAL				\$ 4,184.90	\$ 8,173.50
LESS 10%				\$ 418.49	\$ 817.35
Total Parts				\$ 3,766.41	\$ 7,356.15

Labour Description

1	TO REMOVE / REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.	\$ 1,560.00	\$ 3,120.00
2	TO SPRAY PAINT REAR BUMPER.	\$ 1,200.00	\$ 1,500.00
3	TO REMOVE / REPLACE TAIL PIPE INCLUDE RE-ALIGNMENT OF EXHAUST SYSTEM & CHECK FOR LEAKAGE. NETT	\$ -	\$ 780.00
4	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR. NETT	\$ 480.00	\$ 600.00

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

INDIA INTL INSURANCE PTE LTD 64 CECIL STREET #04-06 IOB BUILDING SINGAPORE 049711		NAME : Mr Howard Ronald Delaney ADDRESS : 21 Anguilla Park #20-02 TwentyOne Anguilla Park Singapore 239974		WIP : 32299 DATE: 08.03.2018	
ATTN :	MOTOR CLAIMS DEPT	TEL :			
FAX :	62244174				
VEH NO :	SFT999S	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP0ZZZ99ZAS780653	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SHC1832Z
MODEL :	911 GT3	DATE REG :	23-11-09	POLICY NO :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	PRICES	(NETT)
1	LINING	1	P997-505-411-9A-	\$ 4,042.50	
2	HEAT PROTECTION	1	P997-505-475-91-	\$ 901.90	
3	BUMPER REINFORCEMENT	1	P997-505-121-92-	\$ 1,572.90	
4	BOLT-HEX HEAD (M12 X 100)	2	P900-378-088-01-	\$ 22.60	
5	IMPACT PIPE BUMPER	2	P996-505-019-01-	\$ 157.00	
6	R/BUMPER TUBE SEAL	2	P996-505-775-00-	\$ 21.00	
7	P900-378-267-01-/SCREW	4	P900-378-351-01-	\$ 16.80	
8	PROTECTIVE FILM	2	P997-504-631-00-	\$ 18.60	
9	RIVET	4	P999-591-941-40-	\$ 8.00	
10	BLIND RIVET	2	P999-190-104-30-	\$ 2.20	
11	HEAT PROTECTION	1	P997-505-811-91-	\$ 206.10	
12	NUMBER PLATE LIGHT	2/1x	P997-631-620-02- us ?	\$ 91.40	
13	TAIL PIPE	1	P997-111-253-90-	\$ 1,021.60	
14	HEXAGON NUT	3	P999-084-649-01-	\$ 45.90	
15	WASHER	2	P997-111-753-91-	\$ 30.00	
16	WASHER TAIL PIPE	1	P997-111-755-91-	\$ 15.00	
SUB TOTAL				\$ 8,173.50	
LESS 10%				\$ 817.35	
Total Parts				\$ 7,356.15	

Labour Description

1	TO REMOVE / REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	1560	\$ 3,120.00
2	TO SPRAY PAINT REAR BUMPER.	1200	\$ 1,500.00
3	TO REMOVE / REPLACE TAIL PIPE INCLUDE RE-ALIGNMENT OF EXHAUST SYSTEM & CHECK FOR LEAKAGE	X	\$ 780.00
4	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	480	\$ 600.00
5	TO SUPPLY 1 PC NO PLATE \$70.00 EA	Crn	\$ 70.00

6	SUNDRIES.	Net	50	\$ 100.00
		TOTAL LABOUR		\$ 6,170.00
		TOTAL PARTS		\$ 7,356.15
		GRAND TOTAL		\$ 13,526.15

Please note that this is **only an estimate** base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentais will be adjusted accordingly.

Prepared By

Acknowledge By

13604 .

RASUL
 Hp 90010068
 +1 = 4 days / print
 3 days
 13/03/18 @ 1620
 Resurvey by paint
 14/3/18

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged pan(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Bevan Lim (LKK Auto)

From: jessicahs@eurokars.com.sg
Sent: Monday, 21 May 2018 4:08 PM
To: Rasul (LKKAuto); SUR; Admin A; CS A Team
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg
Subject: RE: FINALIZATION III TP - SFT999S.xls
Attachments: III TP - SFT999S.xls

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Rasul,

Please find our computation attached for your agreement.

COR: \$7,126.41 before GST

4 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	12 Mar 2018 14:47	Cim Veh Model Changed	(200715) PORSCHE 911 GT3.		[A] Lau Shu Pei
2	12 Mar 2018 14:47	Cim Created	Reg No: SFT999S, Acct Date: 2018/03/06, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: AXA Insurance Pte Ltd (HQ), Workshop: Stuttgart Auto Pte Ltd (HQ)		[A] Lau Shu Pei
3	12 Mar 2018 14:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Lau Shu Pei
4	12 Mar 2018 14:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/21		[A] Lau Shu Pei
5	12 Mar 2018 14:47	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.		[A] Lau Shu Pei
6	12 Mar 2018 14:47	Label Added	(30651):Vehicle Not In,(30653):Direct Settlement.		[A] Lau Shu Pei
7	12 Mar 2018 14:47	Adj Adjuster Assigned	[None] -> MOHD RASUL		[A] Lau Shu Pei
8	13 Mar 2018 08:46	Cim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD, Claimant's ID: -> 1993038 21R.		[A] Lau Shu Pei
9	13 Mar 2018 09:16	Adj Mandate Request	Cur.Reg:0.00:PODS LIABILITY : 100 % REMARKS : BOLA 27 OLD REAR ENDED TP		[A] Lim Chin Siong Bevan
10	13 Mar 2018 09:20	Adj Mandate Request Cancelled			[A] Lim Chin Siong Bevan
11	13 Mar 2018 09:21	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/21		[I] Sherini Pillai
12	13 Mar 2018 09:21	Adj Mandate Set	Approved:0.00,		[I] Sherini Pillai
13	13 Mar 2018 09:24	Adj Mandate Request	Cur.Reg:0.00:PODS LIABILITY : 100% REMARKS BOLA (NIL) OLD NOT IN VEHICLE , VEHICLE ROW FORWARD AND COLLIDED WITH TP VEHICLE		[A] Lim Chin Siong Bevan
14	13 Mar 2018 09:29	Adj Mandate Set	Approved:0.00,		[I] Sherini Pillai
15	16 Mar 2018 14:05	Label Removed	(30651):Vehicle Not In.		[A] Lau Shu Pei
16	16 Mar 2018 14:06	Adj Rpt Initiated			[A] Lau Shu Pei
17	16 Mar 2018 14:06	Cim Details Notified			[A] Lau Shu Pei
18	28 Nov 2018 10:09	Adj Mandate Request	Cur.Reg:8345.26:PODS: LIABILITY: 100% QUANTUM: (a) COR w/GST : \$7,625.26 + (b) LOU: \$720.00 (4days x \$180) Total: a+b = \$8,345.26 VEH MODEL: PORSCHE 911 GT3 3797cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.		[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Print Received Message

This mail is associated with :

***SFT999S (MCT18030176)**
[SHC1832Z]

TP

DELANEY HOWARD RONALD
Mar 6 2018 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Stuttgart Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/11/2018 11:18 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8225.26) - SFT999S - Claim Handler: Sherini Pillai

Approved:8225.26:Try to offer \$150 per day for loss of use at \$600



PORSCHE

DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned Repairers my/our vehicle No: 3FT 9998 which has been repaired to my satisfaction and I/we admit that the payment for such repairs by **Stuttgart Auto Pte Ltd** is in full and final discharge of my claim under policy number: _____ in respect of damage caused to the said vehicle as a result of an accident that occurred on 06/03/2018 at Caltex Dunearn Car Wash - 130 Dunearn Road.

Janice Syn



Witnessed by Repairers

13/04/2018

Date:

Alfred

Signature by Insured

13/04/2018

Date:



PORSCHE

INDIA INT'L INSURANCE PTE LTD

64 Cecil Street
#04-05 IOB Building
Singapore 049711

Attn : Motor Claims Department

DATE : 28/05/2018

Your Ref : **SHC1832Z**

Car Regn No: **SFT999S**

Accident involving SFT999S & SHC1832Z on 06/03/2018

Direct Settlement Claim

Dear Sirs

The repairs have been completed for **SFT999S**. We submit the following documents for your perusal :

1) Invoice No: 13204410	\$ 7,625.26
2) Loss of Use (\$180.00 x 4 days)	\$ 720.00
3) PRI (2 days x \$180.00)	\$ 360.00
4) Letter of Authority	
5) Discharge voucher signed by client	
TOTAL	\$ 8,705.26

Please pay **Stuttgart Auto Pte Ltd** the sum of **\$8,705.26** as soon as possible and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648**.

Yours faithfully,

Stanley Ngu
Manager - Body & Paint Division
DID: 63602845 FAX: 63602899
e-mail: stanley@eurokars.com.sg

Porsche Centre Singapore

 Stuttgart Auto Pte Ltd
Eurokars Group
Company Reg. No. 198403740N

Corporate Headquarters
12 Sungei Kadut Avenue
Singapore 729648
Tel: (65) 6363 0911
Fax: (65) 6363 3911

City Centre
29 Leng Kee Road
Singapore 159099
Tel: (65) 6472 4433
Fax: (65) 6474 3101

www.porsche.com.sg

DeLaney Howard Ronald (Owner's Name)
21 Angellia Park (Address)
#12-03 80399TH

India International Insurance Pte Ltd (Ins Co)
64 Cecil Street (Address)
#04-05 10B Building
80499TH

Attn : Motor Claims Dept

Your ref : SHC 18322
Our ref : SFT 9998

Date :

Dear Sirs,

RE : Accident involving vehicle nos. SFT 9998 and SHC 18322 on 06/05/2018.

I refer to the above accident.

My car has been repaired by Stuttgart Auto Pte Ltd. As they are submitting a 3rd Party claim against India International Insurance Pte Ltd on my behalf, please pay to **Stuttgart Auto Pte Ltd** for the whole claim due to them.

Yours faithfully,


()

I/C No : 826635310

Cc. Stuttgart Auto Pte Ltd
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III-Direct Settlement (PODS)

India Ref: MCT18030176
Claimant Ref: SFT 9995

We/I, STUTTGART AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 7,825.26 (repair cost), S\$ 800.00 (loss of use/rental), S\$ — (search fee), vehicle no. SFT 9995 that was damaged pursuant to the accident which occurred on 06/03/2018 (date) at CALTEX DUNEARN CAR WASH-130 DUNEARN RD (location) involving vehicle no. SHC 1832Z (insured vehicle). This is pursuant to the inspection conducted on 13/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner DELANEY HOWARD RONALD ("the third party claimant") of vehicle no. SFT 9995 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SFT 9995 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 8,225.26 to STUTTGART AUTO PTE LTD

Dated this 07 day of 12 20 18

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:


Signed by "the workshop" (workshop)
Janice Sgn

876434461

27A Tanjong Pagar
8 (609045)

Singapore

Service Advisor

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



MRB
Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933



PORSCHE

INSURANCE INVOICE

GST Reg No: S50364000A

CODE: 10003 INDIA IN
 CUSTOMER: INDIA INT'L INSURANCE PTE LTD
 ADDRESS: 64 CECIL STREET #04-05
 10B BUILDING
 SINGAPORE 049111

PAGE NO: 1
 DOCUMENT NO: 13204410
 JOB NO: 32299
 DATE IN: 09/04/2018
 DATE PRINTED: 24/05/2018
 CSO/OP CODE: Janice Syn
 SVC MNT BAP: 22/11/2014

MODEL: 911 GT3
 CHASSIS NO: WFO222992AS/000033
 ENGINE NO: 61A24396
 DESCRIPTION: 3rd Party Claim

REGN NO: SPT9995
 REGN DATE: 23/11/2009
 MILEAGE: 94998

Item	Description	Unit	U/Price	Disc%	Cost	Amount
EXPENSE	3RD PARTY CLAIM AGAINST III				0.00	0.00
SUB	TO REMOVE / REPLACE REAR DAMAGED					0.00
	BUMPER & OTHER ASSOCIATED BODY PARTS					1360.00
	INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS					
	& FITTINGS WHICHEVER NECESSARY INCLUDING					
	ALIGNMENT OF BODY STRUCTURE.					
SUB	TO SPRAY PAINT REAR BUMPER.		0.00			1200.00
SUB	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODE		0.00			480.00
	AFTER ACCIDENT REPAIR.					
SUB	TO SUPPLY 1 PC NO PLATE \$10.00 EA		0.00			70.00
SUB	SUNDRIES.		0.00			30.00
991-000-411-9A-	LINING	1	4042.50	10.00		3638.25
991-012-000-01-	WIRING HARNESS	1	83.70	10.00		75.33
991-031-040-02-	NUMBER PLATE LIGHT	1	45.70	10.00		41.13
993-190-104-30-	BLIND RIVET	2	1.10	10.00		1.98
993-301-344-40-	FIXING CLIP	3	2.80	10.00		2.52
993-391-341-40-	RIVET	4	2.00	10.00		7.20

Parts 3,766.41
 Sundries 0.00
 Labour 3,390.00
 Menus 0.00

Tel 7126.41
 G.S.T. 1% 498.85
 Total 1625.26
 Paid 0.00
 Amount Due 1625.26

If major repaired parts stated above are covered under a 24 months warranty. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling. Replaced parts that are removed from cars are to be collected within 5 working days failing which TUTTGART AUTO PTE LTD reserved the rights to dispose of these parts without further notice. Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Authorised Signature

STUTTGART AUTO PTE LTD

ORIGINAL COPY

Porsche Centre Singapore

Stuttgart Auto Pte Ltd

10:11:35 Eurokars Group
 Company Reg. No. 198403740N

Corporate Headquarters
 12 Sungei Kadut Avenue Tel : (65) 6363 0911
 Singapore 729648 Fax: (65) 6363 3911

City Centre
 29 Leng Kee Road
 Singapore 159099 Tel : (65) 6472 4433
 Fax: (65) 6474 3101

www.porsche.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018 Edit Reg		12 Mar 2018 00:00 Edit Adj Rpt	S\$7,126.41 Edit Estimates	S\$7,126.41 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	DELANEY HOWARD RONALD, ID: S2663531D		
Vehicle Reg. No.:	SFT999S	Date of Loss:	06/03/2018 11:00 - :59 [99 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18030176	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHC1832Z	Policy No. (Claimant):	VPX/P1722873
		Excess:	
Repairer:	Stuttgart Auto Pte Ltd - Sungai Kadut (HQ) 12 SUNGEI KADUT AVE, 729648 Sungai Kadut - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (29/11/2018): Alert - Adj Mandate Approved (S\$8225.26) - SFT999S - Claim Handler: Sherini Pillai...
- III_SG (13/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SFT999S - Claim Handler: Sherini Pillai
- III_SG (13/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SFT999S - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFT999S (MCT18030176)
[SHC1832Z]
TP
DELANEY HOWARD RONALD
Mar 6 2018 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Stuttgart Auto Pte Ltd - Sungei Kadut

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	16/11/18 14:59	General View						Load JPG	☒	
2	16/11/18 14:59	General View						Load JPG	☒	
3	16/11/18 14:59	General View						Load JPG	☒	
4	16/11/18 14:59	General View						Load JPG	☒	
5	16/11/18 14:59	General View						Load JPG	☒	
6	16/11/18 14:59	General View						Load JPG	☒	
7	16/11/18 14:59	General View						Load JPG	☒	
8	16/11/18 14:59	General View						Load JPG	☒	
9	16/11/18 14:59	General View						Load JPG	☒	
10	16/11/18 14:59	General View						Load JPG	☒	
11	16/11/18 14:59	General View						Load JPG	☒	
12	16/11/18 14:59	General View						Load JPG	☒	
13	16/11/18 14:59	General View						Load JPG	☒	
14	16/11/18 14:59	General View						Load JPG	☒	
15	16/11/18 14:59	General View						Load JPG	☒	
16	16/11/18 14:59	General View						Load JPG	☒	
17	16/11/18 14:59	General View						Load JPG	☒	
18	16/11/18 14:59	General View						Load JPG	☒	
19	16/11/18 14:59	General View						Load JPG	☒	
20	16/11/18 14:59	General View						Load JPG	☒	
21	16/11/18 14:59	General View						Load JPG	☒	
22	16/11/18 14:59	General View						Load JPG	☒	
23	16/11/18 14:59	General View						Load JPG	☒	
24	16/11/18 14:59	General View						Load JPG	☒	
25	16/11/18 14:59	General View						Load JPG	☒	
26	16/11/18 14:59	General View						Load JPG	☒	
27	16/11/18 14:59	General View						Load JPG	☒	
28	16/11/18 14:59	General View						Load JPG	☒	
29	16/11/18 14:59	General View						Load JPG	☒	
30	16/11/18 14:59	General View						Load JPG	☒	
31	16/11/18 14:59	General View						Load JPG	☒	
32	16/11/18 14:59	General View						Load JPG	☒	
33	16/11/18 14:59	General View						Load JPG	☒	
34	16/11/18 14:59	General View						Load JPG	☒	
35	16/11/18 14:59	General View						Load JPG	☒	
Documentation							1 per page		☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/03/18 14:47	TP EST & GIA REPORT	 Load PDF	
2	12/03/18 14:47	EMAIL FROM III DD 09032018	 Load PDF	
3	16/03/18 17:45	TP ESTIMATE- MARKED	 Load PDF	
4	21/12/18 10:46	WORKSHOP INVOICE	 Load PDF	
5	21/12/18 10:46	AUTHORISATION TO ACT FORM	 Load PDF	
6	21/12/18 10:46	DISCHARGE VOUCHER	 Load PDF	
7	21/12/18 10:46	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/03/18 15:31	Singapore Accident Statement-IV	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18004623/R1EB3Q2

Date: 21/12/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SFT999S

Insured Vehicle No : SHC1832Z

Date of Loss: 06/03/2018

Nature of Claim: TP

Claim No: MCT18030176

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFT999S

Make & Model: PORSCHE 911, GT3

Reg. Date: 23/11/2009 (Man. Year: 2009)

Colour: White

Engine Capacity: 3797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 61A24396

Chassis No: WP0ZZZ99ZAS780653

Odometer: 94833 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35ZR19

Rear Tyre Size:

235/35ZR19

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,604.00	3,886.41	3,717.59	48.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	3,240.00	2,760.00	46.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,604.00	7,126.41	6,477.59	47.62
+ GST 7.00/7.00% (S\$)	952.28	498.85	453.43	47.62
Nett Amount (S\$)	14,556.28	7,625.26	6,931.02	47.62
+ Loss of Use (4.0 x S\$150.00/day) (S\$)		600.00		
Nett Liability (S\$)		8,225.26		

INSPECTION

Date of Assignment: 12/03/2018

Date Inspected: 13/03/2018

Inspected At:

Stuttgart Auto Pte Ltd (HQ)

12 Sungei Kadut Ave

Singapore 729648

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)
Parts: M1-COUPE	PORSCHE 911 GT3 (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFT999S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LINING	Cracked	4,042.50 FL	*4,042.50 FL
2	1		*HEAT PROTECTION	Serviceable	901.90 FL	*- FL
3	1		*BUMPER REINFORCEMENT	Serviceable	1,572.90 FL	*- FL
4	2		*BOLT-HEX HEAD (M12X100)	Serviceable	22.60 FL	*- FL
5	2		*IMPACT PIPE BUMPER	Serviceable	157.00 FL	*- FL
6	2		*R/BUMPER TUBE SEAL	Serviceable	21.00 FL	*- FL
7	4		*P900-378-267-01-/SCREW	Serviceable	16.80 FL	*- FL
8	2		*PROTECTIVE FILM	Serviceable	18.60 FL	*- FL
9	4		*RIVET	Necessary	8.00 FL	*8.00 FL
10	2		*BLIND RIVET	Necessary	2.20 FL	*2.20 FL
11	1		*HEAT PROTECTION	Serviceable	206.10 FL	*- FL
12	1		*NUMBER PLATE LIGHT (2 Pcs)	Cracked (1 Pc only)	91.40 FL	*45.70 FL
13	1		*TAIL PIPE	Not Necessary	1,021.60 FL	*- FL
14	3		*HEXAGON NUT	Not Necessary	45.90 FL	*- FL
15	2		*WASHER	Not Necessary	30.00 FL	*- FL
16	1		*WASHER TAIL PIPE	Not Necessary	15.00 FL	*- FL
17	1		*NO PLATE	Cracked	70.00 FS	*70.00 FS
18	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
19	1		*WIRING HARMLESS	Cut	83.70 FL	*83.70 FL
20	1		*FIXING CLIP	Necessary	2.80 FL	*2.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	8,430.00	4,304.90
- List Item Discount on L Items 10.00/10.00% (\$\$)	826.00	418.49
Total Parts (\$\$)	7,604.00	3,886.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE/REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT/STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	New	3,120.00	1,560.00
2	TO SPRAY PAINT REAR BUMPER	New	1,500.00	1,200.00
3	TO REMOVE/REPLACE TAIL PIPE INCLUDE RE-ALIGNMENT	New	780.00	-
4	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	New	600.00	480.00
Gross Labour Cost (\$\$)			6,000.00	3,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >