

Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721 Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg Website : www.ltm.sg

Co.Reg No.: 199307277D GST Reg No.: M2-0119086-0

Survey By.

TP INSURER:

India International Insurance Pte Ltd (HQ)

COMFORT TRANSPORTATION PTE LTD

Date / Time 12.03.2018

11-35am

Singapore

PARTICULARS OF CLAIM

Claim Type:

Policy No:

THIRD PARTY

Ref. No:

LTP032018/025 (SJB

5500 8800

329 Z)

FQ:FSVD

Vehicle Reg. No.:

SJB329Z

Date of Loss:

09/03/2018

Porty At Foult:

THIRD PARTY

Driveable?

Party At Fault: THIRD F

THINDITALL

Driver (Insured):

BENJAMIN LIM CHI

ENG

Make/Model:

Driver (TP):

NISSAN TEANA, 2.5 CVT ABS D/AB HID

JEYA BALAN S/O N KANAGASABAI

.....

14/06/2012

.

2WD 4DR (A)

Vehicle Reg. Date:

14/06/2012

Vehicle Colour:

RED

Engine No:

VQ25539543A

Chassis No:

JN1BBUJ32Z0002900

Odometer:

109479 KM

Paint Type:

Nett Item Discount:

10.00 %

Total Loss?

NO

Est. Duration of

Repair (day)

8 6day,

Nor Northerster USing 87 Reservey After Paring

Description of Accident/Loss TOWARDS MAXWELL ROAD. UPON REACHING A CONTROLLED TRAFFIC JUNCTION, I WANTED TO MAKE A RIGHT TURN AND CONTINUED MY JOURNEY. WHILE MY VEHICLE WAS TURNING, THERE WAS A PEDESTRIAN SUDDENLY CROSSING THE ROAD WITH BLINKING GREEN ME LIGHT. UPON SEEING IT, I BRAKE AND STOPPED MY VEHICLE AND ALLOW THE PEDESTRIAN TO CROSS OVER. IN A SPLIT OF SECONDS, I SUDDENLY FELT A HARD AND STRONG IMPACT COMING FROM MY VEHICLE REAR. I GOTTEN OFF FROM MY VEHICLE AND REALISED THAT VEHICLE B (TAXI) HAD COLLIDED ONTO MY REAR. NO INJURIES

I WAS DRIVING VEHICLE A AND WAS TRAVELLING FROM ANSON ROAD

...

VEHICLE IS IN OUR WORKSHOP PREMISES.

Present Location:

Remarks:

LIM TAN MOTOR PTE LTD (HQ)

WERE INVOLVED. THAT'S ALL.

COST OF CLAIMS	Amount
Parts	6,336.97
Miscellaneous Items	10.00
Labour	960.00
Paintwork Labour	1,200.00
Towing	0.00

Gross Total (S\$)	8,506.97		
+ GST 7.00% (S\$)	595.49		
Nett Amount (S\$)	9,102.46		

This claim is handled by: ANG WEI GUANG, RICHARD

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Mar 2018)

NISSAN TEANA 2.5 CVT ABS D/AB HID 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0) 143 Parts:

Repairer's (Price-denominated Standard List) Labour: Print Code: Lim Tan Motor Pte Ltd/SJB329Z/09/03/2018 16:11

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*REAR BUMPER *REAR BUMPER SPONGE		10.00	0.00 PM	040.00114	
	2		*REAR BUMPER BRACKET	2000	10.00	0.00	*183.40 FN	17
	2		*REAR BUMPER RETAINER MISE!	0/1 In	10.00	0.00	*110.20 FN	
	2		*REAR BUMPER CHROME MOULDING PAISE	n lene con	10.00	0.00	*291.00 FN	-
	1		*REAR END PANEL	By	10.00	0.00	*550.20 FN	
	1		*REAR END PANEL GARNISH	Bux		0.00	*95.30 FN	-
	1		*REAR SPARE TYRE PANEL TOP SPONGE	cns	10.00	0.00	*462.00 FN	-
	2		*TAIL LAMP	cry	10.00	0.00	1,146.20 FN	
0	1		*REAR BOOT LID	R	10.00	0.00	1,000.70 FN	-
1	2		*REAR BOOT HINGE	n		0.00	*340.60 FN	IX
2	1		*REAR BOOT TOP LOCK	P,	10.00	0.00	*135.10 FN	
3	1		*REAR BOOT BOTTOM STICKER	Del		0.00	*58.00 FN	
4	1		*REAR BOOT RUBBER	Peform	10.00	0.00	*156.80 FN	
5	1		*REAR BOOT CHROME MOULDING - TOP		10.00	0.00	*369.10 FN	
6	1		*REAR BOOT CHROME MOULDING - BOTTOM	cn	10.00	0.00	*252.80 FN	1 -
7	1		*REAR BOOT CENTRE ENBLEM	na	10.00	0.00	*66.40 FN	1 -
В	1		*REAR BOOT TENA EMBLEM	m	10.00	0.00	*87.00 FN	1 -
9	1		*REAR BOOT 250XV V6 EMBLEM	na	10.00	0.00	*59.50 FN	-
0	2		*REAR BUMPER REVERSE SENSOR	Do	0	0.00	*588,00 FS	_
1	1		*REAR NUMBER PLATE	15		0.00	*40.00 FS	-
=Fra	nchise	part. S=SpcNe	tt. N=NettItemDisc.		to others	2784204.00	Charleston and Charles	
Sub Total (S\$) - Nett Item Discount on N Items (S\$)				6,971.30				
				634.33				
			To	otal Parts (S\$)			6,336.97	

Lim Tan Motor Pte Ltd/SJB329Z/09/03/2018 16:11. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No (Qty Particulars		Amount
Misce 1 1	Ilaneous Items OD/TP Case (Insurer)		10.00
		Sub Total (S\$)	10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Pair	itwork Labour		8001
1	TO PUTTY & SPRAY PAINTING.	New	1,200.00
Lab	our Items		027
2	TO CHECK REAR WIRING AND WATER LEAKAGE.	New	201 30.00
3	TO ANTI-RUST.	New	601 80.00
4	LABOUR CHARGES.	New	700 850.00
		Gross Labour Cost (S\$)	2,160.00

Lim Tan Motor Pte Ltd/SJB329Z/09/03/2018 16:11. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >