

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No:67452063/67467158 Fax No:67458520

VEH: SKH 6529E

Not Allowed
dkt
12/3/18
2/59 6400
527.

QTY	PARTICULAR	AMOUNT
1PCS	BOOTLID	12 \$1,562.00 X
1PCS	BOOTLID REAR LOGO	Rec \$68.00 ✓
1PCS	BOOTLID WEATHERSTRIP	twi \$275.00 ✓
1PCS	BOOTLID INNERLOCK	11 \$299.08 X
1PCS	BOOTLID REFLECTOR N/S	11 \$385.00 X
1PCS	REAR BUMPER	1/2e \$1,845.00 —
1PCS	REAR BUMPER REINFORCEMENT	521 \$721.01 —
1PCS	REAR BUMPER INNER TOP GUIDE	one \$161.23 —
2PCS	REAR BUMPER SIDE RETAINERS @\$98.20	11 \$196.40 X
1SET	REAR BUMPER CLIPS	rec \$60.00 —
1PCS	REAR BUMPER LOWER SKIRTING	cur/2e \$680.00 —
4PCS	REAR BUMPER PDC SENSOR @\$250.00 215 x 2 = 430	shld \$1,000.00 2pc
2PCS	REAR BUMPER REFLECTORS @\$58.00	11 \$116.00 X
1PCS	REAR BUMPER INNER SENSOR WIRING BOARD	twi \$313.54 —
1PCS	REAR END PANEL	ms \$1,018.57 —
1PCS	REAR END PANEL TOP GARNISH	twi \$248.02 —
2PCS	TAILLAMPS @\$745.00 645	mscne \$1,490.00 1pc
1PCS	REAR EXHAUST ASSY	12 \$1,800.00 X
1PCS 1cat	REAR EXHAUST CHROME PIPE	twi \$480.00 —
1PCS	REAR EXHAUST HEAT SHIELD	12 \$266.00 X
1PCS	REAR LICENCE PLATE W/HOLDER	scr \$50.00 405.00
		\$13,034.85
	TO CHECKING WIRE	6538.69 \$80.00 30
	TO DISMENTLE & REPLAING REVERSE SENSOR	5884.82 \$80.00 50
	TO TRANSFER BOOTLID MECHANISM	11 \$120.00 X
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY	\$150.00 80
	TO SPRAY RUST PROOFING	\$100.00 40
	TO DISMENTLE & REFIX REAR EXHAUST	\$120.00 80
	LABOUR FOR PANEL BEATING ,CUT,WELD,	\$1,080.00 800
	STRAIGHTEN & REPLACING PARTS	
	TO PUTTY & SPRAY PAINTING	\$1,500.00 1000
		\$16,264.85

10%

LKK Auto Consultants hence notify the Repairer of the following: **TOTAL**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

60482
6401