

ASS. REC. BY:

REF: CS/EGI/8004670/Aqd3ⁿ² Special Instruction:

Surveyor: Adrian ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 12/3/2018 @ 1:44pm

Estimated Cost: _____ Bill to: _____

OD TP WS TP RES OD RES EVA INV MV CS

To Inspect Vehicle No: GBA 2013 X Insured: SKC 4310H

at Workshop m/s Cruise Autocare Tel: 68416760

of 53 Ubi Ave 1 #03-53

Policy No: _____ Claim No: SKC4310H/RH/pl

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09/02/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS wp H.O.D. Endorsement: _____

Date/Time: 2:10pm @ 12/3/18 Person Contacted: Mr. Lam Vehicle IN OUT

Date/Time	Action/Instruction	Estimate
		<u>(-/-) Estimate</u>
		<u>GBA 2013 X - X</u>
		<u>SKC 4310 H - X</u>
<u>12/3/18 @ 3:04pm</u>	<u>Informal Bohaini, we are pending estimate from repairer.</u>	
<u>12/4/18 @ 2:55pm</u>	<u>revised to Bohaini by email.</u>	
	<u>US \$2400, 4 days (Red \$664.36, 27%)</u>	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18004670/Aqd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 12-03-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKC 4310H	Veh. Inspected	GBA 2013X
Policy No.		Coverage (\$)	0.00
Claim No.	SKC 4310H/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	12/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/02/2018	Inspection Date	12/03/2018
Survey held at	CRUISE AUTOCARE PL 53 UBI AVE 1 PAYA UBI IND. PARK #03-53 SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SKC4310H/RH/pl

Date: 12th April 2018

Our Ref: CS/EGI18004670/Aqd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. GBA 2013X

We thank you for the instruction on 12/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/03/2018 at the premises of M/s CRUISE AUTOCARE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,064.36</u>
Revised Estimate Amount	: S\$ <u>2,400.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages consistent.
Days of repair: 4 days.
We have NOT authorise repair.

Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 12 March 2018 1:44 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SKC4310H / TP : GBA2013X/LKK / DOA : 09/02/2018
Attachments: GBA2013X - ESTIMATE.pdf; GBA2013X - PRS FORM.pdf; GBA2013X - SAS.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **CRUISE AUTOCARE PTE LTD**,

ADDRESS : 53 UBI AVENUE 1
#03-53 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

PERSON TO CONTACT : TOCK @ 9760 8848 / 6841 6760

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimates and third party's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 12.03.2018
Our Reference: SKC 4310H/RH/pl
Your Reference: GBA 2013X

To: CRUISE AUTOCARE PTE LTD

Sent via Fax 6841 3527
or
Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBA 2013X
Insured's Vehicle: SKC 4310H
Date Of Accident: 09.02.2018

We acknowledge receipt of your request for PRS on: 12.03.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	P5	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - ROHAINI</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 12 April 2018 2:55 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; Rohaini Bte Hussain
Cc: SUR
Subject: RE: SKC4310H / TP : GBA2013X/LKK / DOA : 09/02/2018
Attachments: CSEGI18004670Aqd3.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of GBA 2013X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 13 March 2018 3:04 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>; Rohaini Bte Hussain <Rohaini.Hussain@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKC4310H / TP : GBA2013X/LKK / DOA : 09/02/2018

Dear Rohaini,

Please be informed that we have inspected the vehicle GBA 2013X.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 12 March 2018 2:14 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKC4310H / TP : GBA2013X/LKK / DOA : 09/02/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 13 March 2018 3:04 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.); assignments; Rohaini Bte Hussain
Cc: SUR
Subject: RE: SKC4310H / TP : GBA2013X/LKK / DOA : 09/02/2018

Dear Rohaini,

Please be informed that we have inspected the vehicle GBA 2013X.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 12 March 2018 2:14 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SKC4310H / TP : GBA2013X/LKK / DOA : 09/02/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 12 March 2018 1:44 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SKC4310H / TP : GBA2013X/LKK / DOA : 09/02/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **CRUISE AUTOCARE PTE LTD.**

ADDRESS : 53 UBI AVENUE 1
#03-53 PAYA UBI INDUSTRIAL PARK

- For Hong Kong Movies lovers
- New Hyundai Tucson
- BPL 17/18 - The Explosive Season Begins

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2017 Mercedes GLC250 4MATIC From C&C, Only \$192.8K.



Cheapest In The Market, Serviced And Warranty By C&C, Showroom Condition. Faster Auto Trading StarAd

Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

33 vehicles

Hiace

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Hiace		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Hiace (COE till 02/2022) Fuel Type: Diesel Very Well Maintained By Previous Owner. Most Importantly, Accident Free! Buy With No Worries As Toyota Usually Doesn't Give Much Headaches. Don't Want To Invest Too Much On A Brand New Vehicle? No Pro...	\$35,800	\$9,150 /yr	08-Feb-2007	2,982 cc	-	Van	Available
Car (S) Pte Ltd Posted: 08-Mar-2018 Tags: 2007 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota Hiace (COE till 05/2022) Fuel Type: Diesel Auto! Cheapest In Market, Powerful And Reliable Van, Low Mileage, New Tyres, Excellent Condition, Loan Can Be Arranged, Call Now For Viewing.	\$35,999	\$8,660 /yr	09-May-2007	2,982 cc	150,196 km	Van	Available
Posted: 18-Jan-2018 Tags: 2007 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota Hiace (COE till 06/2022) Fuel Type: Diesel Previous Owner Is Doing News Paper Delivery Work, Engine, Gearbox, Aircon, Tip Top Condition. High Loan Available, Price Neg! Call Or SMS To View!	\$35,800	\$8,440 /yr	08-Jun-2007	2,982 cc	-	Van	Available
ABWIN Bus Pte Ltd Posted: 11-Mar-2018 Tags: 2007 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota Hiace (COE till 08/2022) Fuel Type: Diesel Completed Full Servicing, Tip-Top Condition! Price Negotiable, Flexible Loan With Low Interest Rates, Trade In Are Welcome, Call Now For Viewing And Enquires!	\$38,800	\$8,720 /yr	24-Aug-2007	2,982 cc	-	Van	Available
ABWIN Bus Pte Ltd Posted: 12-Mar-2018 Tags: 2007 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
Car Buying	Car Selling	Car Aftermarket						
Car Ownership	On The Move	Lifestyle		Buy Tyres Online! Latest Special Offers from Tyrepack!				
	Toyota Hiace Commuter (COE till 08/2022) Fuel Type: Diesel Think One Automobile & Trading	\$36,500	\$8,180 /yr	28-Aug-2007	2,982 cc	411,500 km	Bus	Available
Posted: 21-Feb-2018 Tags: 2007 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota Hiace (COE till 09/2022) Fuel Type: Diesel Cheapest In Market! New Timing Belt Set Changed. Excellent Condition With Rear Aircon, Call Now For Viewing And Check Location Before Drop By. Door Step Viewing Can Be Arranged	\$35,800	\$7,920 /yr	18-Sep-2007	2,982 cc	-	Van	Available
Net Link Partners Pte Ltd Posted: 05-Mar-2018 Tags: 2007 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0477H
Vehicle Details	
Vehicle No.:	GBA2013X
Vehicle to be Exported:	Yes
Intended De-registration Date:	12 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	1KD1609639
Chassis No.:	JTFHT02P900003135
Maximum Power Output:	-
Open Market Value:	\$24,590.00
Original Registration Date:	30 Mar 2007
First Registration Date:	30 Mar 2007
Transfer Count:	1
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,394.00
COE Rebate Amount:	\$19,738.00
Total Rebate Amount:	\$19,738.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 12 Mar 2018

CRUISE AUTOCARE PTE LTD

Xico Chen

ESTIMATE

MS: ERGO INSURANCE PTE LTD
TO: CLAIM DEPARTMENT
Fax: 6829 9247

Quotation No: QCA160126
Quote Date: 12-Mar-18
Contact No: 68416760
Fax No: 68413527

Page: 1 of 1.

Veh No.	Description	LIST PRICE	Qty	Amount
GBA2013X				Make / Model: TOYOTA HIACE
PARTS				
1	REAR TAILGATE <i>Dented</i>	\$1,755.30	1	\$1,755.30 ✓
2	REAR BUMPER <i>red</i>	\$347.40	1	\$347.40 ✓
3	REAR EMBLEM, LOGO <i>red</i>	\$67.60	1	\$67.60 ✓
4	REAR END PANEL <i>repair</i>	\$349.30	1	\$349.30 ✓
5	REAR BUMPER RETAINER, LH <i>3mm</i>	\$37.30	1	\$37.30 ✓
6	REAR BUMPER RETAINER, RH <i>3mm</i>	\$37.30	1	\$37.30 ✓
7	REAR BUMPER BRACKET, LH <i>3mm</i>	\$45.85	1	\$45.85 ✓
8	REAR BUMPER BRACKET, RH <i>3mm</i>	\$45.85	1	\$45.85 ✓
9	REAR END GARNISH <i>red</i>	\$154.70	1	\$154.70 ✓

2336.6
1752.45

DISCOUNT GIVEN 25 % (\$710.15)

SPECIAL NETT ITEM				
1	REVERSE SENSOR <i>280</i>	\$250.00	1	\$250.00 <i>200</i>
2	70KM/H STICKER <i>3mm</i>	\$10.00	1	\$10.00 ✓
3	6 PAX STICKER	\$10.00	1	\$10.00 ✓
4	WINDSCREEN SEALANT <i>m</i>	\$60.00	1	\$60.00 ✓

LABOUR				
1	LABOUR TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR			\$120.00 <i>100</i>
2	LABOUR TO REMOVE DAMAGED PARTS, CUT/WELD REAR END PANEL. ALIGN AND REPLACE PARTS			\$800.00 <i>500</i>
3	SPRAY PAINTING ON REAR TAILGATE AND REAR END PANEL			\$450.00 <i>400</i>

LUMP SUM DISCOUNT 20% ~~(\$700.09)~~
3830.45

Sub Total \$3,064.36
GST @ 7% \$214.51
Total: \$3,278.87

Adrian Ling
12/03/18
H/S 04 Days
total: 303245
H/S: 2.41C

Cruise Autocare Pte Ltd.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

53 Ubi Avenue 1, Paya Ubi Industrial Park #03-53 Singapore 408934
TEL: 6841 6760 FAX: 6841 3527
 Email: cruiseac@singnet.com.sg

Signature of Customer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EG118004670/Aqd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 16-04-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKC 4310H	Veh. Inspected	GBA 2013X
Policy No.		Coverage (\$)	0.00
Claim No.	SKC 4310H/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JTFHT02P900003135	Colour	WHITE
Odometer	334369	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	OHTSU	6 mm
L/H Front Tyre	195 R15C	OHTSU	6 mm
R/H Rear Tyre	195 R15C	OHTSU	6 mm
L/H Rear Tyre	195 R15C	OHTSU	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/02/2018	Inspection Date	12/03/2018
Survey held at	CRUISE AUTOCARE PL 53 UBI AVE 1 PAYA UBI IND. PARK #03-53 SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 2013X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	DENTED	1,755.30	1,755.30
1	REAR BUMPER	DEFORMED	347.40	347.40
1	REAR EMBLEM LOGO	NECESSARY	67.60	67.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	349.30	-
1	REAR BUMPER RETAINER,LH	NECESSARY	37.30	37.30
1	REAR BUMPER RETAINER,RH	NECESSARY	37.30	37.30
1	REAR BUMPER BRACKET,LH	BENT	45.85	45.85
1	REAR BUMPER BRACKET,RH	BENT	45.85	45.85
1	REAR END GARNISH	NOT NECESSARY	154.70	-
	LESS 25% DISCOUNT		-710.15	-584.15
			2,130.45	1,752.45
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	70KM/H STICKER (SN)	NECESSARY	10.00	10.00
1	6 PAX STICKER (SN)	NECESSARY	10.00	10.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
			330.00	280.00
LABOUR				
	LABOUR TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR.		120.00	100.00
	LABOUR TO REMOVE DAMAGED PARTS,CUT/WELD REAR END PANEL.ALIGN AND REPLACE PARTS.		800.00	500.00
	SPRAY PAINTING ON REAR TAILGATE AND REAR END PANEL.		450.00	400.00
	-		-	-
	-		-	-
	-		-	-
			1,370.00	1,000.00
GRAND TOTAL			3,830.45	3,032.45



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	----------

Report Ref No. CS/EGI18004670/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.