



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1 Document No 0 Document Date 04/04/2018	Mr Tan Kian Cheong (Chen Jiancha) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE2OR	04/09/2017	SLS0475X	9440	29912 60D/SLS0475X/09031
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	19/03/2018	8.00	04/04/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:A29016406QMY ACC DATE:08/03/18 TOW IN:08/03/18 EXCESS:\$500 DATE-IN:19/03/18 DATE SURVEY:19/03/18 NO OF REPAIR DAYS:10 BY:taufikh AUTHORIZED ON:19/03/18	*			50.00
2	B	BP-LAB CHECK WIRING AND REFOCUS HEADLAMP	*			169.50
3	L	BP-LPO SUPPLY REGN PLATE (PO#)	E33			80.00
4	B	BP-MECH R/I AIRCOND PIPE VACCUM AND REGAS				339.00
5	B	BP-MECH REPL DASHBOARD ASSY				1356.00
6	B	BP-MECH REPL SEAT BELT ASSY				678.00
7	B	BP-MECH RESET ECU UPON COMPLETION OF REPAIR				678.00
8	B	BP-MECH REPL AIRBAG SENSOR AND ECU				169.50
9	B	BP-MECH R/I ABS UMP AND FUSE TO TO FAC REPAIR ON LH AND RH WHEEL HOUSE				508.50
10	Z	BP-SLANT SUPPLY SEALANT (NETT) 2 PANEL				160.00
11	B	BP-LAB REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	*			4068.00
12	B	BP-RES RESRPAY ACC AFF AREA	*			3336.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623274

TO SECURITY GUARD

3623274

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/04/2018
TIME 14:09

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jiancha) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No 0	
	Document Date 04/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	04/09/2017	SLS0475X	9440	29912 60D/SLS0475X/09031
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	19/03/2018	8.00	04/04/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	V	EXC Excess element of insurance repair to be 88 paidby the insured party				-500.00
14	1	T52119-68909 COVER, FR BUMPER	1.00	574.90	15.00	488.66
15	2	T52115-68031 SUPPORT, FR BUMPER RH	1.00	60.90	15.00	51.76
16	3	T52116-68031 SUPPORT, FR BUMPER LH	1.00	60.90	15.00	51.76
17	4	T52611-68030 ABSORBER FR BUMPER	1.00	89.20	15.00	75.82
18	5	T52021-68020 REINFORCEMENT, FR	1.00	295.70	15.00	251.34
19	6	T52030-68010 COVER, BUMPER HOLE RH	1.00	83.30	15.00	70.80
20	7	T53101-68010 GRILLE, RADIATOR	1.00	401.80	15.00	341.53
21	8	S52161-0K040 PIECE, RR BUMPER	10.00	3.90	15.00	33.10
22	9	T53811-68060 FENDER SUB-ASSY, RH	1.00	955.90	15.00	812.51
23	0	T53812-68060 FENDER SUB-ASSY, LH	1.00	955.90	15.00	812.51
24	1	T53301-68020 HOOD SUB ASSY	1.00	945.30	15.00	803.50
25	2	T90467-09050 CLIP	6.00	2.30	15.00	11.70
26	3	T53510-68050 LOCK ASSY HOOD	1.00	89.80	15.00	76.33
27	4	T53410-68030 HINGE ASSY HOOD RH	1.00	57.10	15.00	48.53
28	5	T53420-68030 HINGE ASSY HOOD LH	1.00	57.10	15.00	48.53
29	6	T53208-68020 SUPPORT HOOD LOCK	1.00	89.80	15.00	76.33
30	7	T53201-68021 SUPPORT SUB ASSY	1.00	1441.10	15.00	1224.93
31	8	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	15.00	61.37
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623275

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/04/2018
TIME 14:09

3623275

VEHICLE NO SLS0475X

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

CUSTOMER

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jianche) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No 0	
	Document Date 04/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE2OR	04/09/2017	SLS0475X	9440	29912 :60D/SLS0475X/09031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	19/03/2018	8.00	04/04/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	9	TSUNCY-MOULD	1.00	211.50	15.00	179.77
33	0	S88450-02350	1.00	1507.40	15.00	1281.29
34	1	T55302-68901 BO	1.00	920.80	15.00	782.68
35	2	T81185-68100	1.00	1222.20	15.00	1038.87
36	3	T81145-68100	1.00	1222.20	15.00	1038.87
37	4	T89173-59275	2.00	314.00	15.00	533.80
38	5	T16533-21040	2.00	39.00	15.00	66.30
39	6	T16711-37070	1.00	221.40	15.00	188.19
40	7	T16361-28350	1.00	183.10	15.00	155.63
41	8	T16361-28360	1.00	234.20	15.00	199.07
42	9	T16363-37030	1.00	548.90	15.00	466.56
43	0	T16363-37090	1.00	548.90	15.00	466.56
44	1	T17700-37211	1.00	950.30	15.00	807.75
45	2	T53299-68010	1.00	78.60	15.00	66.81
46	3	T84307-74020	1.00	953.30	15.00	810.30
47	4	T16470-37030	1.00	158.80	15.00	134.98
48	5	T45130-68041 BO	1.00	2402.20	15.00	2041.87
49	6	T73960-68010	1.00	3240.20	15.00	2754.17
50	7	T73210-68040 CO	1.00	838.20	15.00	712.47
51	8	T73220-68040 CO	1.00	838.20	15.00	712.47
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3623276

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 04/04/2018
TIME 14:09

3623276

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	Mr Tan Kian Cheong (Chen Jiancha) 572 Hougang Street 51 #09-37 Singapore 530572 Mobile: 91822482
	Document No 0	
	Document Date 04/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	04/09/2017	SLS0475X	9440	29912 :60D/SLS0475X/09031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W40J007490	2ZR1981506	60	Shashitharan	19/03/2018	8.00	04/04/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
52	9	T89170-68060 SENSOR ASSY, AIR BAG	1.00	741.00	15.00	629.85
53	0	T82140-68020 WIRE ASSY	1.00	24.10	15.00	20.48
54	1	T53113-68010 GRILLE RADIATOR LWR	1.00	55.20	15.00	46.92
55	2	T53112-68030 GRILLE RADIATOR LWR	1.00	55.20	15.00	46.92
56	3	T53119-68010 PROTECTOR GRILLE	1.00	28.50	15.00	24.22
57	4	T53149-68010 PROTECTOR RADIATOR	1.00	31.30	15.00	26.60
58	5	T57141-68010 SUPPORT, FR BUMPER	1.00	49.10	15.00	41.73
59	6	T57142-68010 SUPPORT, FR BUMPER	1.00	49.90	15.00	42.41
60	7	T57117-68010 RETAINER FR BUMPER	1.00	99.20	15.00	84.32
61	8	T57118-68010 RETAINER, FR BUMPER	1.00	102.20	15.00	86.87
62	9	T16410-37201 RADIATOR ASSY, L/CAP	1.00	1800.20	15.00	1530.17
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 22,359.91	33,452.41
		Labour 11,512.50	GST 7.00% 2,341.67
		Materials 80.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
		Amount Due	35,794.08

PLEASE TEAR ALONG PERFORATED LINE

3623277

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 04/04/2018
TIME 14:09

3623277

VEHICLE NO SLS0475X

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors