

Arda

cc 6, III 800 4721, Uwa391

LEK:
IDAC:

Surveyor:

M. A. P. S.

DOI:

ASSIGNMENT

13/3/18

Det./ Time:

13/3/18

Registered in Merimen:

13/3/18

Pre-assign / CCU / FTE

SH7441Y

m418020686



Insured Vehicle No.:

Claim No.:

Name of Insured:

CPL

Policy No.:

mcam0015

Insured Tel No.:

HP:

Make / Model:

H- Sonata

Excess Sec II :SS

D.O.A.:

20/2/18

Place of Accident:

KPG 7 Tampines

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHOO SOON H HONG

OI GIA REPORT: YES / NO, TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHV 7511Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

Choo Soon H
7300~

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

20/3

unsub

SHV 7511Y - c16/11/17 0153m/Uwa392, uen: 81m/1
SHV 7511Y - c16/11/17 0153m/Uwa392, uen: 81m/1
c16/11/17 0153m/Uwa392, uen: 81m/1

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / OIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

20/3/18

Sent liability under via merimen

20/3/18

Receive video from III

20/3/18

reject TP claim. TP change ltr. Box m 220 video

22/3/18

Email to wkshop reject claim.

RECEIVED 22 MAR 2018

Return Case
Refused: Urban
Approved: Olan
Date: 22/3/18

PRELIMINARY ADVICE		Date/Time:	Sent By:		
FINALIZATION		Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	SS	(days)	Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email ☐ Call ☐	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:			If NO or B 28, Ass. Lia:
Repair Cost:	SS				
Loss of Rental (LOR):	SS	(days)			
Loss of Use (LOU):	SS	(\$ x days)			
Loss of Income (LOI):	SS	(\$ x days)			
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS				
Medical:	SS				
Disbursement:	SS	(e.g. Tow/ Independent)			
Legal Cost	SS				
Total:	SS	Global Sum SS:			
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	SS	Name 1:			
Payee 2: (Strike if N.A.)	SS	Name 2:			
Payee 3: (Strike if N.A.)	SS	Name 3:			

COPY SENT 22/3/18

1) Claim status: Normal/Reject/Private Settle
2) Report Format: reject
3) Survey fee: \$20.00

(08/11/13) wel

ASS. REC. BY: Marcus

REF:

c i l

W

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / E/A / INV / MV

To Inspect Vehicle No: SGV 75114at Workshop m/s Choo auto

of _____

Insured: SH 74414

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 28k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: ✓ Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 7300wDate: 25/1/2022 Person Contacted: _____Date / Time Action / Instruction 274 21684have G1421/3/18 Confund x/s 3000 with Aler.Veh No: SGV 75114 Yr Regn: 6107Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (m)Make: mit Lence c.c. 1584Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 390233 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM15NCS3A74008728Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195-160215

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mmR/Bal. 6 mmL/Bal. 0 mmD.O.A. 20/2/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Nil only

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

(Adm \$ 6340.00
681)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III18004721/Uwa3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 13-03-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7441Y	Veh. Inspected	SGV 7511Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/02/2018	Inspection Date	13/03/2018	
Survey held at	CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

CHOO MOTOR SPRAY PAINTER

Not Assembled
Late
2/5 83000
4dy.

VEH: SGV7511Y

QTY	NETT ITEM	AMOUNT
1PCS	FRONT DOOR 1/5	2 \$981.00 X
1PCS	FRONT DOOR CHROME MOULDING 1/5	Scr \$115.00 ✓
1SET	FRONT DOOR FRAME BLACK STICKER 1/5	11 \$112.00 X
1PCS	REAR DOOR N/S 745	20/scr \$922.00 ✓
1PCS	REAR DOOR CHROME MOULDING N/S	scr \$115.00 ✓
1SET	REAR DOOR FRAME BLACK STICKER N/S	scr \$110.00 ✓
1PCS	REAR DOOR RUBBER N/S	scr \$182.00 ✓
1PCS	CENTRE PILLAR N/S	2 \$645.00 X
1PCS	REAR FENDER N/S	2 \$845.00 X
1PCS	REAR BUMPER	De/To.1 \$671.00 ✓
1PCS	REAR BUMPER SIDE HOLDER N/S	scr \$62.00 ✓
1SET	REAR BUMPER CLIPS	scr \$45.00 ✓
1PCS	REAR SHOCK ABSORBER N/S	11 \$320.00 X
1PCS	REAR WHEEL HUB BEARING N/S	11 \$425.00 X
1PCS	REAR SPORT RIM N/S	(4) \$680.00 3005-
		\$6,230.00

10%

20/5
1840.5

TO CHECK WIRING
TO DISMENTLE & REFIX REAR REVERSE SENSOR
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY
TO CONDUCT WHEEL ALIGNMENT
TO TRANSFER REAR DOOR MECHANISM
TO SPRAY RUST PROOFING
TO DISMENTLE & REFIX REAR UNDERCARRIAGE
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$80.00 20
\$80.00 50
\$120.00 60
\$100.00 60
\$100.00 60
\$100.00 30
11 \$150.00 X
\$880.00 450
\$1,500.00 900

TOTAL

\$9,340.00

31705

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey post-repair spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7300W
Vehicle Details	
Vehicle No.:	SGV7511Y
Vehicle to be Exported:	No
Intended De-registration Date:	13 Mar 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	4G18JC4673
Chassis No.:	JMYSNCS3A7U008728
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$9,915.00
Original Registration Date:	26 Jun 2007
First Registration Date:	26 Jun 2007
Transfer Count:	3
Actual ARF Paid:	\$10,907.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,313.00
COE Rebate Amount:	\$21,684.00
Total Rebate Amount:	\$21,684.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Mar 2018

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Fly Singapore to Bali

One way direct

Hot Sale

AS low from

\$79

Book Now

See Conditions

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2016 Audi A3 Sportback Attraction @ \$101,800 Only.

Best Price In Market. White, 1 Owner, Full Records, Boreyton Rims, Drop By Now. Tradeit.Com Pte Ltd StarAd

ABWIN

ONE-STOP

SALE

REPAIR

RENTAL

Browse by Category

▼

◀ Back (1 2 3) Next ▶

Sort by Date Posted

▼

20 results/page

▼

47 vehicles

Mitsubishi Lancer

Advanced Search

Submit

Search Selection

Mitsubishi Lancer

Any

Any

> 10 year(s) old

Any

Any

Any

Available

Mitsubishi Lancer 1.6A GLX (COE till 09/2021)

\$22,500

\$6,430 /yr

12-Sep-2006

1,584 cc

159,000 km

Sedan

Available

Loan Up To 95%. Original Condition All Our Vehicles Has Undergone A 120 Points Safety Check By Our In House Mechanics With Assessment Report And Come With One Year In House Warranty. Purchase With Ass...

Posted: 13-Mar-2018 Tags: 2006 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Mitsubishi Lancer 1.6A GLX (COE till 06/2022)

\$34,800

\$8,120 /yr

25-Jun-2007

1,584 cc

-

Sedan

Available

\$5000 To \$7000 Drive Away! 1 To 1 Exchange Available! Monthly From \$594, Guaranteed Approval! All Our Cars Have Undergone A Workshop Check. Buy With Trust And Assurance! Expect Only Honest Deals! Call...

Posted: 13-Mar-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Mitsubishi Lancer 1.6A GLX Sports (COE till 04/2022)

\$29,800

\$7,230 /yr

26-Apr-2007

1,584 cc

145,000 km

Sedan

Available

One Year In-House Warranty! With Official Warranty Certificate For Peace Of Mind, Our Company Renew COE Cars For Sale Base On Car Condition Not On Ownership, Fully Refurbished, New Paintwork, Accident...

Carway

Posted: 13-Mar-2018 Tags: 2007 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Mitsubishi Lancer 1.6A GLX (New 5-yr COE)

\$29,800

\$5,960 /yr

26-Feb-2008

1,584 cc

45,000 km

Sedan

Available

\$5k Driveaway! Looks, Drives, Feel Like New. 1 Owner, Fully Stock, No Repair Needed, View To Believe, Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergen...

PREMIUM

Posted: 12-Mar-2018 Tags: 2008 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

42233E

Bidded Carplates For Sale!

Mitsubishi Lancer 1.6A GLX (COE till 06/2021)

\$20,900

\$6,330 /yr

06-Jul-2006

1,584 cc

-

Sedan

Available

Beautiful Silver Unit Well Maintained By Owner. Selling Due To Upgrading. Highly Recommended For Daily Usage, Family User, Uber/Grab Purposes. Trade In Welcome, Loan Available! Please Call To Arrange ...

PREMIUM

Posted: 12-Mar-2018 Tags: 2006 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Mitsubishi Lancer 1.6A GLX (COE till 02/2021)

\$18,000

\$6,170 /yr

10-Feb-2006

1,584 cc

128,000 km

Sedan

Available

Japan Made Fantastic Family Car, Mechanically Reliable. Timing Belt, Tyres, Battery Had Been Changed. Previous Owner Was My Wife Cousin. Female Driven By My Wife To Drop Kids To School. Low Millage Of...

CREDIT OWNER

Posted: 12-Mar-2018 Tags: 2006 Mitsubishi Lancer, Mitsubishi Lancer, Mitsubishi, Lancer, Used Mitsubishi

Compare

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Thursday, 22 March, 2018 10:40 AM
To: 'jason@fastechauto.com.sg'
Cc: Joy Irene (LKKAuto)
Subject: Your Ref: SGV 7511Y, Our Ref: CC6/III18004721/Uwa3, Accident on 20/02/2018 involving SGV 7511Y & SH 7441Y
Attachments: SH 7441Y.mp4; Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: SGV 7511Y
Our Ref: CC6/III18004721/Uwa3

Dear Sir/Madam,

Accident on 20/02/2018 involving SGV 7511Y & SH 7441Y

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client swerved and collided onto our Insured.

We attached herewith our insured's accident report and our insured's video for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

As such, we will close the matter at our end.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SGV7511Y (MCT18020686)
[SH7441Y]**

TP
INTECH COMPANY
Feb 20 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Choo Motor Spray Painter

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 20/03/2018 16:41 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SGV7511Y - Claim Handler: Zuhaidah Bte Samsuri

Approved:0.00:Video uploaded. Please reject TP claim since TP was changing lane whilst OID was travelling straight in his own lane.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Mar 2018 Edit Reg		13 Mar 2018 00:00 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	INTECH COMPANY , Co. Reg. No.: 523187300W		
Vehicle Reg. No.:	SGV7511Y	Date of Loss:	20/02/2018 00:00 - :59
Claim Type:	TP / MCT18020686	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SH7441Y	Policy No. (Claimant):	5091479234
	Excess:		
Repairer:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (20/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SGV7511Y - Claim Handler: Zuhaidah Bte S...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGV7511Y (MCT18020686)
[SH7441Y]
TP
INTECH COMPANY
Feb 20 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Choo Motor Spray Painter

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	20/03/18 16:38	Video - Accident(OID)	1	Load MP4	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/03/18 18:28	Odometer Reading	1	Load JPG	☒
2	13/03/18 18:28	General View	1	Load JPG	☒
3	13/03/18 18:28	Chassis Number	1	Load JPG	☒
4	13/03/18 18:28	General View	1	Load JPG	☒
5	13/03/18 18:28	General View	1	Load JPG	☒
6	13/03/18 18:28	General View	1	Load JPG	☒
7	13/03/18 18:28	General View	1	Load JPG	☒
8	13/03/18 18:28	General View	1	Load JPG	☒
9	13/03/18 18:28	General View	1	Load JPG	☒
10	13/03/18 18:28	General View	1	Load JPG	☒
11	13/03/18 18:28	General View	1	Load JPG	☒
12	13/03/18 18:28	General View	1	Load JPG	☒
13	13/03/18 18:28	General View	1	Load JPG	☒
14	13/03/18 18:28	General View	1	Load JPG	☒
15	13/03/18 18:28	General View	1	Load JPG	☒
16	13/03/18 18:28	General View	1	Load JPG	☒
17	13/03/18 18:28	General View	1	Load JPG	☒
18	13/03/18 18:28	General View	1	Load JPG	☒
19	13/03/18 18:28	General View	1	Load JPG	☒
20	13/03/18 18:28	General View	1	Load JPG	☒
21	13/03/18 18:28	General View	1	Load JPG	☒
22	13/03/18 18:28	General View	1	Load JPG	☒
23	13/03/18 18:28	General View	1	Load JPG	☒
24	13/03/18 18:28	General View	1	Load JPG	☒
25	13/03/18 18:28	General View	1	Load JPG	☒
26	13/03/18 18:28	General View	1	Load JPG	☒
27	13/03/18 18:28	General View	1	Load JPG	☒
28	13/03/18 18:28	General View	1	Load JPG	☒
29	13/03/18 18:28	General View	1	Load JPG	☒
30	13/03/18 18:28	General View	1	Load JPG	☒
31	13/03/18 18:28	General View	1	Load JPG	☒
32	13/03/18 18:28	General View	1	Load JPG	☒

33	13/03/18 18:28	General View	1	Load JPG	☒
34	13/03/18 18:28	General View	1	Load JPG	☒
35	13/03/18 18:29	General View	1	Load JPG	☒
36	13/03/18 18:29	General View	1	Load JPG	☒
37	13/03/18 18:29	General View	1	Load JPG	☒
38	13/03/18 18:29	General View	1	Load JPG	☒
39	20/03/18 08:12	Reinspection Photo	1	Load JPG	☒
40	20/03/18 08:12	Reinspection Photo	1	Load JPG	☒
41	20/03/18 08:12	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/03/18 11:32	TP GIA REPORT	1	Load PDF	
2	22/03/18 10:43	Email to wkshop reject claim 22.3.18	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	14/03/18 08:45	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18004721/UWA3Q2

Date: 23/03/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SGV7511Y

Insured Vehicle No: SH7441Y

Date of Loss: 20/02/2018

Nature of Claim: TP

Claim No: MCT18020686

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGV7511Y

Make & Model: MITSUBISHI LANCER, 1.6 (M)

Engine No: 4G18JC4673

Reg. Date: 26/06/2007 (Man. Year: 2007)

Chassis No: JMYSNCS3A7U008728

Colour: Silver

Odometer: 390233 km

Engine Capacity: 1584 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,230.00	2,140.50	4,089.50	65.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,630.00	1,480.00	47.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,340.00	3,770.50	5,569.50	59.63
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	9,340.00	3,000.00	6,340.00	67.88
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/03/2018

Date Inspected: 13/03/2018 Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @
Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2018)
Parts: 143	MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGV7511Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR N/S	Repair	981.00 F	*- FN
2	1		*FRONT DOOR CHROME MOULDING N/S	Scratched	115.00 F	*115.00 FN
3	1		*SET FRONT DOOR FRAME BLACK STICKER N/S	Not Necessary	112.00 F	*- FN
4	1		*REAR DOOR N/S	Dented / Bent	922.00 F	*745.00 FN
5	1		*REAR DOOR CHROME MOULDING N/S	Bent	115.00 F	*115.00 FN
6	1		*SET REAR DOOR FRAME BLACK STICKER N/S	Necessary	110.00 F	*110.00 FN
7	1		*REAR DOOR RUBBER N/S	Necessary	182.00 F	*182.00 FN
8	1		*CENTRE PILLAR N/S	Repair	645.00 F	*- FN
9	1		*REAR FENDER N/S	Repair	845.00 F	*- FN
10	1		*REAR BUMPER	Deformed / Torn	671.00 F	*671.00 FN
11	1		*REAR BUMPER SIDE HOLDER N/S	Bent	62.00 F	*62.00 FN
12	1		*SET REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FN
13	1		*REAR SHOCK ABSORBER N/S	Not Necessary	320.00 F	*- FN
14	1		*REAR WHEEL HUB BEARING N/S	Not Necessary	425.00 F	*- FN
15	1		*REAR SPORT RIM N/S	Cut	680.00 FS	*300.00 FS
					Sub Total (S\$)	6,230.00 2,345.00
					- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00 204.50
					Total Parts (S\$)	6,230.00 2,140.50

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	120.00	60.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	60.00
5	TO TRANSFER REAR DOOR MECHANISM	New	100.00	60.00
6	TO SPRAY RUST PROOFING	New	100.00	30.00
7	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	150.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	880.00	450.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,110.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >