

INS. CASE OWNER

CC 4/AIG1800

4722, A^a MB39

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

04/07/18

Date / Time:

12/7/18

Registered in Merimen:

12/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SYU 903U

Name of Insured:

KOH LEN MYOMAN

Insured Tel No.:

HP:

96856911

Excess Sec II :SS

D.O.A:

09/07/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

005856480159

Policy No.:

200220577

Make / Model:

MERCEDES

Place of Accident:

113 BUKIT BATOK CT 70 open up

If NO, Driver Name / Age:

Driver Tel No.:

(V/L/YES/NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SV 3630C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Torque 5



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

04/7/18
BEVAN

16/3/18

SV 3630C - 7
SV 903U - 7

Called OI confirm accident details
OI coming out of the carpark 101
and collided to TP. Information to OI
claim. OI is aware TP will be
affected. IPATV sent to OI.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

S\$

100

(Agreed / Assessed) BOLA S/N No.:

24

Repair Cost:

S\$

3459.00

Loss of Rental (LOR):

S\$

600.00

(

6

days)

x100

Loss of Use (LOU):

S\$

(

x

days)

Loss of Income (LOI):

S\$

(

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/Independent)

Legal Cost

S\$

Total:

S\$

4561.00

Global Sum S\$:

4560.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4560.00

Name 1:

TORQUE 5 PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Copy sent to
10/7/18

A1G

ASSIGNMENT

Date 13/3/18

SV3630C

2010 Jan.

Estimate Cost

OT/TP/WS/TP/RES/OD/RES/EVA/INV/MV

To: Insurance No: SV3630C

at Workshop: Torque 5

of: 8 Kaki Bk Ave 4 #01-49

Insured

Policy No

Damage No

Sum Insured

Excess

Client's Record

After 2pm

Make of Van

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Ball or Market Value

C/O Accident Report

Consistent? Yes or No

C/A PP Seen

Consistent? Yes or No

Est Repair

5

days

Res.

Yes or No

L/H Sum

20

%

3 Val.

Yes or No

CA / REV / REP. / 24 HRS / up

Date

Person Contacted

Vehicle IN / OUT

Date Time

Action / Instruction

TP A1G.

MV: 25K

PV: 15.7K

Nett: 9.3K

\$ 3700+ (Redt 13583.30 / 78%).

Date Time File Pass of

☐

Prel. Report

☐

Final Report

Date Time File Return of

Days Of Repair

Resurvey No. of Trip

Survey Fee

Report Format

L/H Sum / B

Add Fee

☐

Gre. Fee

C. Fee

Tech. Fee

Exp. Fee

Make

Mazda 3

1598

Colour

White

So Reading

121251

Eng No

C No

JM6BL10.21A014935

Gen Cond Good Fair Poor Bad

Steering In order Jammed Leaked Burnt or

Brake In order Jammed Leaked Burnt or

Mod. No. STD A/B/C/D

Tyre Size

215/45R17

215/45R17.

BS/DUN EXNOVA 3+ PS LIZA 1000CHSL PR SUM

TOYO/YOKO or

1capsen.

Front

Rear

R/Ba

d

R/Ba

o6

L/Ba

e6

L/Ba

o6

D/OA

D/O

13/03/18

Survey noted

Torque 5.

Des of Damages Fr. Rear OS NS LC Roofed or

Front o/s.

The L/C Cross's frame Body Structure affected due to collision



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18004722/Amb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 13-03-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJY 903U	Veh. Inspected	SJV 3630C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/03/2018	Inspection Date	13/03/2018
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

TPA19

Born

Vehicle No : SJV3630C
Make & Model : MAZDA ,MAZDA3 1.6L SDN
LUXJM6BL10Z1A0114935
Year of Manufacture : 2009

ESTIMATION REPORT

Estimation No. : E18030029
DOA : 12/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Bonnet <i>new</i>	1.00	1,039.50	1,039.50 <i>+</i>
2	Bonnet hinge (LH) <i>3 new</i>	1.00	70.50	70.50 <i>+</i>
3	Bonnet hinge (RH)	1.00	70.50	70.50 <i>+</i>
4	Bonnet lock	1.00	127.00	127.00 <i>+</i>
5	Bonnet outer rubber <i>new</i>	1.00	95.00	95.00 <i>+</i>
6	Bonnet insulator	1.00	168.80	168.80 <i>+</i>
7	Bonnet insulator clip	10.00	5.00	50.00 <i>+</i>
8	Front bumper <i>schud</i>	1.00	1,048.20	1,048.20 <i>✓</i>
9	Front bumper clip <i>new</i>	10.00	5.00	50.00 30.00
10	Front bumper retainer (LH) <i>new</i>	1.00	39.90	39.90 <i>+</i>
11	Front bumper retainer (RH) <i>new</i>	1.00	39.90	39.90 <i>✓</i>
12	Front bumper bracket (LH) <i>new new</i>	1.00	20.00	20.00 <i>+</i>
13	Front bumper bracket (RH) <i>new</i>	1.00	20.00	20.00 <i>✓</i>
14	Front bumper reinforcement <i>best</i>	1.00	530.40	530.40 382.70
15	Front bumper sponge <i>Not that crushed</i>	1.00	126.10	126.10 <i>✓</i>
16	Front bumper logo <i>new</i>	1.00	54.00	54.00 <i>✓</i>
17	Front bumper fog lamp (RH) <i>crushed</i>	1.00	0.00	0.00 -288
18	Front bumper fog lamp garnish (RH) <i>missing</i>	1.00	85.80	85.80 <i>✓</i>
19	Front bumper lower lip <i>new</i>	1.00	49.80	49.80 <i>+</i>
20	Head lamp (RH) <i>crushed</i>	1.00	1,152.70	1,152.70 <i>✓</i>
21	Head lamp clip (RH) <i>na</i>	2.00	5.00	10.00 <i>✓</i>
22	Front fender (RH) -Repair <i>Repair</i>	1.00	358.50	358.50 <i>+</i>
23	Front fender cowling (RH) <i>torn</i>	1.00	200.00	200.00 <i>✓</i>
24	Front fender cowling clip (RH) <i>new</i>	10.00	5.00	50.00 50

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJV3630C
Make & Model : MAZDA ,MAZDA3 1.6L SDN
LUXJ M6BL10Z1A0114935
Year of Manufacture : 2009

Estimation No. : E18030029
DOA : 12/03/2018

No	Description	Qty	U/P	Amt
25	Front fender inner panel (RH) <i>Reps</i>	1.00	221.00	221.00 <i>+</i>
26	Front grille assy. <i>cracked</i>	1.00	296.40	296.40 <i>-</i>
27	Front grille assy clip <i>see</i>	10.00	5.00	50.00 <i>10.00</i>
28	Support panel <i>cracked</i>	1.00	556.00	556.00 <i>✓</i>
29	Condenser <i>3 new</i>	1.00	1,025.00	1,025.00 <i>+</i>
30	Radiator	1.00	2,723.70	2,723.70 <i>+</i>
31	Horn <i>new</i>	2.00	0.00	0.00 <i>+</i>
32	Wiper tank <i>no tank new</i>	1.00	219.60	219.60 <i>+</i>
33	Wiper motor <i>new</i>	1.00	0.00	0.00 <i>+</i>
34	Front absorber <i>3 new</i>	1.00	425.00	425.00 <i>+</i>
35	Front bearing	1.00	580.00	580.00 <i>+</i>
36	Front knuckle	1.00	350.00	350.00 <i>+</i>
37	Front lower arm	1.00	480.00	480.00 <i>+</i>

Amt S\$ 12,383.30
Discount (0.00%) S\$ 0.00
Subtotal S\$ 12,383.30

Section: Special Nett Items

38	Front rim <i>3 new</i>	1.00	1,500.00	1,500.00 <i>+</i>
39	Front tyre	1.00	500.00	500.00 <i>✓</i>

Amt S\$ 2,000.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,000.00

Section: Labour Items

40	To R&R front accident affected areas	1.00	1,000.00	1,000.00 <i>700</i>
----	--------------------------------------	------	----------	---------------------

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

Vehicle No : SJV3630C
Make & Model : MAZDA , MAZDA3 1.6L SDN
LUX, JM6BL10Z1A0114935
Year of Manufacture : 2009

ESTIMATION REPORT

Estimation No. : E18030029
DOA : 12/03/2018

No	Description	Qty	U/P	Amt
41	To putty & respray front accident affected areas	1.00	900.00	900.00 <i>400</i>
42	To rust proof front accident affected areas	1.00	60.00	60.00 <i>*</i>
43	To R&R aircon condensor & refill gas	1.00	200.00	200.00 <i>120</i>
44	To R&R engine & attachment part	1.00	200.00	200.00 <i>*</i>
45	To check wiring layout & head lamp focus	1.00	80.00	80.00 <i>30</i>
46	To R&R front under carriage	1.00	280.00	280.00 <i>*</i>
47	To check wheel alignment	1.00	180.00	180.00 <i>*</i>

Amt S\$ 2,900.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lim.
L/S 13/03/18.
O/E Pays.

total: 471384
L/S: B.T.K.

List Items Subtotal S\$ 12,383.30
Special Nett Items S\$ 2,000.00
Subtotal
Labour Items Subtotal S\$ 2,900.00
Total S\$ 17,283.30

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5746C
Vehicle Details	
Vehicle No.:	SJV3630C
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN LUX
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	Z6809737
Chassis No.:	JM6BL10Z1A0114935
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$21,679.00
Original Registration Date:	22 Jan 2010
First Registration Date:	22 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$21,679.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2020
PARF Rebate Amount:	\$11,923.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$8,530.00
COE Rebate Amount:	\$3,797.00
Total Rebate Amount:	\$15,720.00

The information contained herein is correct as at 14 Mar 2018

OK



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

5 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SBM

SEARCH RESULTS

Our Ref No: GR-18-037468

Date of Request: 12/03/2018

Your Ref No:

Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 09/03/2018

Place of Accident: 213 BUKIT BATOK ST 21 CARPARK

Client Vehicle No: SJV3830C

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SJV903U	213 BUKIT BATOK ST 21 OPEN CARPARK	09/03/2018 12:10

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-037469

Date of Request: 12/03/2018

Your Ref No:

Online Purchase

Torque 5 Pte Ltd
No. 8 Kallit Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 09/03/2018

Place of Accident: 213 BUKIT BATOKST 21 CARPARK

Client Vehicle No: SJV3630C

DESCRIPTION	AMOUNT (\$\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

TAX INVOICE

Our Ref No: GR-18-037477
Date of Request: 12/03/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Date of Accident: 09/03/2018
Vehicle No: SJV3630C
Place of Accident: BLK 213 BUKIT BATOK ST 21 CARPARK
Involving Vehicle No: SJY903U

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (\$)	QTY	AMOUNT (\$)
SJY903U	BLK 213 BUKIT BATOK ST 21 CARPARK	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18004722/Amb3

19 MARCH 2018

KOH LEN HIYONG

BLK 456 JURONG WEST ST 41

#01-70

SINGAPORE 640456

Dear Sir/Madam,

ACCIDENT INVOLVING SJY 903U AND SJV 3630C ON 09/03/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim

Case Handler

DID: 6749 4274

FAX: 6741 4108

Email: bevanlim@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. Reg. No.: 201313221G

LETTER OF AUTHORISATION

Accident on 09/03/2018 along Blok 213 Bukit Batok St 21 Carpark
Involving vehicles SJV 3630C, SY 9034

In consideration of Torque 5 Pte Ltd, 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit #01-50 Singapore 415875, repairing my/our motor vehicle no SJV3630C at my request, I/We, Phoon Yip Mun Charmaine ("the claimant") of 612 Elias Rd #17-144 S(510612) (address) bearing NRIC No S8915746C the owner of motor vehicle no SJV 3630C, hereby authorize them to demand claim, settle and receive whatever amount settle payable by the insurance company or third party or commence legal proceeding for cost of repairs, loss of use and etc to any of their appointed solicitors to act for me/us in respect of the said accident/claim and all the amount claimed or settled shall belong and make payable to them absolutely by the insurance company of the third party. I/We further authorized them to give an absolute discharge on my/our behalf and to sign discharge voucher(s) and any other documents necessary or incidentals to the conduct and disposal of my/our above claims.

I/We further agree to fully co-operate and attend all court hearings that are necessary to prosecute the claims maintained by **Torque 5 Pte Ltd**.

I/We further agree and undertake to indemnify them against my/our claim for costs which arise therewith.

In the event that my/our claim is unsuccessful, I/we undertake to pay to **Torque 5 Pte Ltd** the cost of repairs to my/our vehicle.

In the event that the settlement/payment cheque is being made in my/our favour, I/we hereby undertake to return the full amount to **Torque 5 Pte Ltd** account, within 7 days from receiving and clearance of the said settlement/payment cheque. Failing which, **Torque 5 Pte Ltd** will have the legal rights to take legal proceedings against me/us to recover the said sum, with further costs and disbursements to be incurred by me/us.

I/We further authorize **Torque 5 Pte Ltd** to settle the aforesaid claim in a manner that you deem fit and to utilize the monies to pay your charges without further reference to me/us. The payment to **Torque 5 Pte Ltd** shall amount to a good discharge of **Torque 5 Pte Ltd** obligation to me/us in respect of the settlement monies.

Dated this 9 day of March (month) 20 18 (year)

Signed by "the claimant"

Name: CHERMAINE PHOON YIP MUN

NRIC No: S8915746C



Signed by Torque 5 Pte Ltd

Name: Michelle

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TORQUE 5 PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 4,560.00 (Global Sum) for vehicle no. SJV 3630C that was damaged pursuant to the accident which occurred on 09/03/2018 (date) along 213 BUKIT BATOK ST 21 OPEN CARPARK (location) involving vehicle no/s SJY 903U.

This is pursuant to the inspection conducted on 13/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PHOON YIP MUN CHARMAINE ("the third party claimant") of vehicle no. SJV 3630C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJV 3630C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 06 (day) of December (month) 20 18 (year)

 LKK WVP

Signed by appointed surveyor





Signed by "the workshop" (with chop)

my execution of this Discharge Voucher is only
for my claim for property damage and not prejudice
to any other claims arising from the same accident.

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Tel: 6419 1000

Tax Invoice

Inv. No. : T51812030
Inv. Date : 06 Dec 2018
Ref : 09/03/2018
Terms : 30 Days
Veh. No. : SJV3630C
Make & Model : MAZDA MAZDA3 1.6L
SDN LUX

#	Description	Qty	UOM	Unit Price	Disc	Amt
1	TO SUPPLY SPARE PARTS AND LABOUR FOR ACCIDENT REPAIR PARTS LUMP SUM AMOUNT	1.00		3,700.00	0.00	3,700.00

I agree to the price as listed above and
affirm that the goods are received in good
condition.

(Customer's Signature and Company Stamp)

Subtotal : S\$ 3,700.00
GST 7.0% : S\$ 259.00
Total : S\$ 3,959.00

For **TORQUE 5 PTE. LTD.**



(Authorised Signature)



Ang Aaron Celestine
612 Elias Rd #17-144 s510612

C/O

Torque 5 Pte Ltd

8 Kaki Bukit Avenue 4, #01-50
Premier @ KB, Singapore 415875
Tel: 6452 4457 Fax: 6452 4584

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit
#01-50 Singapore 415875
Tel: +65 6452 4457 Fax: +65 6452 4584
Email: leasing@torque5.com
Company Reg. No: 201530768C

Rental Invoice

Inv No. : L51803016

Date : 19 Mar 2018

Ref : SJV3630C

Currency : SGD

Terms : COD

RA No. : R18030012

Veh No. : SGM225S

#	Rental Period	Rate	Disc	Amt
1	Rental (09/03/2018 17:40 to 19/03/2018 17:20)	1,200.00	0.0000	1,200.00

*I agree to the price as listed above and
affirm that the goods are received in good
condition.*

(Customer's Signature and Company Stamp)

Subtotal : S\$ 1,200.00

GST 7.0% : S\$ 0.00

Total : S\$ 1,200.00

For **TORQUE 5 LEASING PTE LTD**



(Authorised Signature)



8 Kaki Bukit Ave 4 Premier @ Kaki Bukit
#01-50 Singapore 415875
Tel: 6452 4457 Fax: 6452 4584
Email: leasing@torque5.com
Company Reg. No: 201530768C

RENTAL AGREEMENT

T 001951

HIRER'S PARTICULAR		Veh. No/Model: <u>SV 3630C Mazda 3</u>	
Name: <u>ANH AARON CELESTINE</u>		Rental Veh. No/Model: <u>SHM 2255 N.Latio</u>	
NRIC/Passport No: <u>S89166562</u>		Date/Time Out: <u>9/3/18 5:46pm</u>	
Address: <u>G12 ELIAS RD</u> <u>#17-144 S510612</u>		Date/Time In: <u>19/3/18 5:20pm</u>	
Tel: <u>85180600</u>			
Driving license No: _____ Exp: _____			
ADDITIONAL DRIVER'S PARTICULAR		Mileage: <u>210583</u> Mileage: <u>211183</u> Rental Charges S\$ per hour S\$ Hours @ per hour <u>10</u> Days @ <u>120</u> per day Weeks @ per week Months @ per month Subtotal <u>1200</u> GST @ 7%	
Name: _____		Others	
NRIC/Passport No: _____		TOTAL CHARGES	
Address: _____			
Tel: _____			
Driving license No: _____ Exp: _____			
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES			
		Mode of Payment: Cash/Nets/Cheque/Credit Card: _____ Deposit _____ Deposit _____ Amount _____ Refunded _____ Remarks: _____ Received by _____	
Physical Damage Excess Singapore - Own Damage S\$2,000 Singapore - 3rd Party Damage S\$2,000 Malaysia (if applicable) S\$8,000 For Driver aged < 27 or above 65 and/or less than 2 yrs driving experience regardless of age S\$3,000 (Additional)		Acknowledgement 9/3/18 	
IMPORTANT NOTE: 1. ONLY PERSONS ABOVE 22 YEARS OF AGE, HOLDING A VALID SINGAPORE LICENCE FOR MORE THAN 2 YEARS, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE. 2. Vehicle is strictly for use in Singapore only and may not be driven out of Singapore without the prior written consent of Torque 5 Leasing Pte Ltd. 3. Use of vehicle for illegal purposes (e.g. in connection with theft, drug peddling or trafficking, smuggling) is strictly prohibited. 4. In case of accident, the hirer shall report to Torque 5 Leasing Pte Ltd immediately.			
		Hirer Signature/Date 9/3/18 Owner Signature/Date 	



3/10/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-037329
Date of Request: 10/03/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

*our vehicle:
SJY 3630 C*

Enquiry Date: 10/03/2018
Enquiry By: Stephanie Teo Wan Ting
TP Vehicle No: SJY903U
Accident Date: 09/03/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJY903U	AIG Asia Pacific Insurance Pte. Ltd.	02/08/2017-01/08/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

9/10/2018

Invoice



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-037329
Date of Request: 10/03/2018

Your Ref No: Online Purchase

Torque 5 Pte Ltd
No. 8 Kaki Bukit Ave 4,
#01-50
Singapore 415875

Dear Sir/Madam,

Enquiry Date: 10/03/2018
Enquiry By: Stephanie Tec Wan Ting
TP Vehicle No: SJY903U
Accident Date: 09/03/2018

DESCRIPTION	AMOUNT (\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIAHMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Mar 2018 Edit Reg		12 Mar 2018 00:00 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Koh Len Hiyong , ID: S02052518								
Main Claimant:	PHOON YIP MUN CHARMAINE , ID: S8915746C								
Vehicle Reg. No.:	SJV3630C	Date of Loss:	09/03/2018 12:00 - :59 [97 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0058854801SG	Policy/Cover Note No.:	2100220577 (Comprehensive) Coverage: 02/08/2017 - 01/08/2018						
Vehicle Reg. No. (Insured):	SJY903U	Policy No. (Claimant):	PNPV2018-00002029						
		Excess:							
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJV3630C (0058854801SG)
[SJY903U]
TP
PHOON YIP MUN CHARMAINE
Mar 9 2018 12:00PM
[Koh Len Hiyong]
Torque 5 Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Video													1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	15/03/18 09:31	TP video front - SJV3630C											Load MP4			
2	15/03/18 09:31	TP video rear - SJV3630C											Load MP4			
Letters/Correspondences													1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit			
Assessment Reports													1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print			
1	14/03/18 14:51	Accident Statement From: OD - Reg. No: SJY903U, Claimant: KOH LEN HIYONG											Load HTM			
Photos/Images													3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print			
1	27/08/18 09:38	General View											Load JPG ☒			
2	27/08/18 09:38	General View											Load JPG ☒			
3	27/08/18 09:38	General View											Load JPG ☒			
4	27/08/18 09:38	General View											Load JPG ☒			
5	27/08/18 09:38	General View											Load JPG ☒			
6	27/08/18 09:38	General View											Load JPG ☒			
7	27/08/18 09:38	General View											Load JPG ☒			
8	27/08/18 09:38	General View											Load JPG ☒			
9	27/08/18 09:38	General View											Load JPG ☒			
10	27/08/18 09:38	General View											Load JPG ☒			
11	27/08/18 09:38	General View											Load JPG ☒			
12	27/08/18 09:38	General View											Load JPG ☒			
13	27/08/18 09:38	General View											Load JPG ☒			
14	27/08/18 09:38	General View											Load JPG ☒			
15	27/08/18 09:38	General View											Load JPG ☒			
16	27/08/18 09:38	General View											Load JPG ☒			
17	27/08/18 09:38	General View											Load JPG ☒			
18	27/08/18 09:38	General View											Load JPG ☒			
19	27/08/18 09:38	General View											Load JPG ☒			
20	27/08/18 09:38	General View											Load JPG ☒			
21	27/08/18 09:38	General View											Load JPG ☒			
22	27/08/18 09:38	Reinspection Photo											Load JPG ☒			
23	27/08/18 09:38	Reinspection Photo											Load JPG ☒			
24	27/08/18 09:38	Reinspection Photo											Load JPG ☒			
25	27/08/18 09:38	Reinspection Photo											Load JPG ☒			
26	27/08/18 09:38	Reinspection Photo											Load JPG ☒			

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				☒
27	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
28	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
29	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
30	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
31	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
32	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
33	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
34	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
35	27/08/18 09:38	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/18 14:55	EMAIL FROM AIG DD 12032018	 Load PDF	
2	13/03/18 14:55	TP GIA REPORT	 Load PDF	
3	19/12/18 08:45	WORKSHOP INVOICE	 Load PDF	
4	19/12/18 08:45	AUTHORISATION TO ACT FORM	 Load PDF	
5	19/12/18 08:45	Release Voucher	 Load PDF	
6	19/12/18 08:45	RENTAL RECEIPT	 Load PDF	
7	19/12/18 08:45	GIA SEARCH	 Load PDF	
8	19/12/18 08:45	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/03/18 09:26	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJY903U (Insd veh)	Model:	MAZDA 3 1.6 L (A)
	SJV3630C (TP veh)		
Date of Accident:	09/03/2018		

Global Sum Settlement	: [X]	Yes	[]	No	
Repair Estimate	:	\$			18,801.29
Final Repair Cost	:	\$			4,560.00
Loss of Use	:	\$			days at \$0.00 per day
Rental (if any)	:	\$			6 days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (Global Sum)	:	\$			4,560.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Torque 5 Pte Ltd	: \$	4,560.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

19 Dec

2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18004722/AAB3Q2

Date: 19/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100220577

Claimant Vehicle No: SJV3630C Insured Vehicle No: SJY903U

Date of Loss: 09/03/2018 Nature of Claim: TP Claim No: 0058854801SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV3630C	Engine No:	Z6809737
Make & Model:	MAZDA 3, 1.6 L (A)	Chassis No:	JM6BL10Z1A0114935
Reg. Date:	22/01/2010 (Man. Year: 2009)	Odometer:	121251 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,671.30	3,463.84	11,207.46	76.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,250.00	1,650.00	56.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,571.30	4,713.84	12,857.46	73.17
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	17,571.30	3,700.00	13,871.30	78.94
+ GST 7.00/7.00% (S\$)	1,229.99	259.00	970.99	78.94
Nett Amount (S\$)	18,801.29	3,959.00	14,842.29	78.94
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,561.00		
Global Sum Settlement (S\$)		4,560.00		

INSPECTION

Date of Assignment: 12/03/2018
Date Inspected: 13/03/2018 Inspected At:

Torque 5 Pte Ltd (Kaki Bukit)
No. 8 Kaki Bukit Ave 4,, #01-50
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: OLIVIA LAU WAN YEE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,039.50 F	*- FL
2	1		*BONNET HINGE (LH)	Not Necessary	70.50 F	*- FL
3	1		*BONNET HINGE (RH)	Not Necessary	70.50 F	*- FL
4	1		*BONNET LOCK	Not Necessary	127.00 F	*- FL
5	1		*BONNET OUTER RUBBER	Not Necessary	95.00 F	*- FL
6	1		*BONNET INSULATOR	Not Necessary	168.80 F	*- FL
7	10		*BONNET INSULATOR CLIP	Not Necessary	50.00 F	*- FL
8	1		*FRONT BUMPER	Deformed	1,048.20 F	*1,048.20 FL
9	10		*FRONT BUMPER CLIP	Necessary	50.00 F	*30.00 FL
10	1		*FRONT BUMPER RETAINER (LH)	Not Necessary	39.90 F	*- FL
11	1		*FRONT BUMPER RETAINER (RH)	Necessary	39.90 F	*39.90 FL
12	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	20.00 F	*- FL
13	1		*FRONT BUMPER BRACKET (RH)	Damaged	20.00 F	*20.00 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	530.40 F	*382.70 FL
15	1		*FRONT BUMPER SPONGE	Cracked	126.10 F	*126.10 FL
16	1		*FRONT BUMPER LOGO	Necessary	54.00 F	*54.00 FL
17	1		*FRONT BUMPER FOG LAMP (RH)	Cracked	288.00 F	*288.00 FL
18	1		*FRONT BUMPER FOG LAMP GARNISH (RH)	Missing	85.80 F	*85.80 FL
19	1		*FRONT BUMPER LOWER LIP	Not Necessary	49.80 F	*- FL
20	1		*HEAD LAMP (RH)	Cracked	1,152.70 F	*1,152.70 FL
21	2		*HEAD LAMP CLIP (RH)	Necessary	10.00 F	*10.00 FL
22	1		*FRONT FENDER (RH)	Repair	358.50 F	*- FL
23	1		*FRONT FENDER COWLING (RH)	Torn	200.00 F	*200.00 FL
24	10		*FRONT FENDER COWLING CLIP (RH)	Necessary	50.00 F	*30.00 FL
25	1		*FRONT FENDER INNER PANEL (RH)	Repair	221.00 F	*- FL
26	1		*FRONT GRILLE ASSY	Cracked	296.40 F	*296.40 FL
27	10		*FRONT GRILLE ASSY CLIP	Necessary	50.00 F	*10.00 FL
28	1		*SUPPORT PANEL	Cracked	556.00 F	*556.00 FL
29	1		*CONDENSER	Not Necessary	1,025.00 F	*- FL
30	1		*RADIATOR	Not Necessary	2,723.70 F	*- FL
31	2		*HORN (NPA)	Not Necessary	0.00 F	*- FL
32	1		*WIPER TANK	Not Necessary	219.60 F	*- FL
33	1		*WIPER MOTOR (NPA)	Not Necessary	0.00 F	*- FL
34	1		*FRONT ABSORBER	Not Necessary	425.00 F	*- FL
35	1		*FRONT BEARING	Not Necessary	580.00 F	*- FL
36	1		*FRONT KNUCKLE	Not Necessary	350.00 F	*- FL
37	1		*FRONT LOWER ARM	Not Necessary	480.00 F	*- FL
38	1		*FRONT RIM	Not Necessary	1,500.00 FS	*- FS
39	1		*FRONT TYRE	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **14,671.30** **4,329.80**
 - List Item Discount on L Items 0.00/20.00% (S\$) **0.00** **865.96**

Total Parts (S\$) **14,671.30** **3,463.84**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R FRONT ACCIDENT AFFECTED AREAS	New	1,000.00	700.00
2	TO PUTTY & RESPRAY FRONT ACCIDENT AFFECTED AREAS	New	900.00	400.00
3	TO RUST PROOF FRONT ACCIDENT AFFECTED AREAS	New	60.00	0.00
4	TO R&R AIRCON CONDENSOR & REFILL GAS	New	200.00	120.00
5	TO R&R ENGINE & ATTACHMENT PART	New	200.00	0.00
6	TO CHECK WIRING LAYOUT & HEAD LAMP FOCUS	New	80.00	30.00
7	TO R&R FRONT UNDER CARRIAGE	New	280.00	0.00
8	TO CHECK WHEEL ALIGNMENT	New	180.00	0.00
Gross Labour Cost (S\$)			2,900.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >