

ASS. R.T.C. BY:

REF: CS3/SMO18004744/K/d35M

Special Instruction:

Surveyor: Kalvin ASSIGNMENT (Office)

From (Person): Irene Henry of SMO Date/Time: 12/3/18 @ 3:20pm

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 9418J Insured: TRC 6364G

at Workshop m/s Michellin Engineering Tel: 81816737

of 56 Jayung way #06-07

Policy No: _____ Claim No: CMTD1801088/NSW

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 8/3/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement: _____

Date/Time: 10:01am @ 13/3/18 Person Contacted: Malcom Vehicle IN / OUT

Date/Time	Action/Instruction (+) Estimate
	<u>GBG 9418J - X</u>
	<u>TRC 6364G - X</u>
	<u>After repair: 16/3/2018</u>

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Monday, 12 March 2018 3:20 PM
To: Yvonne
Cc: Ngo, Sau Wei Shawn; assignments; Catherine Chong (LKK Auto)
Subject: RE: PRI : Sompo Insured TRC6364G [EAL.2018.5508.MK.ya - GBG9418J]

Our Reference: CMTD1801088/NSW
Your Reference: 2018.5508.MK.ya – GBG 9418J

Date: 12TH March 2018

Without Prejudice

BY EMAIL ONLY

Attention:

M/S EASE ASIA LAW CORPORATION

ACCIDENT INVOLVING TRC 6364G & GBG 9418J ON 12.03.2018

Dear Sirs,

We refer to your email reply dated 12/03/2017.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO CONSULTANTS PTE LTD** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain

confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Yvonne [mailto:yvonne@ealc.com.sg]
Sent: Monday, 12 March, 2018 2:34 PM
To: Henry, Irene James <irene.henry@sompo.com.sg>
Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>
Subject: PRI : Sompo Insured TRC6364G [EAL.2018.5508.MK.ya - GBG9418J]

Our ref : 2018.5508.MK.ya - **GBG9418J**
Your ref : **TRC6364G**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

Sompo Insurance Singapore Pte. Ltd
No. 50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s Sompo Insurance Singapore Pte. Ltd		
Vehicle GBG9418J inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: PAN PACIFIC VAN & TRUCK LEASING PTE LTD

ACCIDENT INVOLVING GBG9418J & TRC6364G ON 08 MARCH 2018 ALONG 18 TAMPINES INDUSTRIAL CRESCENT- 3RD FLOOR AT ABOUT 0845 HOURS

We refer to the above matter wherein we are instructed to act for **PAN PACIFIC VAN & TRUCK LEASING PTE LTD**, the owner of vehicle no. **GBG9418J**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **GBG9418J** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Michelin Engineering Pte Ltd
56 Loyang Way,
#06-07 Loyang Enterprise Building,
Singapore 508775
Contact: Malcolm-81810737

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO18004744/K1d3s2
50 RAFFLES PLACE #05-01/06		Date:	06-04-2018
SINGAPORE LAND TOWERSINGAPORE 048623			
		Code:	SMO
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	TRC 6364G	Veh. Inspected	GBG 9418J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801088/NSW	Excess (\$)	0.00
Assign From	IRENE HENRY	Assign Date	12/03/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN URVAN	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JN1MC2E26Z0009608	Colour	GREY
Odometer	9540 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	7 mm
L/H Front Tyre	195 R15C	DUNLOP	7 mm
R/H Rear Tyre	195 R15C	DUNLOP	7 mm
L/H Rear Tyre	195 R15C	DUNLOP	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information			
Accident Date	08/03/2018	Inspect Date / Time	13/03/2018 (10:45 AM)
Survey held at	MICHELIN ENGINEERING PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING S 508775		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,800.00			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

Report Ref No. CS3/SMO18004744/K1d3s2

Inspected By

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.