

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BG 3590**
Date Estimated : **12/03/2018**
Prepared By : **Wong Guo Xiang**

Page No. : **1 of 1**

- ESTIMATE REPAIR FOR -

ONG ZIHAO
BLK 547 ANG MO KIO AVENUE 10
#11-2334
SINGAPORE
SINGAPORE 560547

- ACCOUNT - **2000**

CASH - Sale service
.

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ8128H	WF0EXXGBBE9C52756	29/07/2010	MON 2.3T 5DR	0

DESCRIPTION	VALUE
SUNDRIES	150.00
REPLACE FRT LHS FENDER	900.00
RESPRAY FRT LHS FENDER,FRT LHS DOOR	1,500.00
WIRING CONNECTION & CHECK (NETT)	150.00
TO REMOVE & REFIX FRONT HEADLAMP INCLUDING REALIGN HEADLIGHT BEAM LEVEL (NETT)	200.00
TUFF KOTE @ \$60 PER PANEL	120.00
TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODE (NETT)	600.00
Total Labour 1:	3,620.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
P7S7116006AB	LHF FENDER - M07	1	750.00	10.00	675.00
7S71A16115AH	LHF FENDER INNER SHIELD	1	201.00	10.00	180.90
Total Parts :					855.90

Customer Service Officer

Contact

Labour 1	:	3,620.00
Parts	:	855.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.31
Grand Total	:	4,789.21

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.