

Mon 26/03 @ 10am
S&R

SLV8206M

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

3 MAR 2018

Estimate No. : b1 46222	Page No. : 1 of 2
Date Estimated : 13/03/2018	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Neo Beng Ann 156 Haig Road #13-04 Singapore 438793	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV8206M	G390321	22/08/2016	528iA	0

DESCRIPTION	VALUE
To replace front bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray front bumper	934 1,038.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To replace right headlight including program and conduct tests for proper function.	451 531.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
Sundries.	/ 80.00
Total Labour 1:	3,278.00

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT / M6C	10	0.90	9.00
RIVET /	10	0.50	5.00
RH GRILLE AIR INLET PARTLY CLOSED / SCR	1	68.65	68.65
FRT SHOCK ABSORBER 7.	1	48.00	48.00
LEVER RH / OR	1	7.20	7.20
# DUMMY PLUG RH / M6C	1	7.75	7.75
FRT BUMPER PANEL PRIMED (PDC) / Cut	1	1,277.55	1,277.55
COVERING PRIMEND RH - Cut	1	46.45	46.45
EMBLEM GROMMET -	2	0.80	1.60
BMW EMBLEM - / M6C	1	69.50	69.50
CLIP /	10	1.30	13.00
RH HEADLIGHT LED TECHNOLOGY / SCR	1	4,201.60	4,201.60
DECOUPLING RING PDC TORQUE CONVERTE - M6C	1	5.05	5.05
# BUMPER PDC SENSOR (SCHWARZ) /	1	236.85	236.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 46222	Page No.	: 2 of 2
Date Estimated	: 13/03/2018		
Prepared By	: Han Kwan Yong		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV8206M	G390321	22/08/2016	528iA	0

Total Parts : 5,997.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

before paint photos.

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>26/3/18</u>	Claim No. _____
Date&Time <u>26/3/18</u>	Excess S\$ _____
Surveyor's Name <u>Guo Qiang</u>	Sign _____
Surveyor's Tel <u>82880282</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <u>3</u> PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3</u>	

Labour 1	:	3,278.00
Parts	:	5,997.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	649.26
Grand Total	:	9,924.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **