

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E**13 MAR 2018**

Estimate No. : **b1 46213**
Date Estimated : **13/03/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng Soh Eng
19 Jalan Sedap

Singapore 438275

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0

DESCRIPTION

To replace rear bumper assembly and all attachments
cause by accident

VALUE
~~850~~ 1,700.00

Painting on rear bumper upper assembly

~~934~~ 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

~~150~~ 177.00

Sundries.

? 80.00

Total Labour 1: **2,995.00**

DESCRIPTION

REAR BUMPER SET MOUNTING PARTS
RR BUMPER CARRIER
RR BUMPER CTR GUIDE
RR BUMPER CTR BOTTOM GUIDE
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER INSERT (M)
RR BUMPER COVER (M)
PDC HOLDER OUTSIDE LH
PDC HOLDER OUTSIDE RH
PDC HOLDER INSIDE LEFT
PDC HOLDER INSIDE RIGHT
RR BUMPER (M)
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC	VALUE
1	33.15	? 33.15
1	424.25	? 424.25
1	31.60	? 31.60
1	61.20	? 61.20
1	57.05	? 57.05
1	57.05	? 57.05
1	158.45	? 158.45
1	79.70	? 79.70
1	12.45	? 12.45
1	12.75	? 12.75
1	12.80	? 12.80
1	13.10	? 13.10
1	1,247.70	R 1,247.70
4	5.05	? 20.20

Total Parts : **2,221.45**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46213
Date Estimated : 13/03/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 02/04/18 @ 1400 Excess S\$ _____

Surveyor's Name RPM Sign _____

Surveyor's Tel 90060668 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 3 days

Labour 1	:	2,995.00
Parts	:	2,221.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	365.15
Grand Total	:	5,581.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **