

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
Tel. 63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
Tel. 63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
Fax. 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

13 MAR 2018

Estimate No. : b1 46213 Date Estimated : 13/03/2018 Prepared By : Kevin Leong Wai Kit		Page No. : 1 of 2																																																																	
- ESTIMATE REPAIR FOR - Ng Soh Eng 19 Jalan Sedap Singapore 438275		- ACCOUNT - 40000 Cash Sales - Service Singapore																																																																	
REGN. NO. SKV4480A	CHASSIS NO. FG90241	REGN. DATE 28/07/2011	MODEL 318i/4 (A)																																																																
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">DESCRIPTION</th> <th style="text-align: right;">VALUE</th> </tr> </thead> <tbody> <tr> <td>To replace rear bumper assembly and all attachments cause by accident</td> <td style="text-align: right;">1,700.00</td> </tr> <tr> <td>Painting on rear bumper upper assembly</td> <td style="text-align: right;">1,038.00</td> </tr> <tr> <td>To check electrical wiring systems and lightings at the rear section for proper function.</td> <td style="text-align: right;">177.00</td> </tr> <tr> <td>Sundries.</td> <td style="text-align: right;">80.00</td> </tr> <tr> <td style="border-top: 1px solid black;">Total Labour 1:</td> <td style="text-align: right; border-top: 1px solid black;">2,995.00</td> </tr> </tbody> </table>				DESCRIPTION	VALUE	To replace rear bumper assembly and all attachments cause by accident	1,700.00	Painting on rear bumper upper assembly	1,038.00	To check electrical wiring systems and lightings at the rear section for proper function.	177.00	Sundries.	80.00	Total Labour 1:	2,995.00																																																				
DESCRIPTION	VALUE																																																																		
To replace rear bumper assembly and all attachments cause by accident	1,700.00																																																																		
Painting on rear bumper upper assembly	1,038.00																																																																		
To check electrical wiring systems and lightings at the rear section for proper function.	177.00																																																																		
Sundries.	80.00																																																																		
Total Labour 1:	2,995.00																																																																		
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">DESCRIPTION</th> <th style="text-align: right;">QTY</th> <th style="text-align: right;">PRIC</th> <th style="text-align: right;">VALUE</th> </tr> </thead> <tbody> <tr> <td>REAR BUMPER SET MOUNTING PARTS</td> <td style="text-align: right;">1</td> <td style="text-align: right;">33.15</td> <td style="text-align: right;">33.15</td> </tr> <tr> <td>RR BUMPER CARRIER</td> <td style="text-align: right;">1</td> <td style="text-align: right;">424.25</td> <td style="text-align: right;">424.25</td> </tr> <tr> <td>RR BUMPER CTR GUIDE</td> <td style="text-align: right;">1</td> <td style="text-align: right;">31.60</td> <td style="text-align: right;">31.60</td> </tr> <tr> <td>RR BUMPER CTR BOTTOM GUIDE</td> <td style="text-align: right;">1</td> <td style="text-align: right;">61.20</td> <td style="text-align: right;">61.20</td> </tr> <tr> <td>RR BUMPER LH GUIDE</td> <td style="text-align: right;">1</td> <td style="text-align: right;">57.05</td> <td style="text-align: right;">57.05</td> </tr> <tr> <td>RR BUMPER RH GUIDE</td> <td style="text-align: right;">1</td> <td style="text-align: right;">57.05</td> <td style="text-align: right;">57.05</td> </tr> <tr> <td>RR BUMPER INSERT (M)</td> <td style="text-align: right;">1</td> <td style="text-align: right;">158.45</td> <td style="text-align: right;">158.45</td> </tr> <tr> <td>RR BUMPER COVER (M)</td> <td style="text-align: right;">1</td> <td style="text-align: right;">79.70</td> <td style="text-align: right;">79.70</td> </tr> <tr> <td>PDC HOLDER OUTSIDE LH</td> <td style="text-align: right;">1</td> <td style="text-align: right;">12.45</td> <td style="text-align: right;">12.45</td> </tr> <tr> <td>PDC HOLDER OUTSIDE RH</td> <td style="text-align: right;">1</td> <td style="text-align: right;">12.75</td> <td style="text-align: right;">12.75</td> </tr> <tr> <td>PDC HOLDER INSIDE LEFT</td> <td style="text-align: right;">1</td> <td style="text-align: right;">12.80</td> <td style="text-align: right;">12.80</td> </tr> <tr> <td>PDC HOLDER INSIDE RIGHT</td> <td style="text-align: right;">1</td> <td style="text-align: right;">13.10</td> <td style="text-align: right;">13.10</td> </tr> <tr> <td>RR BUMPER (M)</td> <td style="text-align: right;">1</td> <td style="text-align: right;">1,247.70</td> <td style="text-align: right;">1,247.70</td> </tr> <tr> <td>DECOUPLING RING PDC TORQUE CONVERTE</td> <td style="text-align: right;">4</td> <td style="text-align: right;">5.05</td> <td style="text-align: right;">20.20</td> </tr> <tr> <td style="border-top: 1px solid black;">Total Parts :</td> <td colspan="3" style="text-align: right; border-top: 1px solid black;">2,221.45</td> </tr> </tbody> </table>				DESCRIPTION	QTY	PRIC	VALUE	REAR BUMPER SET MOUNTING PARTS	1	33.15	33.15	RR BUMPER CARRIER	1	424.25	424.25	RR BUMPER CTR GUIDE	1	31.60	31.60	RR BUMPER CTR BOTTOM GUIDE	1	61.20	61.20	RR BUMPER LH GUIDE	1	57.05	57.05	RR BUMPER RH GUIDE	1	57.05	57.05	RR BUMPER INSERT (M)	1	158.45	158.45	RR BUMPER COVER (M)	1	79.70	79.70	PDC HOLDER OUTSIDE LH	1	12.45	12.45	PDC HOLDER OUTSIDE RH	1	12.75	12.75	PDC HOLDER INSIDE LEFT	1	12.80	12.80	PDC HOLDER INSIDE RIGHT	1	13.10	13.10	RR BUMPER (M)	1	1,247.70	1,247.70	DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20	Total Parts :	2,221.45		
DESCRIPTION	QTY	PRIC	VALUE																																																																
REAR BUMPER SET MOUNTING PARTS	1	33.15	33.15																																																																
RR BUMPER CARRIER	1	424.25	424.25																																																																
RR BUMPER CTR GUIDE	1	31.60	31.60																																																																
RR BUMPER CTR BOTTOM GUIDE	1	61.20	61.20																																																																
RR BUMPER LH GUIDE	1	57.05	57.05																																																																
RR BUMPER RH GUIDE	1	57.05	57.05																																																																
RR BUMPER INSERT (M)	1	158.45	158.45																																																																
RR BUMPER COVER (M)	1	79.70	79.70																																																																
PDC HOLDER OUTSIDE LH	1	12.45	12.45																																																																
PDC HOLDER OUTSIDE RH	1	12.75	12.75																																																																
PDC HOLDER INSIDE LEFT	1	12.80	12.80																																																																
PDC HOLDER INSIDE RIGHT	1	13.10	13.10																																																																
RR BUMPER (M)	1	1,247.70	1,247.70																																																																
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20																																																																
Total Parts :	2,221.45																																																																		

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
Tel. 63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
Tel. 63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
Fax. 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46213 Page No. : 2 of 2

Date Estimated : 13/03/2018

Prepared By : Kevin Leong Wai Kit

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV4480A	FG90241	28/07/2011	318i/4 (A)	0

Labour 1	:	2,995.00
Parts	:	2,221.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	365.15
Grand Total	:	5,581.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



redefining insurance

NG SOH ENG
19 JALAN SEDAP
SINGAPORE 438275

AXA Insurance Pte Ltd
1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
(65) 6880 4740
customer.care@axa.com.sg
www.axa.com.sg

Renewal

date
11/01/2018

your servicing distributor
SD CONTEGO SERVICES / 00303

your servicing distributor contact
63190588/0589

Policy Schedule

Your SmartDrive Comprehensive Private

Your policy snapshot

Policyholder name
Cover
Period of insurance

NG SOH ENG
Comprehensive
from 28/01/2018 to 27/01/2019 (both dates inclusive)

Policy number
FIN / NRIC

VA1 / GA148014
S12988521D

Premium breakdown

Gross Premium after 20% NCD
7% GST
Final Premium

SGD 1,609.58
SGD 112.67
SGD 1,722.25

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Private Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Loss or Damage
- Legal Liability
- Workshop of Your Choice
- Daily Transport Allowance of \$50 for a maximum of five (5) days
- Medical and dental expenses up to \$500 per person for either you as the driver or your authorised driver and a passenger
- Personal accident benefit of up to \$20,000 for you and your named drivers
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess

Vehicle details

Make & Model of Vehicle	BMW 318i	Year of manufacture	2011
Vehicle registration number	SNV4480A	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1995
Seating capacity (excl driver)	4	Engine number	B413i944N46B20BZ
Off-Peak car	No	Chassis number	WBAPF72060FG90241

Insured's Estimated Market Value
Limitation to use
Finance Loan Company

Market Value at the time of Loss (including accessories and spare parts)
As per Certificate of Insurance
Nil

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess
Windscreen Excess

SGD 1,000.00
SGD 100.00

Drivers details

AXA Insurance Pte Ltd (199903512M)
8 Shenton Way, #24-01, AXA Tower,
Singapore 068811
Customer Centre, #B1-01

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S8615704G**

Name: **TAN JINWEN MARK (CHEN JINWEN)**

Birth Date: **26 May 1986**

Issue Date: **20 Jan 2006**

001394783G




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8615704G



Name

**TAN JINWEN MARK
 (CHEN JINWEN)**

陈锦文

Race

CHINESE

Sex

M

Date of birth

26-05-1986

Country/Place of birth

SINGAPORE




S8615704G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE


Class 3 Motor Cars <= 3000kg with <= 7 passengers exclusive of the driver, and other motor vehicles <= 2500kg

20 Jan 2006



Licence No. S8615704G

NP 428A



NRIC No. S8615704G



Date of issue
27-02-2017

Address

**19 JALAN SEDAP
 SINGAPORE 438275**

57069;