

Not Notarised
 L1 Reg 883006
 Runway After Paint
 5 days

C. S. ONG AUTO PTE. LTD.

Company & GST Reg No.: 201408916W
 10, Ang Mo Kio Ind. Park 2A, #02-16, AMK AutoPoint, Singapore (568047)
 Tel: 6484 1933 | Fax: 6484 1922
 E-Mail: csongauto@yahoo.com.sg

[Signature]
 16/3/18

To: Motor Claims Department,
 MSIG INSURANCE SINGAPORE PTE LTD

Date: 11/03/2018

Accident Involving Vehicles SFN7828M & SJF9553L [Your Insured] on 11/03/2018 @
 1320 Hrs along Junction Of Ang Mo Kio Street 22 & 23.

Estimated Repair Costs For SFN7828M [M/BENZ] Chassis No.: WDB2110412B392839

1 Pc Front Bumper	1480.00	\$ CM 1,850.00	✓
1 Set Front Bumper Clips		\$ na 50.00	✓
1 Pc Front Bumper Lower Grille		\$ D17 86.00	✓
2 Pcs Front Bumper Bracket LH /RH @\$107.00 Each		\$ R 217.00	X
1 Pc Front Bumper RH Nozzel Cover		\$ D17 65.00	✓
1 Pc Front Bumper LH Nozzel Cover		\$ Sn 65.00	X
1 Pc Front Bumper Reinforcement	655.00	\$ Bu 850.00	✓
2 Pcs Front Bumper Side Retainer LH/RH @ \$98.00 per pc		\$ D17 196.00	✓
1 Pc Front Chrome Grille		\$ CM 790.00	✓
1 Pc Front Number Plate Garnish		\$ na 285.00	✓
1 Pc Front Brace Panel		\$ Bu 88.00	✓
1 Pc Front Support Panel Top Garnish		\$ Sn 137.00	X
1 Pc Front Support Panel		\$ R 295.00	X
1 Pc Front Grille Mercedes Logo		\$ na 171.00	✓
2 Pcs Front Headlamp LH and RH @ \$2895.00 per pc	2516 mg cm	\$ 5,790.00	✓
2 Pcs Front Bumper Fog Lamp With Cover RH and LH @ \$365.00 Each	295.	\$ na CM 730.00	✓
1 Pc Front Bumper LH Chrome Moulding		\$ na 135.00	✓
1 Pc Front Bumper RH Chrome Moulding		\$ na 135.00	✓
1 Pc Front Bumper Sponge RH		\$ Sn 75.00	X
1 Pc Front Bumper Sponge LH		\$ CM 75.00	✓
1 Pc Front Bumper Sponge Centre		\$ Sn 80.00	X
1 Pc Front Bonnet		\$ R 2,550.00	X
1 Pc Front Bonnet Mercedes Logo		\$ na 115.00	X
2 Pcs Front Bonnet Hinge LH and RH @ \$140.00 per pc		\$ R 280.00	X
1 Pc Front Bonnet Inner Lock		\$ R 120.00	X
1 Pc Front Towing Cover		\$ D17 85.00	✓
1 Pc Condenser		\$ Sn 1,420.00	X