## MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 6748 4422/ 6745 4422 Fax: 6747- 6720 REG NO 200501102H

AXA Insurance Singapore Pte Ltd Quotation Ashes. 8 Shenton Way : 14.03.2018 DATE # 27-01 VEH NO : SKX5243B Singapore 068811 MODEL : Audi A3 Tel: 6338 - 7288 DOA : 11.03.2018 Fax: 6880 - 4838 YR REF : SGD3672L

(Pls arrange vehicle survey & check liability)

## RE: ESTIMATE FOR ACCIDENT REPAIR SKX5243B (AUDI A3)

<u> </u>	ESTIMATE FOR ACCIDENT REPAIR SKX5243B (AUDI A3)					
<u>Item</u>	<u>Description</u>		Qty		_Amt	
<u>NO</u>	LIST ITEMS					
1	Rear Bumper Dehomed		1		1,619.00	_
2	Rear Bumper Clips		1 set		30.00	
3	Rear Bumper Side Holder - LH & RH		2		114.00	
4	Rear Bumper Reflector - LH & RH 1/1-P		2		72.00	K
5	Rear Bumper Lower Spoiler		1		258.00	
6	Rear Bumper Reinforcement But		1		501.00	
7	Rear Bumper Tow Cover *** ***	2788	1		38.00	X
8	Bootlid Revi	2658,10.	1		2,310.00	X
9	Bootlid Lock > PC	2658,10	1		170.00	X
10	Audi Logo )		1		108.00	/
11	A3 Wording		1		83.00	
12	TFSI Wording \		1		85.00	
				\$	5,388.00	-
	Less 10%			(538.80)		
				\$	4,849.20	-
	S/Nett items				to Militaria to conta Administrativa	
1	Reverse Sensor 2 pilles dange	430.	4	\$	860.00	430
				\$	860.00	-1.
	Т	otal Parts		\$	5,709.20	•
	LABOUR CHARGE					
1	To knocking & pull out rear portion & renew about	ove parts			600	400
2	To putty & spray up paint works		*		600	450

## RE: **ESTIMATE FOR ACCIDENT REPAIR SKX5243B (AUDI A3)**

3	To underseal		/00 X
4	To check wiring		\$ 30.00
5	To replace reverse sensor		\$ 120,00 60
6	To transfer t <del>ailgate</del> fittings		\$ 150.00 🗶
7	postom dichogolic lest. To re <del>move rear windscreen</del>	90	\$ 12000 /00.
8	To remove rear upholstery	1 -	\$ 150.00 🔀
			\$ 570.00
		Grand Total	\$ 6,279.20

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

bolel: 407810 1/51 3250 other

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: