

長隆汽車服務

CHIANG LEONG MOTOR VEHICLE SPRAY PAINTING

10 Ang Mo Kio Industrial Park 2A #03-15 AMK Autopoint Singapore 568047

Tel : 9662 0782 Fax : 6483 1392

Business regn no : 204106-00A

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd

Date : 13-Mar-18

Vehicle No : GBE4480X

Make/Model: Nissan NV350

Attn: Motor Claims Dept

Qty	Parts And Labour Detail	\$
<u>List Items:</u>		
1	tailgate	1872.40
1	tailgate lock	187.60
1	tailgate weather strip	233.20
1	tailgate Nissan logo	59.40
1	tailgate NV350 emblem	46.70
1	tailgate Urvan emblem	46.70
1	tail lamp	239.80
1	end panel	443.20
1	panel garnish	256.30
1	rear bumper cover	696.50
2	rear bumper bracket	102.40
8	rear bumper clips	36.00
2	rear bumper side retainer	82.40
		4302.60
	Less 10%	430.26
		3872.34
<u>S/Nett Items:</u>		
1	windscreen sealant	100.00
1	reverse sensor	250.00
1	'70km/h' sticker	15.00
		365.00
	Parts Total	4237.34
<u>Labour-charges</u>		
	To remove damaged parts and attachments, panelbeat rear floorboard panel, weld rear end panel, right side fender panel and replace/refit new parts	1600.00
	To transfer tailgate internal components	100.00
	To remove and refit rear windscreen	200.00
	To supply and install digital print sticker	750.00
	To check electrical wiring and reverse sensor function	40.00
	To primer, putty and spray painting on affected areas	1200.00
	To apply anti-rust and sealant	120.00
		4010.00
	Total	8247.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
Kenneth
HP: 96910663
11 Sep 18?
Resurvey After Paint
6 days