

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4301U  
 Ref. No : TAX/03/18/2060  
 Reg. Date : 14/12/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : ANG AH HOCK  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 13/03/2018 11:00:00 AM  
 Accident Reported Date / Time : 13/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024095030  
 Special Instruction to ARC, if any :  
 SDV67U - AXA  
 Prepared Date : 13/03/2018 03:01:40 PM



Sebastian.  
 14/3/18.  
 - Part by part repair.  
 - Question Mark Item  
 Photo.  
 - Photo before Paint

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU303576761

Mileage

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                              | Quotation from ARC       | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges         | : 338.00                 | 0.00                                |
| Total Spray Painting Charges | : 738.00                 | 0.00                                |
| Total Material Charges       | : 1,702.10               | 1,702.10                            |
| Other Charges                | : 260.00                 | 0.00                                |
| <b>TOTAL</b>                 | <b>: 3,038.10</b>        | <b>0.00</b>                         |
| <b>Lum Sum Total</b>         | <b>: 0.00</b>            | <b>0.00</b>                         |
| No. of Repair Days           | : 3.00                   | 0.00                                |
| Prepared / Adjusted By       | :                        | 2 days                              |
| Arc / Surveyor Sign Off Date | : 13/03/2018 05:16:59 PM | 01/01/1900 12:00:00 AM              |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/03/2018 05:15:00 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

|                       |                                      |
|-----------------------|--------------------------------------|
| Quotation No :        | Invoice No :                         |
| Quotation Date :      | Invoice Date :                       |
| Invoice Amount : 0.00 | Prepared Date : 3/13/2018 5:16:44 PM |

**Part 1 - Labour Works**

| Job Scope              | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------|--------------------|-------------------------------------|
| TO REPAIR REAR PORTION | 338.00             | 0.00 200                            |
| <b>Total Labour</b>    | <b>338.00</b>      | <b>0.00</b>                         |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO REPSRAY REAR BUMPER                          | 378.00             | 0.00 200                            |
| TO RESPRAY FILLER RR BUMPER RH                  | 180.00             | 0.00 50                             |
| TO RESPRAY BUMPER BEAM                          | 180.00             | 0.00 ?                              |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>738.00</b>      | <b>0.00</b>                         |

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-----------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION     | 80.00              | 0.00 X                              |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00             | 0.00 30                             |
| TO WASH AND VACUUM                      | 60.00              | 0.00 X                              |
| <b>Total Other Costs</b>                | <b>260.00</b>      | <b>0.00</b>                         |

**Part 4 - Spare Parts / Material Usage**

| Part Number                        | Portion | Stock No | Part Name                    | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved       | Photos Attached |
|------------------------------------|---------|----------|------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------------|-----------------|
| 5215947913                         |         |          | COVER, RR BUMPER ASSY        | 1   | 423.90          | 25.00        | 317.92           | Replace            | Replace <i>R</i>        | No              |
| 5216116010                         |         |          | CLIPS PIECE, FRT & RR BUMPER | 10  | 1.50            | 25.00        | 11.25            | Replace            | Replace <i>✓ NEC</i>    | No              |
| 5246247030                         |         |          | PAD, RR BUMPER, RH & LH , 1  | 2   | 3.80            | 25.00        | 5.70             | Replace            | Replace <i>?</i>        | No              |
| 5246247020                         |         |          | PAD, RR BUMPER, RH & LH , 2  | 2   | 3.80            | 25.00        | 5.70             | Replace            | Replace <i>?</i>        | No              |
| 5246247010                         |         |          | PAD, RR BUMPER, RH & LH , 3  | 2   | 3.80            | 25.00        | 5.70             | Replace            | Replace <i>?</i>        | No              |
| 5219147030                         |         |          | SEAL, RR BUMPER ARM, RH & LH | 2   | 11.00           | 25.00        | 16.50            | Replace            | Replace <i>?</i>        | No              |
|                                    |         |          | SENSOR REVERSE               | 1   | 180.00          | 0.00         | 180.00           | Replace            | Replace <i>?</i>        | No              |
|                                    |         |          | PIXEL STICKER                | 2   | 60.00           | 0.00         | 120.00           | Replace            | Replace <i>✓ NEC</i>    | No              |
| 5256547900                         |         |          | FILLER, RR BUMPER , RH       | 1   | 119.90          | 25.00        | 89.92            | Replace            | Replace <i>✓ CRK</i>    | No              |
| 5259147050                         |         |          | SEAL, RR BUMPER , RH         | 1   | 85.20           | 25.00        | 63.90            | Replace            | Replace <i>?</i>        | No              |
| 5257547040                         |         |          | RETAINER, RR BUMPER, RH      | 1   | 112.70          | 25.00        | 84.52            | Replace            | Replace <i>?</i>        | No              |
| 5202347030                         |         |          | REAR BUMPER REINFORCEMENT    | 1   | 318.80          | 25.00        | 239.10           | Replace            | Replace <i>?</i>        | No              |
| 5245347010                         |         |          | GUARD, RR BUMPER, LOWER      | 1   | 558.30          | 25.00        | 418.72           | Replace            | Replace <i>✓ let</i>    | No              |
| 5216947020                         |         |          | COVER, GUARD RR BUMPER LOWER | 1   | 14.80           | 25.00        | 11.10            | Replace            | Replace <i>✓ Deform</i> | No              |
| 5246147010                         |         |          | PAD, RR BUMPER, CTR          | 3   | 2.20            | 25.00        | 4.95             | Replace            | Replace <i>?</i>        | No              |
| 5839847050                         |         |          | COVER, REAR FLOOR UNDER , RH | 1   | 169.50          | 25.00        | 127.12           | Replace            | Replace <i>?</i>        | No              |
| <b>TOTAL MATERIALS</b>             |         |          |                              |     |                 |              |                  | <b>1,702.13</b>    | <b>1,702.10</b>         |                 |
| <b>TOTAL MATERIALS(Discounted)</b> |         |          |                              |     |                 |              |                  | <b>1,702.10</b>    | <b>1,702.10</b>         |                 |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number                          | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|--------------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| <b>TOTAL SUPPLEMENTARY MATERIALS</b> |         |           |     |                 |              |                  |           |                |          |