

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7084B

DATE 13/3/2018 10:13

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door Mirror (RH) (LH) ✓			\$ 980.50
	SUB TOTAL			\$ 980.50
	LESS 20%			\$ 196.10
	DISCOUNTED TOTAL			\$ 784.40
	Labour Charge			\$ 50
	Panel Beating			\$ 200.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	TOTAL LABOUR			\$ 450.00
	ESTIMATE TOTAL			\$ 1,234.40
Kelvin LKK 13/3/18 1025hrs 1 Day PIP Before Paint photo				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third parties • No illegal • Supplier is subject Acknowledged: Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				