

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ernest Tay

Date: 16 Mar 2018

Preliminary Advice

Insured Vehicle No	: SHD124K		
TP Vehicle No	: SJQ4001M	Accident Date	: 13/03/2018
Make	: TOYOTA PRIUS	Assignment Date	: 14/03/2018
Date of Inspection	: 14/03/2018	Est. Duration of Repair	: 4 days
Inspection At	: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...N/S front and body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,785.50
Revised Amount	:S\$	2,650.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,650.00
Lump Sum Repair	:S\$	2,650.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.