

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

13/03/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8A - SJQ4001M

1pc	front LH fender
1pc	front LH fender "HYBRID" emblem
1pc	front LH door
1pc	front LH door moulding
1pc	front LH door glass
1pc	front LH side mirror
1pc	front LH side mirror cover

B1	\$	591.60	✓
D1	\$	61.75	✓
B1	\$	972.45	✓
Ad/Scr	\$	181.75	✓
Cr	\$	381.75	✓
B20	\$	581.85	✓
M1	\$	182.85	✓

less 25%

\$	2,954.00
\$	738.50
\$	2,215.50

remove & refit front LH door glass
wiring
tuffkote
spray painting
labour charges
Total

\$	60.00	✓
\$	50.00	201
\$	60.00	✓
\$	700.00	5001
\$	700.00	4801
\$	3,785.50	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
L1 Rn B26501
Running After Painting
4 days

BxA
(LKK)