

ASS. REC. BY:

REF:

CS/MS(718004913 / Amber

Special Instruction:

SUPERVISOR: Adrian **ASSIGNMENT (Office)**

From (Person):

Lionel Tan

of

MSLH

Date/Time:

15/3/2018 832am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 2709X

Insured:

YN 1061Y

at Workshop m/s

Torgue 5

Tel:

64524457 | 9147 8841

of

8 Kakt Bukit Ave 4 #01-50

Policy No:

B38669991 MKC

Claim No:

552213

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/3/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wpi

H.O.D. Endorsement:

Date/Time:

15/3/2018 956am

Person Contacted:

StephanieVehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 2709X - NA / FWD17017867 / 13DIA: 120917YN 1061Y - X16/3/18Informed Lionel pending est from repairer by merimen31/8/18@ 11:44am Stephanie said pending Adrian finalise19/11/18@ 2:55pm Peach said vehicle completed repair

ASS. REC. BY: Adrian King

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: **Yes** or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes** or No

Est. Repairs: \_\_\_\_\_ days Res.: **Yes** or No

Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or No

**CA / REV / REP. / 24 HRS**

Vehicle: **IN / OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBF2709X Yr Regn: 2016 August

Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Carter c.c 2998

Colour: White A/C: **Insured / Std / NI / NA**

Sp. Reading: 80796 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: FEA01BA20268

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or

Brake: **Inorder** / Jammed / Leaked / Burnt of

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**

**TOYO / YOKO** or Green Max

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 15/03/18

Survey held at Torque 5

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or

The **U/C / Chassis frame / Body Structure** affected due to collision.

| Date / Time    | Action / Instruction  |
|----------------|---|
|                | <u>TP MS&amp;G.</u>   |
|                | <u>To check consistency on roof panel and front windscreen damages.</u> |
| <u>31/1/19</u> | <u>@10:36am Stephine will email us finalised</u>                        |
| <u>17/6/19</u> | <u>Adrian confirmed LS \$ 6500 (Recd 32,959.50, 8370)</u>               |
| <u>18/6/19</u> | <u>Sand preli revised via merimen</u>                                   |

RECEIVED 10 JUN 2019

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) 18/6 - typist

Report Format: Merimen

Lump Sum / I.B.I: (\$ 6500/2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: 250

Transportation: \_\_\_\_\_

S + RS: SI

Photos \_\_\_\_\_

Others 11

TOTAL

261



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                          |   |
|--|--|--------------------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD   |  | Ref : CS/MSG18004913/Avb |   |
| 16 RAFFLES QUAY<br>#24-01 HONG LEONG BLDG SINGAPORE 048581   |  | Date : 15-03-2018        |  |
|  |  | Code : MSG               |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                          |   |
| Insured Veh.   | YN 1061Y   | Veh. Inspected           | GBF 2709X   |
| Policy No.   | B28669991MKC   | Coverage (\$)            | 0.00  |
| Claim No.  | 552213   | Excess (\$)              | 0.00  |
| Assign From  | MERIMEN (LIONEL TAN)   | Assign Date              | 15/03/2018  |
| 2. Vehicle Particulars & Condition   |  |                          |   |
| Make & Model   |  | c.c                      | 0   |
| Engine No.   | HIDDEN   | Year of Reg.             |   |
| Chassis No.  |  | Colour                   |   |
| Odometer   | -  | Steering                 |   |
| Brakes   |  | Modification             |   |
| General  |  |                          |   |
| 3. Conditions of Tyres   |  |                          |   |
|  | Size   | Make                     | Balance   |
| R/H Front Tyre   |  |                          | mm  |
| L/H Front Tyre   |  |                          | mm  |
| R/H Rear Tyre  |  |                          | mm  |
| L/H Rear Tyre  |  |                          | mm  |
| 4. Description of Damages  |  |                          |   |
|  |  |                          |   |
| 5. General Information   |  |                          |   |
| Accident Date  | 13/03/2018   | Inspection Date          | 15/03/2018  |
| Survey held at   | TORQUE 5 PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#01-50 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                          |   |
| 5a. Remarks  |  |                          |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                          |   |

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |             |               |  |         |               |             |  |
|--------------------------|-------------|---------------|--|---------|---------------|-------------|--|
| Case                     | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status   |
| Main                     | 13 Mar 2018 |               | 15 Mar 2018<br>08:32<br><a href="#">Assign</a> |         |               |             | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

|                                    |   |                               |   |
|------------------------------------|---|-------------------------------|---|
| <b>Insured:</b>                    | CENTURY GLOBAL PTE. LTD., Co. Reg. No.: 200208462M, Tel: +6596874075  |                               |   |
| <b>Main Claimant:</b>              | FORWARDERS & DELIVERY AGENCY SINGAPORE (PTE). LTD., Co. Reg. No.: 200708297N  |                               |   |
| <b>Vehicle Reg. No.:</b>           | GBF2709X  | <b>Date of Loss:</b>          | 13/03/2018 10:00 - :59  |
| <b>Claim Type:</b>                 | TP / 552213   | <b>Policy/Cover Note No.:</b> | B28669991MKC (Comprehensive)<br>Coverage: 03/02/2018 - 02/02/2019 |
| <b>Vehicle Reg. No. (Insured):</b> | YN1061Y   | <b>Policy No. (Claimant):</b> |   |
|                                    |   | <b>Excess:</b>                | S\$1,000.00   |
| <b>Repairer:</b>                   | Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457                          |                               |   |
| <b>Handling Insurer:</b>           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]           |                               |   |
| <b>Adjuster:</b>                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/03/2018]  |                               |   |
| <b>Driver/Custodian (Insured):</b> | NASIRUDEEN BIN SHAUL (54 / Male), NRIC: S1595741G, Tel: +6596874075   |                               |   |
| <b>Adj Asg. Remarks:</b>           | Please appoint MR ADRIAN LING to conduct the survey . Kindly contact MS STEPHANIE TEO @ 6452 44757 to arrange for survey. |                               |   |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

---

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

13032018 @ 9:56am  
Stephanie veh in  
Ti

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

|   |  |
|---|--|
| <b>To:</b> MSIG Insurance (Singapore) Pte. Ltd.<br>4 Shenton Way<br>#21-01 SGX Centre 2<br>Singapore 068807 | <b>From:</b> LKK Auto Consultants Pte Ltd<br>51 Ubi Ave 1 #01-25<br>Paya Ubi Industrial Park<br>Singapore 408933 |
| <b>Attn:</b> Lionel Tan Tian Pei  | <b>Date:</b> 18 Jun 2019   |
| <b><u>Preliminary Advice</u></b>  |  |

|   |                                     |
|---|-------------------------------------|
| <b>Insured Vehicle No</b> : YN1061Y   |                                     |
| <b>TP Vehicle No</b> : GBF2709X   | <b>Accident Date</b> : 13/03/2018   |
| <b>Make</b> : MITSUBISHI CANTER   | <b>Assignment Date</b> : 15/03/2018 |
| <b>Date of Inspection</b> : 15/03/2018  | <b>Est. Duration of Repair</b> : 7  |
| <b>Inspection At</b> : TORQUE 5 PTE LTD (KAKI BUKIT)<br>NO. 8 KAKI BUKIT AVE 4,, #01-50<br>SINGAPORE 415875 |                                     |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

|                                 |             |  |                     |
|---------------------------------|-------------|--|---------------------|
|                                 |             |  |                     |
| Repairer's Estimate (Gross)     | :S\$        |  | 39,459.50           |
| Revised Amount                  | :S\$        |  | 6,500.00 (lump sum) |
| Check Items (Estimated)         | :S\$        |  | 0.00                |
| <b>Total</b>                    | <b>:S\$</b> |  | <b>6,500.00</b>     |
|                                 |             |  |                     |
| Lump Sum Repair                 | :S\$        |  |                     |
|                                 |             |  |                     |
| <b>Total Loss Consideration</b> |             |  |                     |
|                                 |             |  |                     |
| New for Old Value               | :S\$        |  |                     |
| Pre-Accident Value              | :S\$        |  |                     |
| COE / PARF Rebate               | :S\$        |  |                     |
| Salvage Value                   | :S\$        |  |                     |
| Margin for Repair               | :S\$        |  |                     |

### Remarks

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## View Sent Message

This mail is associated with :

**\*GBF2709X (552213)**  
**[YN1061Y]**

TP  
FORWARDERS & DELIVERY AGENCY SINGAPORE (PTE). LTD.  
Mar 13 2018 10:00AM  
[CENTURY GLOBAL PTE. LTD.]  
Torque 5 Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **16/03/2018 08:53 AM**.  
**To** MSIG\_LTTP  
**Subject** **PENDING ESTIMATE FROM REPAIRER**

Dear Lionel,

Please be informed that we have inspected the vehicle GBF 2709X on 15/3/2018.

We are pending estimate from repairer.

Best Regards,  
Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

**Personal Particulars of Owner & Driver (Vehicle A)**

Date of Accident: 13 / 03 / 2018 (dd/mm/yy) Time of Accident: 10 : 55 (24-HR-FORMAT)  
Vehicle No. : 6BF2709K Vehicle Make & Model: Mitsubishi Fuso  
Exact location of Accident: Chun Bee Ave twds Quality Rd  
Policyholder's Name / IC No. : Forwarders & Delivery Agency Singapore Pte Ltd  
Driver's Name / IC No. : Nor Zaidi Bin Nor Zahid / S9534610C (As Above)   
Driver's Contact No. : 8742 5564 Company Contact No: \_\_\_\_\_  
Driver's Address: 338 Woodlands Ave 1 #01-569 S730338  
Insurance Company: \_\_\_\_\_ Email address (if any): \_\_\_\_\_

**Relationship between Owner & Driver:** (Please **CIRCLE** one only)  
Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: \_\_\_\_\_

**What do you wish to claim? (Please TICK one only)**

Own Insurance /  Other Vehicle (The one you want to claim against) /  Reporting (For Record Purpose)

**Exact purpose for which the vehicle was being used at time of accident?**

Private use /  Work purpose

**Occupation (nature of job)**  Indoor /  Outdoor

**No. of Passengers (Including Driver):** 01

**Weather condition & Road conditions? (On the day of accident)**

Clear & Dry /  Raining & Wet /  After-Rain & Wet /  Drizzling & Wet / Others: \_\_\_\_\_

**Was there any video captured by your Car Camera?**  Yes /  No

**Any Injuries:**  Yes /  No (If YES) Injured Person's Name: \_\_\_\_\_

Injuries Sustain: \_\_\_\_\_ Injured Person in Which Vehicle: \_\_\_\_\_

**Police Report filed:**  Yes /  No (If YES) Which Police Station: \_\_\_\_\_

**The Other Party(s) Details:**

1. Driver's Name / IC No: \_\_\_\_\_ Vehicle No: YN1061Y

Driver's Contact No: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

2. Driver's Name / IC No: \_\_\_\_\_ Vehicle No: \_\_\_\_\_

Driver's Contact No: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

\*Independent Witness (If Any): \_\_\_\_\_ Contact No: \_\_\_\_\_

Preferred Workshop Name: \_\_\_\_\_ Contact No: \_\_\_\_\_

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On the stated date and time, I vehicle 'A' was travelling on the stated venue. I was travelling straight in my lane, suddenly vehicle 'B' came out at a very fast speed from chin Bee Ave did not stop had collided onto my entire vehicle right portion. I wish to state that my speed were within the speed limit, I tried to avoid him however his vehicle still collided onto mine.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed



Supplementary item(s) must be resurveyed and final approval from resurveyor.

Acknowledged by Repairer  
Signature:  
Date:

### Torque 5 Pte Ltd

No. 8 Kaki Bukit, Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

### ESTIMATION REPORT

Estimation No. : E18030043  
DOA : 13/03/2018

Vehicle No : GBF2709X  
Make & Model : MITSUBISHI, CANTER FEA01BR1SDEB (CBU), FEA01BA20268  
Year of Manufacture : 2016

| No                         | Description  | Qty  | U/P  | Amt            |
|----------------------------|--|------|------|----------------|
| <b>Section: List Items</b> |  |      |      |                |
| 1                          | Roof <i>Repair</i>                                 | 1.00 | 0.00 | 0.00 *         |
| 2                          | Front windscreen <i>cracked</i>                    | 1.00 | 0.00 | 0.00 - 1300.00 |
| 3                          | Front windscreen moulding <i>cut</i>               | 1.00 | 0.00 | 0.00 - 472.80  |
| 4                          | Side mirror assy (LH) <i>new</i>                   | 1.00 | 0.00 | 0.00 + 233.00  |
| 5                          | Side mirror cover (LH) <i>cut</i>                  | 1.00 | 0.00 | 0.00 - 30.00   |
| 6                          | Side mirror <sup>stay</sup> panel (LH) <i>Best</i> | 1.00 | 0.00 | 0.00 - 150.00  |
| 7                          | Signal lamp (LH) <i>cracked</i>                    | 1.00 | 0.00 | 0.00 - 381.70  |
| 8                          | Signal lamp clip (LH) <i>new</i>                   | 1.00 | 0.00 | 0.00 + 10.00   |
| 9                          | Head lamp (LH) <i>7102 new</i>                     | 1.00 | 0.00 | 0.00 - 699.20  |
| 10                         | Head lamp clip (LH) <i>new</i>                     | 1.00 | 0.00 | 0.00 + 10.00   |
| 11                         | Front bumper <i>cut new</i>                        | 1.00 | 0.00 | 0.00 - 790.00  |
| 12                         | Front bumper clip <i>new</i>                       | 1.00 | 0.00 | 0.00 + 10.00   |
| 13                         | Front bumper retainer (LH) <i>new</i>              | 1.00 | 0.00 | 0.00 + 73.60   |
| 14                         | Front bumper retainer (RH) <i>new</i>              | 1.00 | 0.00 | 0.00 + 73.60   |
| 15                         | Door pillar 'A' <i>Repair Dented</i>               | 1.00 | 0.00 | 0.00 - 791.80  |
| 16                         | Front door (LH) <i>dented</i>                      | 1.00 | 0.00 | 0.00 - 1385.20 |
| 17                         | Front door hinge-up (LH) <i>new</i>                | 1.00 | 0.00 | 0.00 + 191.50  |
| 18                         | Front door hinge-down (LH) <i>new</i>              | 1.00 | 0.00 | 0.00 + 191.50  |
| 19                         | Front door weather strip (LH) <i>new</i>           | 1.00 | 0.00 | 0.00 + 271.70  |
| 20                         | Front door inner weather strip (LH) <i>new</i>     | 1.00 | 0.00 | 0.00 + 183.60  |
| 21                         | Front door lock (LH) <i>new</i>                    | 1.00 | 0.00 | 0.00 - 281.70  |
| 22                         | Front door window moulding (LH) <i>new</i>         | 1.00 | 0.00 | 0.00 + 102.20  |
| 23                         | Front door window garnish (LH) <i>new</i>          | 1.00 | 0.00 | 0.00 + 98.30   |
| 24                         | Front door power window gear (LH) <i>new</i>       | 1.00 | 0.00 | 0.00 + 316.70  |
| 25                         | Front door power window motor (LH) <i>new</i>      | 1.00 | 0.00 | 0.00 + 423.60  |

Continue on next page...



**Torque 5 Pte Ltd**  
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

**ESTIMATION REPORT**

Vehicle No : GBF2709X  
 Make & Model : MITSUBISHI,CANTER FEA01BR1SDEB (CBU),FEA01BA20268  
 Year of Manufacture : 2016

Estimation No. : E18030043  
 DOA : 13/03/2018

| No | Description                            | Qty  | U/P  | Amt                       |
|----|--|------|------|---------------------------|
| 26 | Front door step garnish (LH) <i>mm</i> | 1.00 | 0.00 | 0.00                      |
| 27 | Front door arch garnish (LH) <i>mm</i> | 1.00 | 0.00 | 0.00                      |
| 28 | Door pillar 'B' <i>eye</i>             | 1.00 | 0.00 | 0.00                      |
|    | <i>Corner Panel LH behind 506-70</i>   |      |      | Amt S\$ 0.00              |
|    |  |      |      | Discount (0.00%) S\$ 0.00 |
|    |  |      |      | Subtotal S\$ 0.00         |

*Handwritten notes: 189.90, 210.70, 630.50, 10,009.50*

**Section: Special Nett Items**

|    |  |      |                      |                           |
|----|--|------|----------------------|---------------------------|
| 29 | Front door sticker - company details (LH) <i>mm</i>          | 1.00 | 40.00                | 40.00                     |
| 30 | Front door sticker - DUONIC (LH) <i>mm</i>                   | 1.00 | 50.00                | 50.00                     |
| 31 | Front door window sticker (LH) <i>mm</i>                     | 1.00 | 80.00                | 80.00                     |
| 32 | Rear <del>bumper</del> <i>Fridge</i> Panel LH. <i>anted.</i> | 1.00 | <del>18,000.00</del> | <del>18,000.00</del>      |
|    | <i>Rear Box Rear Fridge Door LH. <del>anted</del> 5000</i>   |      |                      | Amt S\$ 18,170.00         |
|    |  |      |                      | Discount (0.00%) S\$ 0.00 |
|    |  |      |                      | Subtotal S\$ 18,170.00    |

*Handwritten notes: 1630, 4500, 1600*

**Section: Labour Items**

|    |  |      |          |          |
|----|--|------|----------|----------|
| 33 | To R&R accident affected areas             | 1.00 | 2,500.00 | 2,500.00 |
| 34 | To putty & respray accident affected areas | 1.00 | 1,300.00 | 1,300.00 |
| 35 | To rust proof accident affected areas      | 1.00 | 120.00   | 120.00   |
| 36 | To R&R rear cooler box                     | 1.00 | 2,000.00 | 2,000.00 |
| 37 | To R&R front door mechanism                | 1.00 | 80.00    | 80.00    |
| 38 | To check for water seepage                 | 1.00 | 100.00   | 100.00   |
| 39 | To do wheel alignment                      | 1.00 | 180.00   | 180.00   |

*Handwritten notes: 2740, 400, 60*

*Ps 5220.70 - 25%  
 = 3915.53  
 EN: 4580.00*

*Adrian Lij  
 1/3 15/03/19*

Amt S\$ 6,280.00  
 Discount (0.00%) S\$ 0.00  
 Subtotal S\$ 6,280.00

*L= 2240.00  
 10735.53*

*07 Days.*

List Items Subtotal S\$ 0.00  
 Special Nett Items S\$  
 Subtotal 18,170.00  
 Labour Items Subtotal S\$ 6,280.00  
 Total S\$ 24,450.00

*+ 4/5 @ 2590 e  
 7 repair days*

*total 813365 39,459.50*

*2/3 6.5K*

*34999.50*

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |             |   |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 13 Mar 2018 |               | 15 Mar 2018<br>08:32<br><a href="#">Edit Adj Rpt</a> | <b>S\$6,500.00</b><br><a href="#">Edit Estimates</a> | <b>S\$6,500.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS  |   | [Created by insurer]   |            |         |         |             |              |            |       |
|--|---|--|------------|---------|---------|-------------|--------------|------------|-------|
| Insured:   | CENTURY GLOBAL PTE. LTD., Co. Reg. No.: 200208462M, Tel: +6596874075  |  |            |         |         |             |              |            |       |
| Main Claimant:   | FORWARDERS & DELIVERY AGENCY SINGAPORE (PTE). LTD., Co. Reg. No.: 200708297N  |  |            |         |         |             |              |            |       |
| Vehicle Reg. No.:  | GBF2709X  | Date of Loss: 13/03/2018 10:00 - :59<br>[18 Months and 16 Days From LTA Reg Date (Man Yr)] |            |         |         |             |              |            |       |
| Claim Type:  | TP / 552213   | Policy/Cover Note No.: B28669991MKC (Comprehensive)<br>Coverage: 03/02/2018 - 02/02/2019   |            |         |         |             |              |            |       |
| Vehicle Reg. No. (Insured):  | YN1061Y   | Policy No. (Claimant):<br>Excess: S\$1,000.00  |            |         |         |             |              |            |       |
| Repairer:  | Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457                          |  |            |         |         |             |              |            |       |
| Handling Insurer:  | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]           |  |            |         |         |             |              |            |       |
| Adjuster:  | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/04/2018]         |  |            |         |         |             |              |            |       |
| Driver/Custodian (Insured):  | NASIRUDEEN BIN SHAUL (54 / Male) , NRIC: S1595741G, Tel: +6596874075 Email:   |  |            |         |         |             |              |            |       |
| Adj Asg. Remarks:  | Please appoint MR ADRIAN LING to conduct the survey . Kindly contact MS STEPHANIE TEO @ 6452 44757 to arrange for survey. |  |            |         |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>   |   |  |            |         |         |             |              |            |       |
| There are no mail for this case.   |   |  |            |         |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |   |  |            |         |         |             |              |            |       |
| Due Date   | Priority  | Type   | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results.  |   |  |            |         |         |             |              |            |       |

## Claim Documents

\*GBF2709X (552213)

[YN1061Y]

TP

**FORWARDERS & DELIVERY AGENCY SINGAPORE (PTE). LTD.**

Mar 13 2018 10:00AM

[CENTURY GLOBAL PTE. LTD.]

Torque 5 Pte Ltd

| Upload Documents          |                 |   | Upload Photos |  |  | Compose New Letter |           |          | View                                | View in Browser |                                     |
|---------------------------|-----------------|---|---------------|--|--|--------------------|-----------|----------|-------------------------------------|-----------------|-------------------------------------|
| <b>Assessment Reports</b> |                 |   |               |  |  |                    |           |          |                                     | 1 per page      | <input checked="" type="checkbox"/> |
| No                        | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ)   |               |  |  |                    | Thumbnail | Print    |                                     |                 |                                     |
| 1                         | 14/03/18 13:23  | <b>Accident Statement</b><br>From:SC - Reg. No: YN1061Y, Claimant: CENTURY GLOBAL PTE LTD |               |  |  |                    |           | Load HTM | <input type="checkbox"/>            |                 |                                     |
| No                        | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)   |               |  |  |                    | Thumbnail | Print    |                                     |                 |                                     |
| 1                         | 18/06/19 13:59  | <b>Adjuster Immediate Advice</b>  |               |  |  |                    |           | Load HTM | <input type="checkbox"/>            |                 |                                     |
| <b>Photos/Images</b>      |                 |   |               |  |  |                    |           |          |                                     | 3 per page      | <input checked="" type="checkbox"/> |
| No                        | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)   |               |  |  |                    | Thumbnail | Print    |                                     |                 |                                     |
| 1                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 2                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 3                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 4                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 5                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 6                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 7                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 8                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 9                         | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 10                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 11                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 12                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 13                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 14                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 15                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 16                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 17                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 18                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 19                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 20                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 21                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 22                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 23                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 24                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 25                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 26                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 27                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 28                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 29                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 30                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 31                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 32                        | 16/03/18 08:38  | <b>General View</b>   |               |  |  |                    |           | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |

| Assessment Reports |                |   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|---|------------|-------------------------------------|
| No                 | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail  | Print                               |
|                    |                |   |            | <input checked="" type="checkbox"/> |
| 33                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 34                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 35                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 16/03/18 08:38 | General View                              | Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 17/06/19 17:53 | Reinspection Photo                        | Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 17/06/19 17:53 | Reinspection Photo                        | Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 17/06/19 17:53 | Reinspection Photo                        | Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 17/06/19 17:53 | Reinspection Photo                        | Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 17/06/19 17:53 | Reinspection Photo                        | Load JPG   | <input checked="" type="checkbox"/> |

| Documentation |                |   | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|---|------------|-------------------------------------|
| No            | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)   | Thumbnail  | Print                               |
| 1             | 14/03/18 13:23 | <b>TPD GBF2709X - GIA REPORT</b><br>From: SC - Reg. No: YN1061Y, Claimant: CENTURY GLOBAL PTE LTD | Load PDF   |                                     |
| 2             | 15/03/18 08:33 | <b>TPD GBF2709X - PRI</b>   | Load PDF   |                                     |

### Documents Checklist

| DOCUMENTS CHECKLIST   | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured.  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  |       |      |       |
|   |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br>Note: Remarks are private unless you show it to other parties. |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004913/AGVBE2

Date: 21/06/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28669991MKC  
 Claimant Vehicle No: GBF2709X Insured Vehicle No: YN1061Y  
 Date of Loss: 13/03/2018 Nature of Claim: TP Claim No: 552213

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **GBF2709X**  
 Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR1SDEB (M) Engine No: 4P10C22928  
 Reg. Date: 25/08/2016 (Man. Year: 2016) Chassis No: FEA01BA20268  
 Colour: White Odometer: 80796 km  
 Engine Capacity: 2998 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C  
 Front Left Side: GREEN-MAX 6 mm Rear Left Side: GREEN-MAX 6 mm  
 Front Right Side: GREEN-MAX 6 mm Rear Right Side: GREEN-MAX 6 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|--|------------------|-----------------|------------------|--------------|
| Parts                                    | 28,679.50        | 5,443.65        | 23,235.85        | 81.02        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 6,280.00         | 2,740.00        | 3,540.00         | 56.37        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>34,959.50</b> | <b>8,183.65</b> | <b>26,775.85</b> | <b>76.59</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>6,500.00</b> |                  |              |
| (S\$)                                    | 34,959.50        | 6,500.00        | 28,459.50        | 81.41        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>2,447.17</b>  | <b>455.00</b>   | <b>1,992.17</b>  | <b>81.41</b> |
| <b>Nett Amount (S\$)</b>                 | <b>37,406.67</b> | <b>6,955.00</b> | <b>30,451.67</b> | <b>81.41</b> |

## INSPECTION

Date of Assignment: 15/03/2018  
 Date Inspected: 15/03/2018 Inspected At: Torque 5 Pte Ltd (Kaki Bukit)  
 No. 8 Kaki Bukit Ave 4,, #01-50  
 Singapore 415875  
 Estimated Period of Repair: 7.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

|                      |  |  |
|----------------------|--|--|
| <b>Reference</b>     |  |  |
| <b>Part Source:</b>  | (Last Synchronised: 21 Jun 2019)   |  |
| <b>Parts:</b>        | N/A  | mitsubishi canter 3.0 D FEA01BR1SDEB (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBF2709X)  |  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

## Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's   | Amount       |
|-----|-----|----------|--|---------------|--------------|--------------|
| 1   | 1   |          | *ROOF (NPA)                            | Repair        | 0.00 F       | *- FL        |
| 2   | 1   |          | *FRONT WINDSCREEN                      | Cracked       | 1,300.00 F   | *1,300.00 FL |
| 3   | 1   |          | *FRONT WINDSCREEN MOULDING             | Cut           | 472.80 F     | *472.80 FL   |
| 4   | 1   |          | *SIDE MIRROR ASSY LH                   | Not Necessary | 233.00 F     | *- FL        |
| 5   | 1   |          | *SIDE MIRROR COVER LH                  | Cut           | 30.00 F      | *30.00 FL    |
| 6   | 1   |          | *SIDE MIRROR STAY LH                   | Bent          | 150.00 F     | *150.00 FL   |
| 7   | 1   |          | *SIGNAL LAMP LH                        | Cracked       | 381.70 F     | *381.70 FL   |
| 8   | 1   |          | *SIGNAL LAMP CLIP LH                   | Not Necessary | 10.00 F      | *- FL        |
| 9   | 1   |          | *HEAD LAMP LH                          | Not Necessary | 699.20 F     | *- FL        |
| 10  | 1   |          | *HEAD LAMP CLIP LH                     | Not Necessary | 10.00 F      | *- FL        |
| 11  | 1   |          | *FRONT BUMPER                          | Not Necessary | 790.00 F     | *- FL        |
| 12  | 1   |          | *FRONT BUMPER CLIP                     | Not Necessary | 10.00 F      | *- FL        |
| 13  | 1   |          | *FRONT BUMPER RETAINER LH              | Not Necessary | 73.60 F      | *- FL        |
| 14  | 1   |          | *FRONT BUMPER RETAINER RH              | Not Necessary | 73.60 F      | *- FL        |
| 15  | 1   |          | *DOOR PILLAR A                         | Dented        | 791.80 F     | *791.80 FL   |
| 16  | 1   |          | *FRONT DOOR LH                         | Dented        | 1,385.20 F   | *1,385.20 FL |
| 17  | 1   |          | *FRONT DOOR HINGE-UP LH                | Not Necessary | 191.50 F     | *- FL        |
| 18  | 1   |          | *FRONT DOOR HINGE-DOWN LH              | Not Necessary | 191.50 F     | *- FL        |
| 19  | 1   |          | *FRONT DOOR WEATHER STRIP LH           | Not Necessary | 271.70 F     | *- FL        |
| 20  | 1   |          | *FRONT DOOR INNER WEATHER STRIP LH     | Not Necessary | 183.60 F     | *- FL        |
| 21  | 1   |          | *FRONT DOOR LOCK LH                    | Not Necessary | 281.70 F     | *- FL        |
| 22  | 1   |          | *FRONT DOOR WINDOW MOULDING LH         | Not Necessary | 102.20 F     | *- FL        |
| 23  | 1   |          | *FRONT DOOR WINDOW GARNISH LH          | Not Necessary | 98.30 F      | *- FL        |
| 24  | 1   |          | *FRONT DOOR POWER WINDOW GEAR LH       | Not Necessary | 316.70 F     | *- FL        |
| 25  | 1   |          | *FRONT DOOR POWER WINDOW MOTOR LH      | Not Necessary | 423.60 F     | *- FL        |
| 26  | 1   |          | *FRONT DOOR STEP GARNISH LH            | Not Necessary | 189.90 F     | *- FL        |
| 27  | 1   |          | *FRONT DOOR ARCH GARNISH LH            | Not Necessary | 210.70 F     | *- FL        |
| 28  | 1   |          | *DOOR PILLAR B                         | Repair        | 630.50 F     | *- FL        |
| 29  | 1   |          | *CORNER PANEL LH                       | Deformed      | 506.70 F     | *506.70 FL   |
| 30  | 1   |          | *FRONT DOOR STICKER-COMPANY DETAILS LH | Necessary     | 40.00 FS     | *30.00 FS    |
| 31  | 1   |          | *FRONT DOOR STICKER-DUONIC LH          | Necessary     | 50.00 FS     | *50.00 FS    |
| 32  | 1   |          | *FRONT DOOR WINDOW STICKER LH          | Not Necessary | 80.00 FS     | *- FS        |
| 33  | 1   |          | *REAR FRIDGE PANEL LH                  | Dented        | 18,000.00 FS | *1,600.00 FS |
| 34  | 1   |          | *REAR FRIDGE DOOR LH                   | Repair        | 500.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (S\$)</b>                                   | <b>28,679.50</b> | <b>6,698.20</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (S\$)</b> | <b>0.00</b>      | <b>1,254.55</b> |
| <b>Total Parts (S\$)</b>                                 | <b>28,679.50</b> | <b>5,443.65</b> |

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>            |  |          |                 |                 |
| 1                              | TO R&R ACCIDENT AFFECTED AREAS             | New      | 2,500.00        | 1,200.00        |
| 2                              | TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS | New      | 1,300.00        | 1,000.00        |
| 3                              | TO RUST PROOF ACCIDENT AFFECTED AREAS      | New      | 120.00          | 0.00            |
| 4                              | TO R&R REAR COOLER BOX                     | New      | 2,000.00        | 400.00          |
| 5                              | TO R&R FRONT DOOR MECHANISM                | New      | 80.00           | 80.00           |
| 6                              | TO CHECK FOR WATER SEEPAGE                 | New      | 100.00          | 0.00            |
| 7                              | TO DO WHEEL ALIGNMENT                      | New      | 180.00          | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>6,280.00</b> | <b>2,740.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >