



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: ERGO Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/02/2018
Vehicle Reg. No.:	SDD19D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHUA JIA CHUN		
Make/Model:	MERCEDES-BENZ E250, 2.0 SEDAN (A)	Vehicle Reg. Date:	24/02/2014
Vehicle Colour:	WHITE	Chassis No:	WDD2120362A895423
Engine No:	27492030109367		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

*Tarif 97495749
"up"
resurvey before paint
surel@meand.com
20/3/18 @ 1520.
3 days.*

COST OF CLAIMS	Amount
Parts	2,595.96
Miscellaneous Items	10.00
Labour	920.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,525.96
+ GST 7.00% (S\$)	246.82
Nett Amount (S\$)	3,772.78

This claim is handled by: JIAYU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2018)
Parts: 143	MERCEDES-BENZ E250 2.0 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDD19D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	10.00	0.00	AM ✓ *1,680.00 FL
2	2		*FRONT OUTER SENSOR RH	10.00	0.00	? *510.00 FL
3	2		*FRONT SENSOR O-RING	10.00	0.00	? *25.00 FL
4	1		*FRONT BUMPER FOGLAMP COVER RH	10.00	0.00	? *78.00 FL
5	1		*FRONT FOGLAMP COVER CHROME RH	10.00	0.00	? *138.00 FL
6	1		*FRONT FOGLAMP COVER BRACKET RH	10.00	0.00	? *46.00 FL
7	1		*FRONT BUMPER SPONGE	10.00	0.00	? *195.00 FL
8	1		*FRONT BUMPER BRACKET RH	10.00	0.00	? *87.60 FL
9	1		*FRONT BUMPER RETAINER RH	10.00	0.00	? *32.00 FL
10	16		*FRONT BUMPER RIVET	10.00	0.00	AM ✓ *92.80 FL
11	1		*FRONT HEADLAMP RH -TBA	10.00	0.00	-
12	1		*FRONT BUMPER REINFORCEMENT - CHECK	10.00	0.00	-
13	1		*FRONT HEADLAMP PANEL RH - REPAIR	10.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,884.40
- List Item Discount on L Items (S\$)	288.44
Total Parts (S\$)	2,595.96

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR FRONT HEADLAMP PANEL RH. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS	New	300. 450.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	250. 350.00
3	TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING	New	30 80.00
4	TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST	New	20. 40.00
Gross Labour Cost (S\$)			920.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >