



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/FWD (SKJ5437H)
DOA: 08/03/2018@080

FWD SINGAPORE PTE LTD

14/3/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SGP 5599 S - FORD FOCTA4
CHASSIS NO: WF04XXWPD45B46767 (04/2006)

1 pc	Rear boot logo	\$	65.00
1 pc	Rear boot 'FOCUS' emblem	\$	66.00
1 pc	Rear bumper	\$	920.00
1 pc	Rear bumper protector LH	\$	125.00
1 pc	Rear bumper protector CTR	\$	230.00
1 pc	Rear bumper protector RH	\$	125.00
1 pc	Rear bumper reinforcement	\$	408.00
		\$	1,939.00
	LESS 20%	\$	387.80
		\$	1,551.20

1 set	Reverse Sensor	\$	200.00
-------	----------------	----	--------

Remove necessary parts: jacking, panel beating, repair and
straighten rear inner panel, rear end panel, rear boot and
rear bumper.

\$ 500.00

Putty and respray rear inner panel, rear end panel, rear
boot and rear bumper.

\$ 500.00

\$ 2,751.20

ADD 7% GST

\$ 192.58

\$ 2,943.78

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT