



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKQ8772H

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT  
16 RAFFLES QUAY #24-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
66431303

### Vehicle & Document Information

WIP No **21833**  
Reg No/Reg Date **SKQ8772H / 02/01/2015**  
Date In/Mileage **16/03/2018 / 29901**  
Chassis No **WDD2120362B060046**  
Engine No **27492030235569**  
Make/Model **MB/E 250 2.0 CGI SEDAN (W212)**  
Colour/Trim **021 197 Obsidian Bl/ 042 274 Leather Jav**

**SKQ8772H**

Account No	Terms	Date/Time Printed	CSE	Operator			
WI000558	Credit	17/04/2018/ 09:31	VS	356 / Vincent Seah			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M. BPNSUN  
POLICY NO/ACC DATE : 828868902M0Y // 07.03.18  
DRIVE IN/EXCESS : 08.03.18 // TP CAR NO: SJM2786T=MSIG  
DATE IN/DATE SURVEY: 15.03.18 // 16.03.18 TAUFIKH-LKK 16:00PM  
DIRECT SETTLEMENT: CATHERINE THIA-MSIG// 12.03.18

- X STOP
- X RIVETED NUT
- X COVER

2.00	9.41	00.00
4.00	3.66	00.00
1.00	38.15	00.00

18.82 *net*  
14.64 *net*  
38.15 *de*

**THIS IS NOT AN OFFICIAL TAX INVOICE**

**ESTIMATE**

**SUPPLEMENTARY**

Confirmed & accepted by

	<b>Nett</b>	<b>71.61</b>
<b>7% GST on</b>	<b>71.61</b>	<b>5.01</b>
<b>Total Payable</b>		<b>76.62</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg